

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBG 5278Y

DATE ACCIDENT : 5-Feb-20

MAKE / MODEL : PIAGGIO / VESPA LX 150

S/No	DESCRIPTION	AMOUNT
1	FRONT FENCER	\$ 265.00
2	FORK ASSY	\$ 850.00
3	LEFT HAND MIRROR	\$ 165.00
4	LEFT HAND MIRROR BRAK CET	\$ 120.00
5	RH LEFT HAND BRAKE LEVER	\$ 65.00
6	HANDLE BAR	\$ 185.00
7	GRIP	\$ 85.00
8	STEERING CON	\$ 150.00
9	RIGHT HAND BODY BEADING TOP	\$ 85.00
10	LEFT HAND BODY BEADING TOP	\$ 85.00
11	RIGHT HAND BODY BEADING LOW	\$ 75.00
12	LEFT HAND BODY BEADING LOW	\$ 75.00
13	FOOT REST RUBBER SHIELD	\$ 65.00
14	MUFFLER ASSY	\$ 795.00
15	BODY WORK	\$ 350.00
16	SPRAY WORK	\$ 480.00
SUB-TOTAL		\$ 3,895.00
	TRANSPORT	\$ 80.00
	LABOUR	\$ 500.00
<p>Tanpin 97495749 'WP' 27/2/20 @ 5pm Resury new parts su @ lkkauto.com 4-X days</p>		
Total		\$ 4,475.00

cut
?
mis
mis
cut
?
at
?
at
cut
cut
th
?
200
300

60
250

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: