

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 596G**AAD2002-162***Not Authorised**Refusing B4 paint*

Vehicle No.: 25 FEB 2020
Chassis No.:
Vehicle Make: 25 FEB 2020
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 596G
VF1ABL15AUC283244
RENAULT
LATITUDE
24.2.2020
FCIL
24/11/2017

PART		LIST	
1	BUMPER COVER REAR	\$	<i>Tn</i> 561.70 ✓
1	BUMPER LOWER REAR	\$	<i>Nollar</i> 411.90 ✓
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 98.10 X
1	BUMPER BRACKET SIDE RH REAR	\$	<i>cm</i> 82.10 ✓
1	BUMPER RETAINER RH REAR	\$	<i>cm</i> 59.80 ✓
1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 16.60
1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 80.80
1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 54.20
1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 16.60 } X
1	BUMPER BEAM REAR	\$	<i>R</i> 547.80
1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50
1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 100.90
1	BUMPER BLOCK RH REAR L70Y	\$	<i>Sn</i> 76.50
1	BUMPER HARNESS REAR	\$	<i>Sn</i> 301.10
1	OUTER PANEL REAR (End Panel)	\$	<i>B</i> 745.80 ✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Sn</i> 404.56 X
1	TAILLAMP RH	\$	<i>cm</i> 401.40 ✓
1	TAILLAMP PANEL RH	\$	<i>R</i> 401.40 X
1	TAILLAMP LH	\$	<i>Sn</i> 401.40 X
1	TAILLAMP PANEL LH	\$	<i>R</i> 401.40 X
1	BOOT REAR	\$	<i>R</i> 1,677.20 X
1	BOOT FINISHER	\$	<i>Sn</i> 344.70 X
1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 178.20 X
1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 277.70 X
1	BOOT REFLECTOR LAMP RH	\$	<i>cm</i> 277.70 ✓
1	BOOT BADGE 'RENAULT'	\$	<i>nn</i> 82.40 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 596G**AAD2002-162**

1	BOOT BADGE	\$	nn	95.80	}	X
1	BOOT STRUT LH	\$	sn	145.10		
1	BOOT STRUT RH	\$	sn	145.10		
1	BOOT HINGE LH	\$	n	254.20		
1	BOOT HINGE RH	\$	n	253.80		
2	BOOT RUBBER PLUG	\$	sn	139.90		
1	BOOT INNER TRIM BOARD	\$	sn	611.00		
1	BOOT LOCK	\$	n	246.60		
1	SPARE TYRE BOARD L70Y	\$	sn	680.90		
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	n	1,229.40		
1	SPARE WHEEL PANEL TRIM	\$	sn	612.21	}	✓
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	n	69.20		
1	FENDER PANEL REAR RH	\$	sn	1,933.20	}	X
1	WHEELARCH REAR RH	\$	sn	275.40		
1	FENDER PANEL INNER TRIM REAR RH	\$	sn	671.45		
1	AIR VENT	\$	sn	59.40		
1	CHASSIS PANEL REAR RH L70Y	\$	n	2,192.40		
1	FENDER PANEL INNER REAR RH L70Y	\$	n	952.50		
1	FENDER INNER BOARD RH L70Y	\$	n	561.40		
1	WHEEL HOUSING PANEL REAR RH	\$	n	4,682.09		
1	EXHAUST REAR	\$	n	5,263.60		
1	EXHAUST CAP REAR	\$	sn	125.40		
1	DOOR PANEL REAR RH	\$	n	758.70		
1	ROCKER PANEL OUTER RH	\$	n	1,184.99		
1	KNUCKLE ARM REAR RH	\$	sn	472.10		
1	BRAKE DISC REAR	\$	sn	266.50		
1	ABS SENSOR REAR RH	\$	sn	190.50		
1	WHEEL HUB NUT	\$	sn	41.80		
1	WHEEL HUB CAP	\$	sn	30.50		
1	KNUCKLE HUB+ BEARING RH	\$	sn	272.30		
1	REAR AXLE	\$	sn	3,469.00		
1	AXLE ARM RH	\$	sn	69.50		
2	REAR AXLE SPACER	\$	sn	49.00		
1	REAR AXLE ARM ROD	\$	sn	69.50		

Trans-cab Auto Services Pte Ltd**AAD2002-162**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 596G

1	LOWER ARM REAR RH	\$	543.50	} <i>Sh</i> X
1	AXLE SPRING ARM RH	\$	220.60	
1	ABSORBER REAR	\$	217.30	
1	ABSORBER DUST COVER REAR	\$	47.10	
1	ABSORBER MOUNTING REAR	\$	49.40	
1	STABILIZER BAR REAR	\$	427.90	
1	STABILIZER LINK REAR	\$	55.20	
1	BRAKE CALIPER REAR RH	\$	659.10	
1	BRAKE CALIPER BRACKET REAR RH	\$	384.00	
1	BRAKE HOSE REAR RH	\$	79.50	
1	SUBFRAME ARM REAR	\$	198.33	
1	RODE- LONG REAR	\$	120.16	

TOTAL	\$	39,192.99
10%	\$	3,919.30
	\$	35,273.69

Special Nett

1SET	PARKING AID	\$	<i>Shon</i> 700.00	<i>400sn</i>
1SET	REAR BUMPER CLIP	\$	<i>na</i> 66.00	<i>—</i>
1SET	BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	<i>—</i>
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	X
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	X
1SET	BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	✓
1	BOOT STICKER "Trans-cab"	\$	<i>na</i> 35.00	X
1	BOOT STICKER "6555-3333"	\$	<i>na</i> 35.00	X
2	REAR WINDSCREEN SEALANT	\$	<i>na</i> 100.00	<i>40sn</i>
1	WINDSCREEN MOULDING	\$	<i>na</i> 130.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	<i>30sn</i>
1	BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00	X
1SET	BOOT FINISHER CLIP	\$	<i>na</i> 24.20	X

Trans-cab Auto Services Pte Ltd**AAD2002-162**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 596G

1	TAILLAMP CLIP RH	\$	na	5.00	X
1	Rear Bumper Protector	\$	na	100.00	30na
1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	} X
1	FENDER INNER TRIM CLIP RH	\$	na	28.00	
1	REAR RIGHT TYRE	\$	su	330.00	
1	REAR RIGHT TYRE RIM	\$	su	385.00	
1	REAR RIGHT TYRE RIM COVER	\$	su	60.00	
1	EXHAUST BRACKET REAR	\$	na	24.80	
1	EXHAUST MOUNTING REAR	\$	su	16.00	
1	REAR DOOR STICKER "6555-3333"	\$	na	100.00	
1SET	Rear licence plate with holder	\$	su	100.00	
1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	su	385.00	
1	SPARE TYRE	\$	su	330.00	
TOTAL		\$		3,315.00	

TOTAL PARTS	\$	38,588.69
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1001
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd**AAD2002-162**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 596G

To Rust-Proofing Of The Affected Areas.	\$	170.00	601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	12001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To Check Electrical Lighting Concerned.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	4 350.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	7,500.00	6601
To check ABS and brake efficiency, final checking and testing.	\$	4 380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	4 170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	4 380.00	X
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	4 380.00	X

Trans-cab Auto Services Pte Ltd**AAD2002-162**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 596G

To repair and realign rear exhaust pipe.	\$	<i>na</i>	170.00	X
Towing Fees	\$	<i>4</i>	150.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>4</i>	380.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>4</i>	380.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>4</i>	170.00	X
TOTAL	\$		20,420.00	
Over All Total	\$		59,008.69	

PART BY PART (REPAIR DAY)**25 DAYS***7 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: