

Section A - Accident Details

Registration Number	SHB808G
Case Reference Number	TAX/02/20/2063
Registration Date	7/5/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LAI FONG LIANG
Type of Accident	Side Swipe
Accident Date and Time	22/2/2020 2:05 AM
Accident Reported Date and Time	22/2/2020 8:27 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105827
Special Instruction to ARC, if any	TP
Prepared Date and Time	22/2/2020 9:24 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$1,674.00	\$400.00
Total Spare Part Cost	\$3,980.73	\$96.00
Total Other Cost	\$600.00	\$20.00
TOTAL COST	\$6,761.73	\$816.00
Lump Sum Total	\$6,750.00	\$800.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	24/02/2020 5:56 PM	24/02/2020 2:58 PM
Signature		
Remarks		Lump Sum Repair, Take after paint photo

