



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2104074

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/06/2021
Reference CC6/CTI20003244/Db3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 8109B
Insured Veh. GBE 3716Z
Claim No. SNM20D200838
Policy No. DMCVSN3087482002
Accident Date 13/02/2020
Inspection Date 19/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20003244/Db3q2 Date: 10/06/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBE 3716Z	Veh. Inspected	SH 8109B
	Policy No.	DMCVSN3087482002	Coverage (\$)	0.00
	Claim No.	SNM20D200838	Excess (\$)	0.00
	Assign From		Assign Date	19/02/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU703562684	Colour	BLUE
	Odometer	384585 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	5 mm
	L/H Front Tyre	195/65 R15	DAVANTI	5 mm
	R/H Rear Tyre	195/65 R15	DAVANTI	5 mm
	L/H Rear Tyre	195/65 R15	DAVANTI	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	13/02/2020	Inspection Date	19/02/2020
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Ind Est S575644		
	Repairer	BIFROST AUTO PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8109B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	DISTORTED / CUT	499.90	499.90
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	696.40	-
1	FRONT BUMPER REINFORCEMENT ABSORBER	NOT NECESSARY	115.70	-
1	FT BUMPER LOWER REINFORCEMENT BRACKET	NOT NECESSARY	330.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	78.80	-
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	301.90	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	148.60	-
1	LAMP ASSY, FOG, RH	NOT NECESSARY	920.00	-
1	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	77.00	-
1	REINFORCEMENT, FRONT BUMPER LOWER	NO SUCH PARTS	236.10	-
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	NO SUCH PARTS	110.40	-
1	SUPPORT FR BUMPER, RH	NOT NECESSARY	81.70	-
1	FRONT BUMPER CENTRE FRAME	NO SUCH PARTS	236.90	-
1	BRACKET, FRONT BUMPER SIDE, RH	BROKEN	82.30	82.30
1	BRACKET, FRONT BUMPER MOUNTING	NOT NECESSARY	29.60	-
1	BRACKET, FRONT BUMPER MOUNTING, NO.2	NOT NECESSARY	97.80	-
1	ABSORBER, FRONT BUMPER, LOWER	NOT NECESSARY	127.70	-
1	UNIT ASSY, HEADLAMP, RH (LED)	MTG BROKEN	3,455.00	3,455.00
1	TOP PANEL CENTRE	NOT NECESSARY	364.98	-
1	TOP PANEL SIDE	BENT	145.90	145.90
1	BRACKET, HEADLAMP MOUNTING, RH	NOT NECESSARY	25.50	-
1	FENDER SUB-ASSY, FRONT RH	DENTED	945.30	945.30
1	FRONT FENDER SHIELD	DEFORMED	198.50	198.50
1	FRONT FENDER SHIELD CLIP	NECESSARY	14.90	14.90
1	FRONT FENDER HYBRID EMBLEM, RH	NECESSARY	86.50	86.50
1	BRACKET, FRONT SIDE PANEL, RH	NOT NECESSARY	44.50	-
1	EXTENSION, FRONT FENDER, RH	NO SUCH PARTS	47.20	-
1	PORTECTOR, FRONT FENDER SIDE PANEL, RH	NO SUCH PARTS	113.90	-
1	SEAL, FRONT FENDER TO COWL SIDE, RH	NOT NECESSARY	15.20	-
1	GUSSET, FRONT FENDER APRON, LOWER RH	NOT NECESSARY	34.90	-

Report Ref No. CC6/CTI20003244/Db3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXTENSION, FRONT FENDER APRON, FRONT RH	NOT NECESSARY	23.20	-
1	MEMBER, FRONT APRON TO COWL SIDE, UPPER RH	NOT NECESSARY	138.40	-
1	FRONT APRON TO COWL SIDE, LOWER FRT RH	NOT NECESSARY	82.30	-
1	MIRROR ASSY, OUTER REAR VIEW, RH	BROKEN	1,728.70	1,728.70
1	WIPER SPARE TANK	DEFORMED	183.75	183.75
1	WIPER SPARE TANK MOTOR	NOT NECESSARY	242.70	-
1	WIPER SPARE TANK FLOAT (NECK)	NOT NECESSARY	55.50	-
1	FRONT WHEEL RIM	BENT	1,570.55	1,570.55
1	FRONT WHEEL HUB CAP	BENT	175.80	175.80
1	FRONT WHEEL HUB BEARING	DAMAGED	559.94	559.94
1	FRONT SUSPENSION LOWER ARM (RH)	DISTORTED	631.90	631.90
1	FRONT SHOCK ABSORBER (RH)	DISTORTED	398.20	398.20
1	ABSORBER TOP MOUNTING	NOT NECESSARY	196.20	-
1	FRONT DRIVE SHAFT (RH)	NOT NECESSARY	1,764.00	-
1	RACK & PINION ASSY	NOT NECESSARY	1,621.30	-
1	BAR, STABILIZER	NOT NECESSARY	352.40	-
1	LINK ASSY, FRONT STABILIZER,	NOT NECESSARY	196.80	-
1	KNUCKLE, STEERING, RH	DISTORTED	580.80	580.80
1	JOINT ASSY, LOWER BALL, FRON T RH	NOT NECESSARY	199.98	-
1	HUB SUB-ASSY, FRONT AXLE, RH/LH	NOT NECESSARY	549.70	-
1	END SUB-ASSY, TIE ROD, RH	NOT NECESSARY	159.30	-
1	ENGINE UNDER COVER	NOT NECESSARY	457.20	-
1	ENGINE CROSS MEMBER	NOT NECESSARY	2,504.40	-
1	FRT ABS WIRE	NOT NECESSARY	450.70	-
	LESS 20% DISCOUNT		-4,901.76	-
	LESS 25% DISCOUNT		-	-2,819.98
			19,607.04	8,459.96
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (LH/RH) (SN)	SERVICEABLE	216.00	-
1	FRONT NO. PLATE (SN)	NOT NECESSARY	25.00	-
1	FRONT NO. PLATE TRIM COVER (SN)	NOT NECESSARY	30.00	-
1	FRONT NO. PLATE GARNISH (SN)	NOT NECESSARY	99.00	-

Report Ref No. CC6/CTI20003244/Db3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOGO (SN)	NOT NECESSARY	87.10	-
			457.10	-
	LABOUR			
	PANEL BEATING.		1,200.00	700.00
	SPRAY PAINTING CHARGE.		1,000.00	600.00
	WIRING CHARGE.		120.00	30.00
	TUFF KOTE.		150.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE / REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE / REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE / REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
			3,080.00	1,580.00
GRAND TOTAL			23,144.14	10,039.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CC6/CTI20003244/Db3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 8109B

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 8109B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 8109B

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

