



**KT GARAGE PTE LTD** UEN: 201906115R  
 Auto Bay@ Kaki Bukit Entrance A  
 BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date : 27/02/2020

Total Pages : 1

TO: **AIG Asia Pacific Pte Ltd**  
 AIG Building, 78 Shenton Way#08-16  
 Singapore 079120

Our Customer : Tan Siew Keng

Vehicle No : **SFY4431K**

Model : TOYOTA VIOS

Manufacture Year : 2005

Date of Accident : 17/02/2020

Total Estimate Repair Days : 8


Attn : Motor Claim Department

Email :

Re: Repair Estimate For Third Party Claim against : SMD9523Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Rear bumper ✓ <i>BT</i>	1	\$208.89	\$208.89	
2	Rear bumper clips ✓ <i>sc</i>	10	\$3.00	\$30.00	
3	Rear bumper side retainer ✓ <i>sc</i>	2	\$15.19	\$30.38	
4	Rear boot ✓ <i>BT</i>	1	\$313.33	\$313.33	
5	Rear boot lock ✓ <i>Jan</i>	1	\$28.48	\$28.48	
6	Rear boot weatherstrip X (svc)	1	\$49.37	<del>\$49.37</del>	
7	End panel ✓ <i>cut</i>	1	\$417.78	\$417.78	
8	End panel top garnish ✓ <i>can</i>	1	\$53.17	\$53.17	
9	Tail lamp - RH ✓ <i>can</i>	1	\$85.45	\$85.45	
10	Tail lamp - LH ✓ <i>can</i>	1	\$85.45	\$85.45	
	<b>Sub Total</b>			<b>\$1,302.30</b>	
	Less 25%			\$325.58	
	<b>Sub Total 1</b>			<b>\$976.73</b>	
<b>B.</b>	<b>Spare Parts (S/Nett)</b>				
1	Rear number plate ✓ <i>scr</i>	1	\$50.00	<del>\$50.00</del>	<i>35</i>
	<b>Sub Total 2</b>			<b>\$50.00</b>	
	<b>Total Spare Parts</b>			<b>\$1,026.73</b>	
<b>C.</b>	<b>Labour</b>				
1	To knock and straighten necessary portion. To remove and renew damaged panel. To adjust and realign the same <i>+ repair spray type panel + tail lamp RH</i>			\$800.00	✓
2	To putty and spray all affected areas <i>+ spray type panel, tail lamp</i>			\$800.00	✓
3	To rust proof all affected areas			\$200.00	<i>30</i>
4	To check wiring and all lighting			\$120.00	<i>30</i>
	<b>Total Labour</b>			<b>\$1,920.00</b>	
	<b>Total Repair Cost</b>			<b>\$2,896.73</b>	
* The above quoted are exclusive of GST.					

Yours faithfully,



Darla  
 f KT Garage Pte Ltd

*L/S repair without prejudice  
 Resurvey after part  
 27/2/20 1:30pm  
 6 day  
 Hook Ann (MUC)  
 85314883  
 Hook ANN @ lkkAuto.com  
 need to check (MV)*

*Resurvey after  
 H. Ann  
 2:45pm  
 27/2/20*

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	
DATE	Remark From Mr Tan
	Please arrange for survey asap