

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref

: 20/20/20/VP05/023092

Date: 11th March 2020

Our Ref

: CS/LPC20003254/Kqf3e2

M/s Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555 (The Motor Claims Department)

Dear Sirs/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SCP 8626Y ACCIDENT ON 20/02/2020

Instruction was received to inspect the vehicle Reg. No. SCP 8626Y. The inspection was conducted on 27/02/2020 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd, 160 Sin Ming Drive #04-01/02, Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

Registration Number

: SCP 8626Y

Make/Model

: Mercedes Benz B180 STYLE (R16 LED)

Year of Registration

: 2015

Body Colour

: Metalllic brown

Chassis Number

: WDD2462422J371197

Engine Capacity

: 1595 cc

Speedometer Reading

: 36527 km

The vehicle sustained damages at the rooftop, rear o/s, rear n/s portion and n/s body. The cause of damaged due to fallen tree trunk. The Estimated repair cost of such vehicle is S\$28,000.00 (Sin Dollars: Twenty Eight Thousand only.) (Details see photographs enclosed)



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as "Total Loss".

(a)	If the vehicle to be "Total Loss"
	Market Value

		23 010 00
Less: LTA Reimbursement Value (RV)	(S\$	51,090.00)
	S\$	75,000.00

	5.0	23,710.00
Less: Excess	(<u>S\$</u>	3,500.00)

Nett Liability
S\$ 20,410.00

(b) If the vehicle to be "Repair"

Repair Cost	S\$	28,000.00

Nett Liability
S\$ 24,500.00

$$(a) - (b) = (S\$ - 4,090.00)$$

The amount of estimated saving of S\$4,090.00 if the vehicle to be written off as "Total Loss" instead of to be repair.

Vehicle Inspected By:

KONG SENG CHEONG

Licensed Appraiser

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust), MBA(UK),

MASME(USA), B Bus(Aust), MBA(UK), IEng(UK), MHE(mech), MinstAEA, MFIEA,

MIRTE, MINI, MSAE, MCIArd, AM, NIJAAR(USA), AM CATARI(CAN), M. MATA(USA), M. MdATA(USA)

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.