

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FIRSRT CAPITAL	DATE	: 25/02/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMM6791M		
MODEL	: TOYOTA VIOS 1.5A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 11-Feb-20
		TIME	: 20:30HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>torn</i>	1	\$ 580.00	\$ 580.00
2	FRONT BUMPER SIDE RETAINER LH <i>new</i>	1	\$ 52.30	\$ 52.30
3	HEADLAMP LH <i>new</i>	1	\$ 890.50	\$ 890.50
4	FRONT FENDER LH <i>Dented</i>	1	\$ 488.90	\$ 488.90
5	FRONT FENDER INNER COWLING LH <i>Dented</i>	1	\$ 155.80	\$ 155.80
6	FRONT DOOR LH <i>3 Dented</i>	1	\$ 1,025.30	\$ 1,025.30
7	REAR DOOR LH	1	\$ 1,025.30	\$ 1,025.30
8	REAR FENDER LH <i>Repair</i>	1	\$ 920.30	\$ 920.30
9	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 103.00	\$ 103.00

3275.30

2456471

TOTAL PRICE \$ 5,241.40

LESS 25% \$ 1,310.35

SUB TOTAL PRICE \$ 3,931.05

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER COWLING CLIPS <i>new</i>	1	\$ 22.00	\$ 22.00
3	REAR WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00
4	WHEEL TYRE <i>new</i>	1	\$ 380.00	\$ 380.00

5	WHEEL RIM <i>ut</i>	1	\$ 850.00	\$ 850.00	<i>580</i>
---	---------------------	---	-----------	-----------	------------

622

TOTAL \$ 1,392.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>1000</i>	
3	TUFF COAT	\$ 250.00	<i>60</i>	
4	WIRING CHECK	\$ 80.00	<i>30</i>	
5	REFOCUS HEADLAMP BEAM	\$ 80.00	<i>x</i>	
6	TRANSFER FRONT DOOR MECHANISM LH	\$ 80.00	<i>✓</i>	
7	TRANSFER REAR DOOR MECHANISM LH	\$ 80.00	<i>✓</i>	
8	TRANSFER REAR WINDSCREEN	\$ 160.00	<i>x</i>	
9	FOUR WHEEL ALIGNMNET	\$ 100.00	<i>80</i>	

2130

TOTAL \$4,030.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,323.05
TOTAL LABOUR COST : \$ 4,030.00
TOTAL REPAIR COST : \$ 9,353.05

Adrian Lj
H/s 25/02/20.

06 Days.

total 520847

H/s 4.11K ✓

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

FAX :

Acknowledged by Repairer
Signature:
Date: