

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AXA18004300/BGA3Q2-1

Date: 26/03/2021

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : FS9322R

Insured Vehicle No :

SHB9928J

Date of Loss: 15/02/2018

Nature of Claim:

TP

Claim No: C0470895

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FS9322R**

Make & Model: SYM JOYRIDE 200 A, 171cc (A)

Engine No: KB210558

Reg. Date: 30/12/2011 (Man. Year: 2011)

Chassis No: RFGLF18WYBS007300

Colour: Black

Odometer: 0 km

Engine Capacity: 172 cc

Market Value/New Car

Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13

Rear Tyre Size:

130/70-12

Front Left Side: Michelin 3 mm

Rear Left Side:

Michelin 3 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
Approved Total (Overridden) (\$\$)		3,700.00		
Nett Amount (\$\$)	0.00	3,700.00	-3,700.00	
+ Loss of Use (5.0 x S\$20.00/day) (\$\$)		100.00		
(\$\$)		3,800.00		
Liabe Amount (50.00%) (\$\$)		1,900.00		

INSPECTION

Date of Assignment: 02/03/2018

Date Inspected: 07/03/2018 Inspected At:

Sg 98 Motor Pte Ltd (HQ)

BLK 4001 ANG MO KIO INDUSTRIAL

PARK 1 #01-21

Singapore 569622

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$2,000.00

LTA REIMBURSEMENT VALUE (RV) : \$551.00

NETT VALUE : \$1,449.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Nov 2020)	
Parts:	N/A	SYM JOYRIDE 200 A 171cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FS9322R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >