

ASS. REC. BY:

Surveyor: Adnan

REF: es/AGI 20003272/Ag d3¹²

Special Instructions:

ASSIGNMENT (Office)

From (Person): Iy Ratilla

of AUI

Date/Time: 27/2/2020 @ 12.33pm

Estimated Cost:

Bill to:

OD - TP - WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMR 9416B

Insured:

SV 103C

at Workshop m/s

ACE Auto Solution

Tel:

9189 2617

of

23 kaki Bukit Ave 4 # 04-01

Policy No:

Claim No:

C10005690

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/02/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12.55pm @ 27/2/2020

Person Contacted:

Suheimi

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate

27/2/2020

Suheimi said he will arrange with Adnan. (Adnan on leave today)

SMR 9416B - X

SV 103C - X

US \$6050, 5 days, Cld \$650.01, 50%

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SMR 94/6B.

Yr Regn: 2020, Jan.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216 Gran Tourer c.c. 1499

Colour: Black. A/C: Insured / Std / NI / NA

Sp. Reading: 1172. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA6V120205P79951

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16.

R: 205/60R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 28/02/20

Survey held at

Ace Auto Solution.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct.

RECEIVED 12 MAR 2020

MV:

PV:

Nett:

Date/Time, File Pass to?

☐

Preli. Report

1) 12/3 trans

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / Daily

TP

6050

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Workings (\$)

Survey Fee:

Transportation:

S + PS \$

Photos

Other

TOTAL

350

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Thursday, 27 February 2020 12:33 PM
To: Admin-D (LKKAuto)
Cc: SUR; Loganathan Agoram
Subject: FW: Accident vehicle between our insured SMR9416BT and your insured SJV103C on 25/02/2020 || C10005690
Attachments: SMR9416R.pdf; SJV103C.pdf

Hi Team,

We would like to arrange TP PRS for SMR9416B. They have chosen Mr. Adrian Ling to survey the mentioned vehicle.

Workshop information:

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185

F +65 6725 0853

E ivy.r@budgetdirect.com.sg

**Budget
Direct**
insurance



Customer Care +65 6221 2111

Claims +65 6221 2199

Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore

239924

budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee,

confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Ace Auto Solution <aceautosolution@gmail.com>

Sent: Thursday, 27 February 2020 11:46 AM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Cc: Claims <claims@budgetdirect.com.sg>; Loganathan Agoram <loganathan.a@budgetdirect.com.sg>

Subject: Re: Accident vehicle between our insured SMR9416BT and your insured SJV103C on 25/02/2020 || C10005690

Hi Ivy,

We would like to appoint Adrian Ling LKK Auto Consultants Pte Ltd as the single joint expert for this accident case.

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

From: Ace Auto Solution <aceautosolution@gmail.com>

Sent: Thursday, 27 February 2020 8:49 AM

To: Claims <claims@budgetdirect.com.sg>

Subject: Fwd: Accident vehicle between our insured SMR9416BT and your insured SJV103C on 25/02/2020

Dear Sir

We are instructed by Alpine Car Rental Pte Ltd to notify you of a road traffic accident on 25/02/2020 at about 0745 at North Buona Vista involving our client's/customer's vehicle registration number SMR9416B and vehicle registration number SJV103C driven by you at the material time. A copy of the Singapore accident statement/traffic police report filed is enclosed.

As a result of the accident, our client's/customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

We look forward in having a direct settlement and request that one of the following named survey companies **be appointed as the single joint expert** as finalization/processing of the claims after finalization are done promptly.

1)

2)

3)

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/02/2020 15:57
Date Of Accident	25/02/2020 07:45
Exact Location Of Accident	NORTH BUONA VISTA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMR9416B
Insured/Policyholder	
Name Of Registered Owner	ALPINE CAR RENTAL PTE LTD
Co Reg No	1XXXXX483E
Email Address	PHILLIP.PHANG@ALPINECARRENTAL.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65113021

Vehicle Particulars

Manufacturer	BMW
Model	216I GRAN TOURER HALOGEN LIGHT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHEN SEAN CHUAN
Passport No/FIN	GXXXXX914M
Date Of Birth	24/05/1975
Occupation	OUTDOOR
Date Of Driving Pass	21/05/2012
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90664731
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 5 EVERTON, #08-28

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV103C

Vehicle Make/Model/Colour NISSAN / TEANA 2.5L CVT

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: S. L. L.
NRIC/FIN No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was driving down the North Buena Vista Road, when the road merged 3-way, I did full stop, then drove slowly, then ~~the~~ my car was rammed from behind by a light brown Nissan Teana.

The collision took place behind the double white dotted line. Debris is on the floor, picture submitted

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Sean Ch
Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name: *Suhaimi*
NRIC/FIN No:

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date :

Reference: SMR9416B
 B.M.W. / 216I
 Make: GRAN TOURER
 HALOGEN
 LIGHT

TP Budget Direct
 Ximo Chan

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SMR9416B
CHASSIS NO.: WBA6V120205P79951
ENGINE NO.: 45125888B38A15A

Name of insured : Alpine Car Rental Pte Ltd
 Date of accident.: 25/02/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Rear Tailgate Dented	\$ 1,898.70
2	1	Rear Windscreen new	\$ 957.60
3	10	Rear Tailgate Inner Trim Clips new	\$ 80.00
4	1	Rear Tailgate Inner Weatherstrip cut	\$ 250.80
5	1	RHR Taillamp new	\$ 539.70
6	1	Rear Bumper Discolored	\$ 1,620.40
7	10	Rear Bumper Clips new	\$ 80.00
8	1	Rear Bumper Towing Cover Rehd	\$ 65.10
9	1	RHR Bumper Reflector could	\$ 78.70
10	2	Reverse Sensor 1 piece dented	\$ 661.60
11	1	Reverse Sensor Wiring Harness New Snapped	\$ 1,548.50
12	1	Rear Bumper Reinforcement Bar Bent	\$ 530.70
13	1	Rear End Panel Repr	\$ 484.80
14	1	Rear End Panel Trim new	\$ 85.00
15	6	Rear End Panel Trim Clips new	\$ 48.00
16	1	Rear Bumper Lower Aluminium Plate Bent	\$ 98.70
17	1	Rear Bumper Bracket Centre could	\$ 105.30

<u>18</u>	1	Rear Bumper Bracket Centre <i>crushed</i>	\$ 105.30	✓
<u>19</u>	1	LHR Bumper Bracket <i>new</i>	\$ 150.70	+
<u>20</u>	1	RHR Bumper Bracket <i>crushed</i>	\$ 150.70	✓
<u>21</u>	1	LHR Bumper Bracket Lower <i>7/10/12</i>	\$ 124.30	+
<u>22</u>	1	RHR Bumper Bracket Lower	\$ 124.30	+

6746.10
6071.49.

Parts Total: \$ 9,788.90
Less 10%: \$ 978.89
Total: \$ 8,810.01

Labour

Labour Description

No.

Price (SGD)

Rear portion

<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 1,200.00	500
<u>2</u>	Carry out spray painting on accident affected area	\$ 1,000.00	600
<u>3</u>	To conduct anti rust of under carriage tuff coat	\$ 80.00	50
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 50.00	30
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 100.00	60
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 150.00	80
<u>7</u>	To conduct water leakage test after repairs of vehicle	\$ 50.00	+
<u>8</u>	To apply sealant to rear tail gate	\$ 80.00	+
<u>9</u>	To remove and refix rear tail gate windscreen	\$ 120.00	✓

1440

Labour Total: \$ 2,830.00

Others

Other Description

No. Qty

Price (SGD)

Rear portion

1	1	Rear end panel insulation seal <i>2</i>	\$ 120.00	+
2	1	Rear floor panel insulation seal <i>from</i>	\$ 100.00	+
3	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	60
4	1	Tailgate windscreen solar film <i>new</i>	\$ 220.00	+

60

Other Total: \$ 560.00

GRAND TOTAL: \$ 12,200.01

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com

APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

Admin Lj

A/s 28/02/20

05 Days.

total: 7571.49.

C/s: 6050.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Finalisation

Ace Auto Solution

Registration number : 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : Auto & General Insurance(Singapore) Pte. Limited
190 CLEMENCEAU AVENUE
#03-01, SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

Invoice No: ACC-2015001
Invoice Date:

Vehicle No: SMR9416B
Chasis No: WBA6V120205P79951
Engine No: 45125888B38A15A

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
<u>1</u>	1	Rear Tailgate	\$ 1,898.70
<u>2</u>	1	Rear Tailgate Inner Weatherstrip	\$ 250.80
<u>3</u>	1	Rear Bumper	\$ 1,620.40
<u>4</u>	10	Rear Bumper Clips	\$ 30.00
<u>5</u>	1	Rear Bumper Towing Cover	\$ 65.10
<u>6</u>	1	RHR Bumper Reflector	\$ 78.70
<u>7</u>	1	Reverse Sensor	\$ 265.00
<u>8</u>	1	Reverse Sensor Wiring Harness	\$ 1,548.50
<u>9</u>	1	Rear Bumper Reinforcement Bar	\$ 530.70
<u>10</u>	1	Rear Bumper Lower Aluminium Plate	\$ 98.70
<u>11</u>	1	Rear Bumper Bracket Centre	\$ 105.30
<u>12</u>	1	Rear Bumper Bracket Centre	\$ 105.30
<u>13</u>	1	RHR Bumper Bracket	\$ 150.70

Total: \$ 6,747.90
Less 10%: \$ 674.79
Parts Total : \$ 6,073.11

Labour

No.		Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 500.00
<u>2</u>	Carry out spray painting on accident affected area	\$ 600.00
<u>3</u>	To conduct anti rust of under carriage tuff coat	\$ 50.00
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>5</u>	To remove and refix reverse sensor and conduct test	\$ 60.00
<u>6</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
<u>7</u>	To remove and refix rear tail gate windscreen	\$ 120.00

Labour Total : \$ 1,440.00

Other

No.			Price (SGD)
1	1	Tailgate windscreen sealant	\$ 60.00

Other Total : \$ 60.00

Total : \$ 7,573.11
Less lump sum 20%: \$ 1,514.62
Grand Total: \$ 6,050.00

Yours Faithfully



Suhaimi
Service Executive
Tel: 9189 2617 Fax: 6844 5185
Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI20003272/Aqd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 16-03-2020 Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 103C	Veh. Inspected	SMR 9416B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10005690	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	27/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	BMW 216I GRAN TOURER	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WBA6V120205P79951	Colour	BLACK	
Odometer	1172	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/02/2020	Inspection Date	28/02/2020	
Survey held at	ACE AUTO SOLUTION 23 KAKI BUKIT AVE 4,#04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 9416B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	DENTED	1,898.70	1,898.70
1	REAR WINDSCREEN	NOT NECESSARY	957.60	-
10	REAR TAILGATE INNER TRIM CLIPS	NOT NECESSARY	80.00	-
1	REAR TAILGATE INNER WEATHERSTRIP	CUT	250.80	250.80
1	RHR TAILLAMP	NOT NECESSARY	539.70	-
1	REAR BUMPER	DISTORTED	1,620.40	1,620.40
10	REAR BUMPER CLIPS	NECESSARY	80.00	30.00
1	REAR BUMPER TOWING COVER	DEFORMED	65.10	65.10
1	RHR BUMPER REFLECTOR	CRACKED	78.70	78.70
2	REVERSE SENSOR	DAMAGED (1 PC ONLY)	661.60	265.00
1	REVERSE SENSOR WIRING HARNESS	SNAPPED	1,548.50	1,548.50
1	REAR BUMPER REINFORCEMENT BAR	BENT	530.70	530.70
1	REAR END PANEL	TO REPAIR SEE LABOUR	484.80	-
1	REAR END PANEL TRIM	NOT NECESSARY	85.00	-
6	REAR END PANEL TRIM CLIPS	NOT NECESSARY	48.00	-
1	REAR BUMPER LOWER ALUMINIUM PLATE	BENT	98.70	98.70
1	REAR BUMPER BRACKET CENTRE	CRACKED	105.30	105.30
1	REAR BUMPER BRACKET CENTRE	CRACKED	105.30	105.30
1	LHR BUMPER BRACKET	NOT NECESSARY	150.70	-
1	RHR BUMPER BRACKET	CRACKED	150.70	150.70
1	LHR BUMPER BRACKET LOWER	NOT NECESSARY	124.30	-
1	RHR BUMPER BRACKET LOWER	NOT NECESSARY	124.30	-
	LESS 10% DISCOUNT		-978.89	-674.79
			8,810.01	6,073.11
SPECIAL NETT ITEMS				
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	120.00	-
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	100.00	-
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	TAILGATE WINDSCREEN SOLAR FILM (SN)	NOT NECESSARY	220.00	-
			560.00	60.00

Report Ref No. CS/AGI20003272/Aqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN, ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,200.00	500.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		1,000.00	600.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		80.00	50.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		50.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		100.00	60.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.		150.00	80.00
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	50.00	-
	TO APPLY SEALANT TO REAR TAIL GATE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.		120.00	120.00
			2,830.00	1,440.00
	GRAND TOTAL		12,200.01	7,573.11
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,050.00

Report Ref No. CS/AGI20003272/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.