

RANS-CAB AUTO SERVICES PTE LTD
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9692C - AXA

Francis

PART BY PART

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9692C - Francis
 KL1LA69RJBB121796*
 CHEVROLET
 EPICA 2.0
 06.01.2014
AXA

PART

LIST

1	1	Front Bumper	\$	Bul/121 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	Bul 295.25 ✓
3	1	Front Bumper Lower Absorber	\$	CPA 180.00 ✓
4	1	Front Bumper Lower Grille	\$	Dit 78.00 ✓
5	1	Front Bumper Retainer RH	\$	CPA 102.00 ✓
6	1	Front Bumper Retainer LH	\$	Dit 102.00 ✓
7	1	Front Bumper Lower Stiffener	\$	R 134.37 X
8	1	Front Headlamp RH	\$	CPA 816.00 ✓
9	1	Front Headlamp LH	\$	Bul 816.00 ✓
10	1	Front Bumper Fog Lamp Outer Cover LH	\$	Sum 32.40 X
11	1	Front Support Panel Assy (Panel A-Frt)	\$	Bul 1,222.32 ✓
12	1	Bonnet (Panel A-Hood)	\$	Bul 1,250.00 ✓
13	1	Bonnet Centre 'CHEVROLET' Logo Badge	\$	Sum 144.30 ✓
14	1	Bonnet Moulding	\$	Dit 257.00 ✓
15	1	Bonnet Insulator	\$	Deform 84.63 ✓
16	1	Bonnet hinge RH	\$	R 36.00 X
17	1	Bonnet hinge LH	\$	R 36.00 X
18	1	Bonnet cable	\$	Th 150.00 ✓
19	1	Bonnet lock	\$	Bul 200.00 ✓
20	1	HORN LH	\$	Dit 159.20 ✓
21	1	Radiator Grille (Grille A-Rad)	\$	CPA 367.00 ✓
22	1	Radiator Assembly (Radiator A)	\$	Bul/Per 618.00 ✓
23	1	Aircon Condenser (Conderser A)	\$	Bul 600.00 ✓
24	1	Air Intercooler (Cooler A-Air Charge)	\$	Bul/Per 652.00 ?
25	1	Fan Blade (Fan A-Auxiliary (Diesel) Small)	\$	CPA 536.00 ✓
26	1	Fan Blade (Fan A-Eng Cool (Diesel) Big)	\$	CPA/Th 634.00 ✓
27	1	Front Fender LH	\$	Bul 837.60 ✓
28	1	Front Fender RH	\$	Bul 837.60 ✓
29	1	Fender Insulation LH	\$	Sum 39.00 X
30	1	Front Fender Liner LH	\$	Bul 47.00 X
31	1	Fender Insulation RH	\$	Sum 39.00 X
32	1	Front Fender Liner RH	\$	Bul 47.00 X
33	1	Fuse Box	\$	Per 716.00 X

RANS-CAB AUTO SERVICES PTE LTD
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHD 9692C - AXA

Francis

PART BY PART

34	1	Air intake resonator (beside fender)	\$	Sm	20.01 X
35	1	Air intake resonator hose (bottom)	\$	Sm	60.90 X
36	1	Air intake resonator tank top bracket	\$	R	45.00 X
37	1	Resonator A-A/CL	\$	Sm	37.00 X
38	1	Engine Splash Cover RH (Cover A-Engine)	\$	CRM	168.00 —
39	1	Engine Splash Cover LH (Cover A-Engine)	\$	Sm	168.00 X
40	1	Front Seat Belt RH (Belt A-Frt Seat RH)	\$	Sm	402.50 X
41	1	Front safety belt cover garnish	\$	Sm	125.00 X
42	1	Front Seat Belt LH (Belt A-Frt Seat LH)	\$	Sm	402.50 X
43	1	Front safety belt cover garnish	\$	Sm	125.00 X
44	1	Front Door RH (Panel A-Frt DR RH)	\$	R	1,133.00 X
45	1	Front Door LH (Panel A-Frt DR LH)	\$	R	1,133.00 X
46	1	Front Side Rocker Panel Garnish LH	\$	Br	236.40 —
47	1	Front Side Rocker Panel Garnish RH	\$	Sm	236.40 X
48	1	Front Windscreen (Glass A-W/ Shield)	\$	Cr	1,304.00 —
49	1	Front Windscreen Moulding (Moulding A-W/ Si	\$	me	196.00 —
50	1	Rear Bumper	\$	BT	1,202.00 —
51	1	Rear Bumper Beam	\$	Br	239.94 —
52	1	Rear Bumper Centre Absorber	\$	CRM	260.00 —
53	1	Rear Bumper Side Retainer RH	\$	CRM	68.76 —
54	1	Rear Bumper Side Retainer LH	\$	CRM	68.76 —
55	1	Rear Bumper side support RH	\$	mi	25.00 —
56	1	Rear Bumper side support LH	\$	mi	25.00 —
57	1	Rear Bumper Reflectors RH	\$	Br	119.74 —
58	1	Rear Bumper Reflectors LH	\$	Br	119.74 —
59	1	Rear bumper stay RH	\$	mi	35.00 —
60	1	Rear bumper stay LH	\$	mi	35.00 —
61	1	Rear Bumper Tow Hook Cover	\$	mi	93.00 —
62	1	Rear Luggage Floor Panel	\$	Br/Br	973.00 —
63	1	Rear Luggage Floor Panel Insulator	\$	me	63.50 —
64	1	Rear Luggage Floor Panel Trim Board	\$	Tr	378.00 —
65	1	Rear End Panel Inner	\$	Br	336.84 —
66	1	Rear End Panel Outer	\$	Br	623.76 —
67	1	Rear End Panel Inner Trim	\$	CRM	263.84 —
68	1	Bootlid	\$	Br	973.00 —
69	1	Bootlid inner trim board	\$	Deform	400.00 —
70	1	Bootlid Weatherstrip	\$	Tr	344.28 —
71	1	Bootlid Lock - Top	\$	Br	466.56 —
72	1	Bootlid lock - bottom	\$	Br	39.40 —
73	1	Bootlid 'CHEVROLET' Badge	\$	me	120.62 —
74	1	Bootlid Logo	\$	me	138.84 —
75	1	Bootlid 'EPICA LT' Badge	\$	me	119.84 —

TRANS-CAB AUTO SERVICES PTE LTD

NO. 466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO. 6287 6666 FAX NO. 6366 8862

DO/GST REG NO. 201019626G

SHD 9692C - AXA

Francis

PART BY PART

76	1	Rear number plate lamp RH	\$	Sim	25.00 X
77	1	Rear number plate lamp LH	\$	Sim	25.00 X
78	1	Bootlid inner handle	\$	Sim	45.55 X
79	1	Bootlid Reflector Centre	\$	CRA	217.97
80	1	Bootlid Reflector RH	\$	CRA	128.40
81	1	Bootlid Reflector LH	\$	CRA Sim	128.40 X
82	1	Rear Gas T/Gate Spring RH	\$	Per Sim	286.90 X
83	1	Rear Gas T/Gate Spring LH	\$	Per	286.90
84	1	Bootlid Hinge RH	\$	Bt	120.00
85	1	Bootlid Hinge LH	\$	Bt	120.00
86	1	Rear Tail Lamp RH	\$	Bt	479.30
87	1	Rear Tail Lamp Panel RH	\$	Bt	359.00
88	1	Rear Tail Lamp LH	\$	Bt	479.30
89	1	Rear Tail Lamp Panel LH	\$	Bt	359.00
90	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R	1,110.00 X
91	1	Rear Fender RH	\$	Bt	1,145.00
92	1	Rear Fender Inner Cowling RH	\$	CRA	298.00
93	1	Rear Fender Inner Trim RH	\$	Tn	418.44
94	1	Rear Fender Inner Wheel House Panel RH	\$	Bt	2,556.35
95	1	Rear fender inner wheel house extension RH	\$	Bt	180.00
96	1	Rear Fender Center Panel RH	\$	Bt	986.23
97	2	Rear Fender Air Vent Lourve RH	\$	Sim	163.22 X
98	1	Rear Fender LH	\$	Bt	1,145.00
99	1	Rear Fender Inner Cowling LH	\$	CRA	298.00
100	1	Rear Fender Inner Trim LH	\$	Tn	418.44
101	1	Rear Fender Inner Wheel House Panel LH	\$	Bt	2,556.35
102	1	Rear fender inner wheel house extension LH	\$	Bt	180.00
103	1	Rear Fender Center Panel LH	\$	Bt	986.23
104	1	Diesel Tank Filler Pipe (Tube A Fuel Filler)	\$	Sim	157.00 X
105	1	Diesel Tank Cap (Cap A Fuel Filler)	\$	Sim	46.00 X
106	1	Diesel Tank Door Panel (Door A Fuel Filler)	\$	Sim	75.00 X
107	1	Holder A Fuel Filler	\$	Sim	50.00 X
108	1	Cable A Fuel Filler	\$	Sim	160.00 X
109	1	Cable Lock A Fuel Filler	\$	Sim	25.00 X
110	1	Longitudinal A-RR LH	\$	Sim	709.20 X
111	1	Longitudinal A-RR RH	\$	Sim	709.20 X
112	1	Crossmember Out Panel A-RR FLR	\$	R	226.05 X
113	1	Rear Door RH (Panel A-RR DR RH)	\$	Bt	1,133.00
114	1	Rear door weatherstrip - Inner RH	\$	Sim	41.40 X
115	1	Rear door weatherstrip - 2nd Frame RH	\$	Sim	25.90 X
116	1	Rear door top hinge RH	\$	Bt	35.00
117		Rear door bottom hinge RH	\$	Bt	35.00

RANS-CAB AUTO SERVICES PTE LTD
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9692C - AXA

Francis

PART BY PART

118	1	Rear door inner lock RH	\$
119	1	Rear door check / arrestor RH	\$
120	1	Rear door lock striker / latch RH	\$
121	1	Rear door outer weatherstrip moulding RH	\$
122	1	Rear door outer handle RH	\$
123	1	Rear door outer handle - rubber seal RH	\$
124	1	Rear door inner opening handle RH	\$
125	1	Rear door inner trim board RH	\$
126	1	Rear door kicking plate / step garnish RH	\$
127	1	Rear door glass RH	\$
128	1	Rear door window glass channel weatherstrip	\$
129	1	Rear door window glass channel holder RH	\$
130	1	Rear door channel weatherstrip / felt RH	\$
131	1	Rear door interior light switch RH	\$
132	1	Rear door power window motor (master) RH	\$
133	1	Rear door regulator gear RH	\$
134	1	Rear door regulator handle RH	\$
135	1	Rear fender 1/4 glass with moulding RH	\$
136	1	Rear Door LH (Panel A-RR DR RH)	\$
137	1	Rear door weatherstrip - Inner LH	\$
138	1	Rear door weatherstrip - 2nd Frame LH	\$
139	1	Rear door top hinge LH	\$
140	1	Rear door bottom hinge LH	\$
141	1	Rear door inner lock LH	\$
142	1	Rear door check / arrestor LH	\$
143	1	Rear door lock striker / latch LH	\$
144	1	Rear door outer weatherstrip moulding LH	\$
145	1	Rear door outer handle LH	\$
146	1	Rear door outer handle - rubber seal LH	\$
147	1	Rear door inner opening handle LH	\$
148	1	Rear door inner trim board LH	\$
149	1	Rear door kicking plate / step garnish LH	\$
150	1	Rear door glass LH	\$
151	1	Rear door window glass channel weatherstrip	\$
152	1	Rear door window glass channel holder LH	\$
153	1	Rear door channel weatherstrip / felt LH	\$
154	1	Rear door interior light switch LH	\$
155	1	Rear door power window motor (master) LH	\$
156	1	Rear door regulator gear LH	\$
157	1	Rear door regulator handle LH	\$
158	1	Rear fender 1/4 glass with moulding LH	\$
159	1	Roof panel Out	\$

Del	425.00	✓
Sub	65.00	X
R	120.00	X
Br	85.00	✓
Sub	60.00	X
Sub	25.00	X
Sub	45.50	X
Deform	455.69	✓
Sub	63.25	X
Sub	420.35	X
Del	143.25	✓
Sub	205.60	X
Dis/Del	89.50	✓
Sub	139.20	X
Sub	274.97	X
R	55.30	X
Sub	65.30	X
Shattered	215.00	✓
Br	1,133.00	✓
Del	41.40	✓
Del	25.90	✓
Br	35.00	✓
Br	35.00	✓
Del/Sub	425.00	✓
Sub	65.00	X
R	120.00	X
Del	85.00	✓
Dis/Br	60.00	✓
Sub	25.00	X
Sub	45.50	X
Deform	455.69	✓
Sub	63.25	X
Sub	420.35	X
Del	143.25	✓
Sub	205.60	X
Dis/Del	89.50	✓
Sub	139.20	X
Sub	274.97	X
Br	55.30	✓
Shattered	65.30	X
Shattered	215.00	✓
Br/Del	1,784.15	✓

RANS-CAB AUTO SERVICES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835
TEL NO.6287 6666 FAX NO.6366 8862

CO/GS

SHD 9

Francis

PART BY PART

160	1	Roof panel inner	\$	R	984.15	X
161	1	Roof top inner side panel LH	\$	R	385.00	X
162	1	Roof top inner side panel RH	\$	R	385.00	X
163	1	Roof top center side panel LH	\$	R	475.23	X
164	1	Roof top center side panel RH	\$	R	475.23	X
165	1	Roof top out side panel LH	\$	Bar	356.85	—
166	1	Roof top out side panel RH	\$	Bar	356.85	—
167	1	Roof side moulding - roof gutter LH	\$	Bar	45.00	—
168	1	Roof side moulding - roof gutter RH	\$	Bar	45.00	—
169	1	Roof lining	\$	Reform	1,345.60	✓
170	1	Centre pillar outer LH	\$	R	446.00	X
171	1	Centre pillar inner LH	\$	R	460.00	X
172	1	Centre pillar outer RH	\$	R	446.00	X
173	1	Centre pillar inner RH	\$	R	460.00	X
174	1	Centre Pillar Reinforcement (Centre) LH	\$	R	596.00	X
175	1	Centre Pillar Reinforcement (Centre) RH	\$	R	596.00	X
176	1	Rear Axle Housing (Axle A-RR)	\$		711.00	?
177	1	Parallel Link RR (Link A-Parallel RR)	\$		93.00	?
178	1	Parallel Link Frt (Link A-Parallel Frt)	\$		93.00	?
179	1	Stabilizer Bar RR (Bar RR Stabilizer	\$		97.00	?
180	1	Trailing Link RR RH (Link A-Trailing RR RH)	\$		90.00	?
181	1	Trailing Link RR LH (Link A-Trailing RR LH)	\$		90.00	?
182	1	Upr Arm RH (Arm A-Upr RH)	\$		343.00	?
183	1	Upr Arm LH (Arm A-Upr LH)	\$		343.00	?
184	1	Rear Knuckle Arm LH	\$		350.00	?
185	1	Rear Knuckle Arm RH	\$		350.00	?
186	1	Rear shock absorber LH	\$		243.57	?
187	1	Rear shock absorber top mounting LH	\$		51.65	?
188	1	Rear shock absorber RH	\$		243.57	?
189	1	Rear shock absorber top mounting RH	\$		51.65	?
190	1	Rear hand brake cable	\$		1,021.90	?
191	1	Rear hand brake cable o/s	\$		231.90	?
192	1	Break Down Triangle Sign With Box	\$		100.00	?
193	1	Rear Seat LOWER	\$	R	734.50	X
194	1	Rear Seat Garnish TOPPER	\$		1,012.35	?
195	1	Diesel Tank (Tank A-Fuel)	\$		717.00	?
196	1	Diesel Tank Filler Pipe (Tube A Fuel Filler)	\$		157.00	?
197	1	Diesel Tank Cap (Cap A Fuel Filler)	\$		46.00	?
198	1	Diesel Tank Door Panel (Door A Fuel Filler)	\$		75.00	?
199	1	Holder A Fuel Filler	\$		50.00	?
200	1	Cable A Fuel Filler	\$		160.00	?
201	1	Cable Lock A Fuel Filler	\$		25.00	?

X NN

X NN

check

NN

TRANS-CAB AUTO SERVICES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9692C - AXA

Francis

PART BY PART

202	1	PANEL A-BACK UPR	\$	Sur	800.00	X
203	1	SHELF A-BACK UPR INCL(TRIM)	\$	Sur	400.00	X
204	1	W/HARNESS-TRK ROOM (Reflector Circuit)	\$	Sur	68.35	X
205	1	REAR BOOT HARNESS	\$	Sur	101.25	X
206	1	Third brake light	\$	CPM	350.64	—
207	1	Rear Windscreen Glass With Moulding	\$	Shattered	1,647.00	—
208	1	Rear Windscreen Weatherstrip Seal	\$	Sur	68.50	—
209	1	Rear windscreen inner garnish side RH	\$	CPM	185.00	—
210	1	Rear windscreen inner garnish side LH	\$	CPM	185.00	—
211	1	Rear windscreen inner top garnish	\$	Dis	80.00	—

TOTAL	\$	73,708.54
10%	\$	7,370.85
	\$	66,337.69

Specical Nett

1Set	Front Bumper Fastener Clip	\$	Sur	24.00	—
1Set	Front Licence Plate With Holder	\$	Sur	192.00	45.50
2	Front windscreen sealant	\$	Sur	80.00	40.50
1	Front windscreen inner sponge seal	\$	Sur	100.00	30.50
2	Front ERP Sticker	\$	Sur	40.00	26.50
1Set	Roof lining Clip	\$	Sur	45.00	—
1Set	Bonnet Insulator Clip	\$	Sur	40.00	—
1Set	Radiator Grille Clip	\$	Sur	18.00	—
1Set	Bootlid inner trim board Clip	\$	Sur	40.00	—
1Set	Radiator Grille Top Cover Clip	\$	Sur	10.00	—
1Set	Front Fender Liner Clip	\$	Sur	40.00	X
1Set	Engine Splash Cover Clip RH	\$	Sur	12.00	—
1Set	Engine Splash Cover Clip LH	\$	Sur	12.00	X
1Set	Rear Bumper Parking Sensor	\$	Tr	300.00	—
1Set	Rear Bumper Fastener Clip	\$	Sur	30.00	—
2Set	Rear Fender inner cowling clip	\$	Sur	30.00	—
1Set	Rear Fender Inner Trim Clip RH	\$	Sur	30.00	—
1Set	Rear Fender Inner Trim Clip LH	\$	Sur	30.00	—
1Set	Rear Bumper End Dust Cover Clip	\$	Sur	30.00	—
1	Rear Boot Sticker 'Trans-cab'	\$	Sur	30.00	—
1	Rear Boot Sticker '6555-3333'	\$	Sur	30.00	—
2	Door Sticker "Trans-cab"	\$	Sur	120.00	—
2	Door Sticker "6555-3333"	\$	Sur	120.00	—
1	Rear door inner trim board LH Clip	\$	Sur	45.00	—
1	Rear door inner trim board RH Clip	\$	Sur	45.00	—

RANS-CAB AUTO SERVICES PTE LTD

NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9692C - AXA**Francis****PART BY PART**

1	Rear Exhaust Mounting	\$	10.00 X
1	Rear Bumper End Sealant	\$	80.00 X
1	Spare Tyre Board	\$	10.00 X
1	Spare Tyre	\$	180.00 X
1	Spare Wheel Rim	\$	126.74 X
1	Spare Tyre Board	\$	10.00 X
1	Spare tyre fastener bolt	\$	65.00 X
1	Rear Tyre RH	\$	360.00 John
1	Rear Wheel Rim RH	\$	254.00 X
1	Rear Tyre LH	\$	360.00 X
1	Rear Wheel Rim LH	\$	254.00 X
2	Hub Cup Rim	\$	70.00 X
2	Rear Windscreen Sealant	\$	80.00 4000
1	Rear Windscreen Inner Sponge Seal	\$	100.00 John
1 Set	SHELF A-BACK UPR INCL(TRIM)Clip	\$	20.00 X

TOTAL \$ 3,472.74**TOTAL PARTS \$ 69,810.43**

Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And
Renewal Of Parts, Adjust And Realign The
Same

\$ 28,000.00 6000

To Check Electrical Lighting Concerned.

\$ 170.00 600

To Rust-Proofing Of The Affected Areas.

\$ 170.00 ✓

Putty And Spray Painting Of The Affected
Portion.

\$ 27,000.00 3000

To Remove And Refit Front W/ Screen Glass
To Facilitate Bodywork Repair.

\$ 170.00 1200

To dismantle and refit rear undercarriage
parts, final checking and testing.

\$ 380.00 2400

To drop diesel tank, pipes, hoses to facilitate
bodywork repair, final checking and testing.

\$ 380.00 800

RANS-CAB AUTO SERVICES PTE LTD
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9692C - AXA

Francis

PART BY PART

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	} 601
To repair and realign rear exhaust pipe.	\$	170.00	
To reinstall rear bumper parking sensor.	\$	170.00	601
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	2501
To drop diesel/petrol tank, pipes, hoses and renew the necessary parts and final checking and testing for leak.	\$	Repair 440.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
To transfer of door and roof panel fittings and conduct water seepage test.	\$	340.00	1201
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	801
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	} 1501
To transfer of luggage floor panel fittings and conduct water seepage test.	\$	170.00	
To transfer of boot fittings and conduct water seepage test.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	Repair 380.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.466-468 TAGORE INDUSTRIAL AVENUE SINGAPORE 787835
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9692C - AXA

Francis

PART BY PART

To check steering geometry and computer wheel alignment	\$	220.00 60/
To transfer of tire, rim and on wheel balancing.	\$	170.00 20/
To Remove And Refit Rear W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120/
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	~ 120.00 X
To check ABS brake efficiency, final checking and testing.	\$	~ 380.00 X
To remove and refit ABS pump relay to enable repair.	\$	~ 380.00 X
To remove and refit air bag system and reset.	\$	480.00 7.
To vacuum, replace, refix and recharge air condenser	\$	380.00 100/
To replace, refix and top up coolant for radiator	\$	170.00 50/
To vacuum, replace, refix and recharge Air Intercooler	\$	Repaired 170.00 X
Towing Fees.	\$	120.00 100/
	\$	<u>61,680.00</u> 62,520.00

TOTAL \$ 131,490.43

132,130.43

Repair Days

45 Days