

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Mar 2020		27 Feb 2020 15:06 Edit Adj Rpt	S\$8,521.52 Edit Estimates	S\$8,521.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured: NORFAHIZAH BINTE ABDUL MAJID , ID: S7902679D, Tel: +6598360174				
Vehicle Reg. No.: SME3960D		Date of Loss: 06/02/2020 18:00 - :59 [16 Months and 10 Days From LTA Reg Date (Man Yr)]		
Claim Type: OD / 6208400656SG		Policy/Cover Note No.: 1800115446-01 (Comprehensive)		
		Excess: S\$600.00		
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911				
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/03/2020]				
Driver/Custodian: ALI BIN LATIP (44 / Male) , NRIC: S7508576A, Tel: +6592370401 Email: DUJARZ@HOTMAIL.COM				
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
- AIG_SG (22/07/2020): Alert - Adj Mandate Approved (S\$8521.52) - SME3960D - Claim Handler: Mithoo Sing... - AIG_SG (03/03/2020): Alert - Adj Mandate Approved (S\$2592.00) - SME3960D - Claim Handler: Mithoo Sing... - AIG_SG (03/03/2020): SME3960D / OD / 06/02/2020 / Coverage & Excess update				
ALL ASSOCIATED TASKS			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
Handler	Assigned By	Completed On	Created On	Done?
No results.				

Claim Documents

***SME3960D (6208400656SG)**
OD
Feb 6 2020 6:45PM
[NORFAHIZAH BINTE ABDUL MAJID]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼		
Assessment Reports															1 per page ▼			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	28/02/20 09:41		Adjuster Immediate Advice												Load HTM					
2	06/03/20 14:14		Adjuster Immediate Advice												Load HTM					
Photos/Images															3 per page ▼			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	28/02/20 08:56		General View												Load JPG		☒			
2	28/02/20 08:56		General View												Load JPG		☒			
3	28/02/20 08:56		General View												Load JPG		☒			
4	28/02/20 08:56		General View												Load JPG		☒			
5	28/02/20 08:56		General View												Load JPG		☒			
6	28/02/20 08:56		General View												Load JPG		☒			
7	28/02/20 08:56		General View												Load JPG		☒			
8	28/02/20 08:56		General View												Load JPG		☒			
9	28/02/20 08:56		General View												Load JPG		☒			
10	28/02/20 08:56		General View												Load JPG		☒			
11	28/02/20 08:56		General View												Load JPG		☒			
12	28/02/20 08:56		General View												Load JPG		☒			
13	28/02/20 08:56		General View												Load JPG		☒			
14	28/02/20 08:56		General View												Load JPG		☒			
15	28/02/20 08:56		General View												Load JPG		☒			
16	28/02/20 08:56		General View												Load JPG		☒			
17	28/02/20 08:56		General View												Load JPG		☒			
18	28/02/20 08:56		General View												Load JPG		☒			
19	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
20	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
21	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
22	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
23	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
24	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
25	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
26	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
27	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
28	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
29	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
30	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
31	06/03/20 14:17		Reinspection Photo												Load JPG		☒			
32	21/04/20 16:44		Reinspection Photo												Load JPG		☒			
33	21/04/20 16:44		Reinspection Photo												Load JPG		☒			
34	21/04/20 16:44		Reinspection Photo												Load JPG		☒			
35	21/04/20 16:44		Reinspection Photo												Load JPG		☒			
36	21/04/20 16:44		Reinspection Photo												Load JPG		☒			
37	21/04/20 16:44		Reinspection Photo												Load JPG		☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/04/20 16:44	Reinspection Photo	Load JPG	☒
39	21/04/20 16:44	Reinspection Photo	Load JPG	☒
40	21/04/20 16:44	Reinspection Photo	Load JPG	☒
41	21/04/20 16:44	Reinspection Photo	Load JPG	☒
42	21/04/20 16:44	Reinspection Photo	Load JPG	☒
43	21/04/20 16:44	Reinspection Photo	Load JPG	☒
44	21/04/20 16:44	Reinspection Photo	Load JPG	☒
45	21/04/20 16:44	Reinspection Photo	Load JPG	☒
46	21/04/20 16:44	Reinspection Photo	Load JPG	☒
47	21/04/20 16:44	Reinspection Photo	Load JPG	☒
48	21/04/20 16:44	Reinspection Photo	Load JPG	☒
49	21/04/20 16:44	Reinspection Photo	Load JPG	☒
50	21/04/20 16:44	Reinspection Photo	Load JPG	☒
51	21/04/20 16:44	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/02/20 16:09	ESTIMATE	Load PDF	
2	27/02/20 16:09	SG CAR MART AND LTA	Load PDF	
3	27/02/20 16:11	Singapore Accident Statement	Load PDF	
4	03/03/20 15:39	driving license, under taking, interview letter, insurance cert	Load PDF	
5	15/06/20 17:22	SUPPLEMENTARY	Load PDF	
6	19/06/20 13:32	estimate	Load PDF	
7	22/07/20 13:26	email correspond	Load PDF	
8	24/08/20 16:21	DISCHARGE VOUCHER	Load PDF	
9	24/08/20 16:21	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/02/20 14:05	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/02/20 13:49	Accident Photo	Load JPG	☒
2	25/02/20 13:49	Accident Photo	Load JPG	☒
3	25/02/20 13:49	Accident Photo	Load JPG	☒
4	25/02/20 13:49	Accident Photo	Load JPG	☒
5	25/02/20 13:49	Accident Photo	Load JPG	☒
6	25/02/20 13:49	Accident Photo	Load JPG	☒
7	25/02/20 13:49	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	25/02/20 13:44	Sketch Plan	Load JPG	☒
2	25/02/20 13:44	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20003277/R1TD3S2**Date:** 24/08/2020**REFERENCE**

Insured/Claimant: NORFAHIZAH BINTE ABDUL MAJID Policy No: 1800115446-01
Date of Loss: 06/02/2020 Nature of Claim: OD Claim No: 6208400656SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME3960D**
Make & Model: AUDI A3, 1.4 TFSI S-TRONIC (A) Engine No: CZE807256
Reg. Date: 27/09/2018 (Man. Year: 2018) Chassis No: WAUZZZ8VXJ1083656
Colour: Black Odometer: 34813 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$98,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R18 Rear Tyre Size: 205/55 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,785.76	5,449.52	4,336.24	44.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,432.00	3,072.00	360.00	10.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,217.76	8,521.52	4,696.24	35.53
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	12,617.76	7,921.52	4,696.24	37.22
+ GST 7.00/7.00% (S\$)	883.24	554.51	328.73	37.22
Nett Amount (S\$)	13,501.00	8,476.03	5,024.97	37.22

INSPECTION

Date of Assignment: 27/02/2020
Date Inspected: 27/02/2020 Inspected At: 24 BENOI SECTOR
Estimated Period of Repair: 6.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE OIL SUMP LOWER PART	Bent	310.00 FS	*310.00 FS
2	1		*SILICON SEALANT	Necessary	92.16 FS	*92.16 FS
3	1		*HIGH LUBRICITY ENGINE OIL	Necessary	214.00 FS	*214.00 FS
4	1		*STEERING GEAR	Cracked	3,602.40 FS	*3,602.40 FS
5	1		*NOISE INSULATION COVER	Cracked	195.20 FS	*195.20 FS
6	1		*STEERING GEAR	Repeated	3,071.00 FS	*- FS
7	1		*SET STEERING BOX REPAIR	Necessary	44.00 FS	*34.72 FS
8	2		*TRACK ROD	Serviceable	175.00 FS	*- FS
9	2		*TIE ROD END - LH / RH	Serviceable	242.00 FS	*- FS
10	1		*ASSEMBLY CARRIER	Cut	962.00 FS	*769.60 FS
11	1		*SET BONDED RUBBER BUSHES - UPPER / LOWER	Necessary	154.00 FS	*123.20 FS
12	2		*ASSEMBLY CARRIER SUPPORT - LH / RH	Cracked	44.00 FS	*17.36 FS
13	1		*STABILIZER BAR	Serviceable	380.00 FS	*- FS
14	1		*SUNDRIES	Necessary	300.00 FS	*90.88 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	9,785.76 5,449.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW ENGINE OIL SUMP AND OTHER ENGINE COMPONENTS. TO REFILL ENGINE OIL.	New	480.00	480.00
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	0.00
3	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	New	2,400.00	2,400.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			3,432.00	3,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >