

ASS. REC. BY: Asu

REF:

A19

CC3/A1920003277/RT63

6790

ASSIGNMENT

From: _____

Date: 27.2.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 3960Dat Workshop m/s Premiumof 24 Benoi Sector

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: \$600

(Client's Record)

Make of Veh: 11a.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 98K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SME 3960DYr Regn: 2018 / SEPType: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A3 Sedan 1.4 TFSIc.c 1395Colour: BLACK

A/C: Insured / Std / NI / NA

Sp. Reading: 34813

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2228VXJ1083656Gen. Cond: Good / Fail / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 205/55R18R: 205/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 06/02/2020D.O.I. 27/02/2020Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/2- Revert via manmen.3/3 @ 16:44- mandate approval by victor3/3 @ 5:03pm. inform work shop authorise repair excess \$600.Part by part \$8521.52

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 3960 D

S/N Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assv.	S/N \$ 360.00	X NN
2	To remove and reinstall front suspension assy with subframe. Inspect for damages and renew if necessary.	S/N \$ 2,400.00	✓
3	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,952.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 3960 D

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	STEERING GEAR X SVC	\$ 3,071.00	X
2	STEERING BOX REPAIR SET NEC /	\$ 44.00	34.72
3	TRACK ROD X SVC	2 \$ 175.00	X
4	TIE ROD END - LH / RH X SVC	2 \$ 242.00	X
5	ASSEMBLY CARRIER cut /	\$ 962.00	769.60
6	BONDED RUBBER BUSHES SET - UPPER / LOWER ? NEC /	\$ 154.00	123.20
7	ASSEMBLY CARRIER SUPPORT - LH / RH CRA /	2 \$ 44.00	17.36
8	STABILIZER BAR X SVC	\$ 380.00	X
9	SUNDRIES ? NEC /	\$ 300.00	✓ 90.88
TOTAL SPARE PARTS CHARGES		: \$ 5,372.00	
TOTAL LABOUR CHARGES		: \$ 2,952.00	
GRAND TOTAL		: \$ 8,324.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

ENGINE LOWER COVER - CR /