

22/03/2002

ASS. REC. BY:

REF: CS/TM1 2000 3284/Pvt302

Special Instruction:

Survivor: Ram

ASSIGNMENT (Office)

From (Person): Fiona Ram Bu Song

of

TM1

Date/Time: 27.2.2020 14.43p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 2689P

Insured:

YN 9179P

at Workshop m/s

Combaradulgro

Tel:

62148300

of

59 loyang Drive

Policy No:

MT 107239

Claim No:

M 2001511

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

26.2.2020

CA / REV / REP. / REV 24 HRS

Date/Time:

27/2/2020

2.14p.m

Person Contacted:

Jumani

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate.
	SHC 2689P - CSI FC1 18004505 / R19d3n2 RDA - 04/03/2018
	YN 9179P - NA/CT217021633 / r3 RDA - 11/11/2017
28/2/20	Sand preli revised via merimen

ASS. REC. BY: Ram

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YN 9179P

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 2699P Yr Regn: 20/08/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata c.c 1991Colour: blue A/C: Insured / Std / NI / NASp. Reading: 194467 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHETA1VMCA828919Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or HarpoonFront RearR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 26/02/2020 D.O.I. 27/02/2019Survey held at comfortdelgo (copy)Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orO/S rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Waiting for confirmation
	if still proceeding Proceeding to repair
	L/S: \$3000/- with 4 repair days
	confirm with sumari on 10/3/2020
	(Red 4736.02, 61%)
	Total rebate: \$11793
	Back value: \$9706
	Repair limit: \$3087

RECEIVED 12 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 12/3 - typistDays Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

24011261

Report Format:

merimen

Lump Sum / L.S.:

3000/-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Feb 2020 Sendback Est	27 Feb 2020 10:57 \$7,736.02	27 Feb 2020 14:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	S.P.M FROZEN FOOD PTE. LTD., Co. Reg. No.: 200412500R		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC2689P	Date of Loss:	26/02/2020 00:00 - :59 [89 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2001511	Policy/Cover Note No.:	MT107239 (Comprehensive) Coverage: 14/09/2019 - 13/09/2020
Vehicle Reg. No. (Insured):	YN9179P	Policy No. (Claimant):	
		Excess:	\$S0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/03/2020]		
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fiona Gan Bee Song

Date: 28 Feb 2020

Preliminary Advice

Insured Vehicle No : YN9179P

TP Vehicle No : SHC2689P

Accident Date : 26/02/2020

Make : HYUNDAI SONATA

Assignment Date : 27/02/2020

Date of Inspection :27/2/2020

Est. Duration of Repair :4

Inspection At :COMFORTDELGRO ENGINEERING PTE LTD

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,736.02
Revised Amount	:S\$	5,836.10
Check Items (Estimated)	:S\$	886.64
Total	:S\$	6,722.74

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC2689P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Feb 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	D4EAC159559
Chassis No.:	KMHET41VMCA828919
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$14,509.00
Original Registration Date:	30 Aug 2012
First Registration Date:	30 Aug 2012
Transfer Count:	0
Actual ARF Paid:	\$14,509.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2020
PARF Rebate Amount:	\$8,705.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$48,892.00
COE Rebate Amount:	\$3,088.00
Total Rebate Amount:	\$11,793.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Feb 2020

① Cost of taxi : \$88,272.75 OK

ARF 60% = $\$14,509 \times 60\% = \underline{\$8,705.4}$

Depri : $(\$88,272.75 - \$8,705.4) \div 96 \text{ months}$
= \$828.32 / =

② Book value = $(\$828.32 \times 6 \text{ months}) + \$8,705.4$
= \$13,678.32

③ $\$13,678.32 - \$11,793 = \underline{\$1,885.32}$

Report ID : ZPTCPL32
DATE : 27.02.2020
TIME : 14:51:13

Comfort Transportation PL
Vehicle NAV for Fleet Safety Division
AS AT 31.01.2020

USER ID : CTPNEX03
PAGE : 1

Co. Code : CTEPL
Licence Pl. No : SHC2689P
Old Asset No :
Veh. Model : Hyundai Sonata
Reg. Date : 30.08.2012
Cap. Date : 30.08.2012
Accident. Date : 26.02.2020
Veh. Age : 090

Asset No	SA No	Bal. Dep. Mths	Pur Mth. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap Value/Estimated PAGE Refund
			\$	\$		\$	\$	\$	\$	\$	\$
10029455	0	000	242.54	0.00	SHC2689P HSN 30.08.2012 BASIC COST \$21830 W AIRCON	21,830.00	21,586.46	242.54	21,829.00	1.00	1.00
10029455	1	000	32.24	0.00	SHC2689P HSN 30.08.2012 IMPORT DUTY	2,901.75	2,869.51	32.24	2,901.75	0.00	0.00
10029455	2	000	64.49	0.00	SHC2689P HSN 30.08.2012 ARF 100%OWS14509	14,509.00	5,739.51	64.49	5,804.00	8,705.00	8,705.00
10029455	3	000	543.24	0.00	SHC2689P HSN 30.08.2012 CIE 80%	48,892.00	48,348.76	543.24	48,892.00	0.00	0.00
10029455	4	000	0.00	0.00	SHC2689P HSN 30.08.2012 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10029455	5	000	0.00	0.00	SHC2689P HSN 30.08.2012 AIE CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10029455	6	000	0.00	0.00	SHC2689P HSN 30.08.2012 PRINTER DIGITAL THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10029455	7	000	0.00	0.00	SHC2689P HSN 30.08.2012 TAXIMETER DIGITAL FL	0.00	0.00	0.00	0.00	0.00	0.00
10029455	8	000	1.56	0.00	SHC2689P HSN 30.08.2012 VEH REG FEE	140.00	138.44	1.56	140.00	0.00	0.00
			884.07	0.00		88,272.75	78,682.68	884.07	79,566.75	8,706.00	
COE Vehicle			543.24	0.00	Vehicle : Without T/M & COE	39,380.75	30,333.92	340.83	30,674.75	8,706.00	
			340.83	0.00	Vehicle : Without T/M, With COE	88,272.75	78,682.68	884.07	79,566.75	8,706.00	
			884.07	0.00	Taximeter	0.00	0.00	0.00	0.00	0.00	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2020 09:29
Date Of Accident	26/02/2020 21:10
Exact Location Of Accident	ALONG UPPER SERANGOON RD TOWARDS BENDEMEER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC2689P
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	LAM POH KHOON
NRIC No	SXXXX536E
Date Of Birth	17/11/1960
Occupation	OUTDOOR
Date Of Driving Pass	18/12/1981
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96830608
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	499B #02-224 TAMPINES AVENUE 9
Postcode	522499
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN9179P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	VEERIYAKETHAN MURUGAPANDI
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name

LAM POH KHOON

Approximate Age

60

Injuries Sustain

BACK

Injured person in which vehicle?

SHC2689P

Were seat belts worn?


YES

Was this injured conveyed to hospital by
ambulance?

NO

Address

Postcode



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement as per attached.

DECLARATION

We declare the foregoing particulars are true in every respect.

UNION TRANSPORTATION LTD
CO REG NO 199303621R

Policyholder's Signature
Date & Time:

Thorn

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Olivia Wendy

Olivia Wendy

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 27 FEB 2020


Declaration

Policyholder's Signature/Date & Time Driver's Signature/Date & Time

Driver's Signature(If driver is not the policyholder)/Date
& Time


Olivia Vreedy

Witnessed by Reporting
Centre Personnel





JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		
1. Date: <u>26/2/20</u> Time Received: <u>2153</u>	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : <u>Lam Poh Khoo</u> Contact No. : <u>96830608</u> Vehicle No. : <u>SHC2689P</u> Make / Model / Colour : Email :	5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>66P HABN6 GBECK AV</u>	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:		 # : Cracked X : Dented / : Scatched O : Missing <u>Shen</u> Signature of Customer
10. Odometer Reading : Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E		
Job Attended		
2. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input checked="" type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS Name of Driver : <u>H01</u> Vehicle No. : <u>Y473135</u> Time Dispatch : <u>2153</u> Time of Arrival : <u>2208</u> Time Completed : <u>2246</u>		

ash Invoice Details (if applicable)

3. Cash Invoice No. :

ustomer Acknowledgement

I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

26/2/20 Date 2153 Time Shen Signature of Customer

1. WORKSHOP

Name of Attending Staff/Guard Date & Time of Arrival Signature of Attending Staff/Guard

Date/Time: 27.02.2020 10:16

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3994844

JC NO.: 305384130

OMER

S

OMER NO.

ESS

(R)

(P)

OUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

(O)

REGN NO.:

SHC2689P

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MQDEL

SONATA

DATE/TIME IN

26.02.2020 21:10

YR OF MANU

30.08.2012

TARGET DATE

CHASSIS CODE

KMHET41VMCA828919


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 26.02.2020

NATURE: 3P 26.02.2020

S/NO	LABOR CODE	DESCRIPTION
000010	23-01	TOWING FEE
000020	L	LUMPSUM REPAIR



VED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

io.: SHC2689P JU TOKIO LKK

Vehicle No.: SHC2689P

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	26/02/2020
Vehicle Reg. No.:	SHC2689P	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 CRDI (A)	Vehicle Reg. Date:	30/08/2012
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4EAC159559	Chassis No:	KMHET41VMCA828919
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	5,425.02
Miscellaneous Items	11.00
Labour	2,300.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,736.02
+ GST 7.00% (S\$)	541.52
Nett Amount (S\$)	8,277.54

This claim is handled by: JUMANI BIN MASUDIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2020)

Parts: 143 HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHC2689P/27/02/2020 10:57

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOTLID COVER <i>Bc</i>	20.00	0.00	*1,349.50 FL ✓
2	1		*BOOTLID RUBBER <i>xnn</i>	20.00	0.00	*110.90 FL
3	1		*BOOTLID LOCK UPPER <i>xnn</i>	20.00	0.00	*132.10 FL
4	1		*BOOTLID LOCK LOWER <i>xnn</i>	20.00	0.00	*30.30 FL
5	1		*BOOTLID EMBLEM - SONATA <i>nec</i>	20.00	0.00	*43.60 FL ✓
6	1		*BOOTLID EMBLEM - HYUNDAI <i>nec</i>	20.00	0.00	*24.20 FL ✓
7	1		*BOOTLID EMBLEM - H <i>nec</i>	20.00	0.00	*26.10 FL ✓
8	1		*BOOTLID EMBLEM - CRDI <i>nec</i>	20.00	0.00	*22.70 FL ✓
9	1		*BOOTLID LAMP RH <i>scr</i>	20.00	0.00	*230.20 FL ✓
10	1		*TAILLAMP ASSY RH <i>scr</i>	20.00	0.00	*344.00 FL ✓
11	1		*REAR BUMPER ASSY <i>Bc</i>	20.00	0.00	*578.40 FL ✓
12	1		*REAR BUMPER REINFORCEMENT <i>DBT</i>	20.00	0.00	*483.30 FL ✓
13	10		*REAR BUMPER CLIPS <i>nec</i>	20.00	0.00	*22.00 FL ✓
14	1		*REAR BUMPER SPONGE <i>TSV</i>	20.00	0.00	*137.40 FL ✓
15	1		*REAR BUMPER UNDER COVER <i>xnn</i>	20.00	0.00	*185.80 FL ✓
16	1		*REAR BUMPER PROTECTOR RH <i>scr</i>	20.00	0.00	*38.00 FL ✓
17	1		*REAR PANEL <i>TXR</i>	20.00	0.00	*391.80 FL
18	1		*REAR PANEL GARNISH <i>TXnn</i>	20.00	0.00	*95.80 FL
19	1		*REAR FENDER RH <i>XR</i>	20.00	0.00	*1,935.90 FL
20	1		*REAR FENDER TRIM BOARD RH <i>xnn</i>	20.00	0.00	*180.90 FL
21	1		*REAR WINDSCREEN MOULDING <i>xnn</i>	20.00	0.00	*60.00 FL
22	1		*REAR WINDSCREEN SEALANT <i>xnn</i>	0.00	0.00	*46.00 F
23	1		*REAR BUMPER MAT <i>nec</i>	0.00	0.00	*50.00 F ✓
24	1		*REAR NUMBER PLATE <i>St</i>	0.00	0.00	*25.00 F ✓
25	1		*REVERSE SENSOR <i>xnn</i>	0.00	0.00	*135.70 F
26	1		*BOOTLID COMFORT LOGO & TEL.NO <i>nec</i>	0.00	0.00	*30.00 F ✓

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,709.60
- List Item Discount on L Items (\$\$)	1,284.58
Total Parts (\$\$)	5,425.02

ComfortDelGro Engineering Pte Ltd/SHC2689P/27/02/2020 10:57. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

\$2639.52

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

1574.68

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TOWING FEE	New	60.00
2	PANEL BEATING	New 480 1700	1,000.00
3	SPRAYPAINT	New 400	800.00
4	WIRING	New	50.00
5	TUFF KOTE	New	50.00
6	REMOVE/REFIX REAR UPHOLSTERY	New	120.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00
8	REMOVE/REFIX REVERSE SENSOR	New	100.00
Gross Labour Cost (\$\$)			2,300.00

ComfortDelGro Engineering Pte Ltd/SHC2689P/27/02/2020 10:57. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

28/2/2020
27/02/2020 1255
Ran CLK?
Paresum@erratoro
88622718 (45)
412pair kg S
att repair photo

L/S: \$3000/=
@under 1

Our Job Ref No 305384130
Date : 07/03/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : RAM
: SHC2689P

Fax :

DOA: 26.02.2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: TOKIO MARINE --- YN 9179P
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges ### _____
 - Total for Part-By-Part Repair Cost** ###
 - (c.) Lumpsum Repair (if applicable) N _____
 - Total for Lumpsum repair cost after Less: 20% **\$3,000.00**
 - Final Lumpsum Repair cost** _____

3. Estimated normal period for repairs: 4 working days

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature : 
Name : Ram
Date : 10/3/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

...CLAIM SUBFOLDER...(Pending for Survey Report)

































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Feb 2020 Sendback Est	27 Feb 2020 10:57 \$7,736.02	27 Feb 2020 14:43 Edit Adj Rpt	\$3,000.00 Edit Estimates	\$3,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	S.P.M FROZEN FOOD PTE. LTD., Co. Reg. No.: 200412500R								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHC2689P	Date of Loss:	26/02/2020 00:00 - :59 [89 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2001511	Policy/Cover Note No.:	MT107239 (Comprehensive) Coverage: 14/09/2019 - 13/09/2020						
Vehicle Reg. No. (Insured):	YN9179P	Policy No. (Claimant):							
		Excess:	\$0.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Fiona Gan Bee Song - 65926378]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 09/03/2020]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHC2689P (M2001511)
[YN9179P]
TP
COMFORT TRANSPORTATION PTE LTD
Feb 26 2020 12:00AM
[S.P.M FROZEN FOOD PTE. LTD.]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	27/02/20 10:57	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/02/20 10:14	Adjuster Immediate Advice	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
2	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
3	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	10/03/20 09:13	General View	1	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
33	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/03/20 09:13	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/03/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	10/03/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	10/03/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	10/03/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	10/03/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	10/03/20 09:15	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	10/03/20 09:15	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	10/03/20 09:15	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	10/03/20 09:15	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	27/02/20 10:58	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20003284/FVF3E2

Date: 17/03/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MT107239

Claimant Vehicle No : SHC2689P

Insured Vehicle No : YN9179P

Date of Loss: 26/02/2020

Nature of Claim: TP

Claim No: M2001511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC2689P

Make & Model: HYUNDAI SONATA, 2.0 CRDI (A)

Engine No: D4EAC159559

Reg. Date: 30/08/2012 (Man. Year: 2012)

Chassis No: KMHET41VMCA828919

Colour: Blue

Odometer: 494467 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,425.02	2,744.52	2,680.50	49.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,300.00	1,040.00	1,260.00	54.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,736.02	3,795.52	3,940.50	50.94
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	7,736.02	3,000.00	4,736.02	61.22
+ GST 7.00/7.00% (S\$)	541.52	210.00	331.52	61.22
Nett Amount (S\$)	8,277.54	3,210.00	5,067.54	61.22

INSPECTION

Date of Assignment:	27/02/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	27/02/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	

Adjuster: PARASURAM SHANMUGAM**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Mar 2020)
Parts:	143	HYUNDAI SONATA 2.0 CRDI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2689P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID COVER	Buckled	1,349.50 FL	-	*1,349.50 FL
2	1		*BOOTLID RUBBER	Not Necessary	110.90 FL	-	*- FL
3	1		*BOOTLID LOCK UPPER	Not Necessary	132.10 FL	-	*- FL
4	1		*BOOTLID LOCK LOWER	Not Necessary	30.30 FL	-	*- FL
5	1		*BOOTLID EMBLEM - SONATA	Necessary	43.60 FL	-	*43.60 FL
6	1		*BOOTLID EMBLEM - HYUNDAI	Necessary	24.20 FL	-	*24.20 FL
7	1		*BOOTLID EMBLEM - H	Necessary	26.10 FL	-	*26.10 FL
8	1		*BOOTLID EMBLEM - CRDI	Necessary	22.70 FL	-	*22.70 FL
9	1		*BOOTLID LAMP RH	Scratched	230.20 FL	-	*230.20 FL
10	1		*TAILLAMP ASSY RH	Cracked	344.00 FL	-	*344.00 FL
11	1		*REAR BUMPER ASSY	Buckled	578.40 FL	-	*578.40 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	483.30 FL	-	*483.30 FL
13	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
14	1		*REAR BUMPER SPONGE	Broken	137.40 FL	-	*137.40 FL
15	1		*REAR BUMPER UNDER COVER	Not Necessary	185.80 FL	-	*- FL
16	1		*REAR BUMPER PROTECTOR RH	Scratched	38.00 FL	-	*38.00 FL
17	1		*REAR PANEL	Repair	391.80 FL	-	*- FL
18	1		*REAR PANEL GARNISH	Not Necessary	95.80 FL	-	*- FL
19	1		*REAR FENDER RH	Repair	1,935.90 FL	-	*- FL
20	1		*REAR FENDER TRIM BOARD RH	Not Necessary	180.90 FL	-	*- FL
21	1		*REAR WINDSCREEN MOULDING	Not Necessary	60.00 FL	-	*- FL
22	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 F	-	*- F
23	1		*REAR BUMPER MAT	Necessary	50.00 F	-	*50.00 F
24	1		*REAR NUMBER PLATE	Bent	25.00 F	-	*25.00 F
25	1		*REVERSE SENSOR	Not Necessary	135.70 F	-	*- F
26	1		*BOOTLID COMFORT LOGO & TEL.NO	Necessary	30.00 F	-	*30.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,709.60	3,404.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,284.58	659.88
Total Parts (\$\$)	5,425.02	2,744.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	60.00	60.00
2	PANEL BEATING	New	1,000.00	480.00
3	SPRAYPAINT	New	800.00	400.00
4	WIRING	New	50.00	50.00
5	TUFF KOTE	New	50.00	50.00
6	REMOVE/REFIX REAR UPHOLSTERY	New	120.00	0.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
8	REMOVE/REFIX REVERSE SENSOR	New	100.00	0.00
Gross Labour Cost (S\$)			2,300.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >