



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

LONPAC INSURANCE BHD

Ref: CS3/LPC20001751/Usf3s2-1

300 BEACH ROAD

Date: 27-02-2020

#17-04/07 THE CONCOURSESINGAPORE 199555



Code: LPC2

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

<b>Insured Veh.</b>	S A Valet PL	<b>Veh. Inspected</b>	SLL 6465Y
<b>Policy No.</b>	Z/19/LL00/015920	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	19/20/20/LL00/003436	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG LI LI	<b>Assign Date</b>	27/02/2020

#### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA VEZEL (A)	<b>c.c</b>	1496
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	RU11207632	<b>Colour</b>	RED
<b>Odometer</b>	042019 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	215/60 R16	DUNLOP	6 mm
<b>L/H Front Tyre</b>	215/60 R16	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	215/60 R16	DUNLOP	6 mm
<b>L/H Rear Tyre</b>	215/60 R16	DUNLOP	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

<b>Accident Date</b>	15/01/2020	<b>Inspect Date / Time</b>	03/02/2020 ( 11:25 AM )
<b>Survey held at</b>	HUAT AUTOMOBILE - BLK 3007 UBI RD 1 #01-404		
<b>Repairer</b>	-		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**