

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF7673G
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 26/02/2020

TP Veh Reg No: SHC8482D

Estimate No: ES2090184/YISHUN

Date: 27 Feb 2020

Policy No: D19MTHCVE000387

Veh Reg No: GBF7673G

Make/Model: NISSAN NV200

Chassis No: VM20101784

Engine No: HR16078240D

Reg. Date: 27/02/2017

Estimate Repair Cost to Vehicle No :GBF7673G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Price				
1 FRONT BUMPER	655.20	1 PC	655.20	✓
2 FRONT BUMPER REINFORCEMENT	688.10	1 PC	688.10	✓
3 FRONT BUMPER RH SIDE RETAINER	29.60	1 PC	29.60	✓
4 FRONT BUMPER CLIPS	5.00	6 PCS	30.00	✓
5 RH HEADLAMP	444.50	1 PC	444.50	✓
6 HEADLAMP LOWER GARNISH COVER	368.50	1 PC	368.50	✓
7 FRONT GRILLE	356.10	1 PC	356.10	?
8 FRONT GRILLE CLIPS	5.00	4 PCS	20.00	?
			2,592.00	
		Less 10%	259.20	2,332.80
Labour				
9 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,TO KNOCK & REPAIR FRT RH FENDER,HEADLAMP PANEL & REALIGN THE SAME	600.00	1 LA	600.00	500
10 PUTTY & RESPRAY ON FRT RH FENDER,HEADLAMP LOWER GARNISH,GRILLE,FRT BUMPER,REINFORCEMENT	550.00	1 LA	550.00	500
			1,150.00	1,150.00
			Total	S\$ 3,482.80
			Add GST @ 7%	243.80
			Total Amount Payable	S\$ 3,726.60

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: