

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54578**
Date Estimated : **25/02/2020**
Prepared By : **Foong Shiuh Jye**

**- ESTIMATE REPAIR FOR -
HWANG HUNG CHOONG
7 SENGKANG EAST AVENUE
#07-23**

SINGAPORE 544741

**- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGE1226A	WBA5F32050FH81341	29/11/2019	320i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the front bumper including remove attachments to facilitate repair.	850.00		850.00
To respray front bumper.	934.00		934.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
Sundries.	40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	0.00
Total Labour & Parts :	1,974.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18