

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 30890

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0215/2020/NS
Date	:	27-Feb-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SKK 9057 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Chee Lucy
Address	:	43 Maryland Drive Singapore 227531
Telephone	:	(HP) +65 94759043
Type of Claim	:	Third Party Claims
Policy No.	:	5107043313-01
Vehicle No	:	SKZ 6225 L
Model Code	:	A4 Sedan 1.4 TFSI S
Model / Year	:	28/1/2016
Engine No	:	CVN 001544
Chassis No	:	WAUZZZF44GA012634
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	23-Feb-20
Place of Accident	:	On Dunearn Road Towards City

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKZ 6225 L

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$	1,050.00 500	
3	To respray rear bumper.	\$	900.00 550	
4	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,502.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKZ 6225 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER <i>rehd</i>	\$ 2,079.00	✓
2	REAR BUMPER FIXING PARTS <i>neu</i>	\$ 69.00	+
3	REAR BUMPER SECURING STRIP <i>neu</i>	\$ 210.00	+
4	REAR BUMPER SPOILER <i>rehd</i>	\$ 234.00	✓
5	REAR LIGHT REFLECTOR - LH REAR <i>neu</i>	\$ 39.00	+
6	REAR BUMPER CARRIER <i>neu</i>	\$ 845.00	+
7	REAR BUMPER SEAL <i>neu</i>	2 \$ 26.00	+
8	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 42.00	+
9	REAR PARKING AID SENSOR - INNER OUTER	2 TBC	+
10	REAR PARKING AID SEAL RING	4 \$ 14.00	+
11	SUNDRIES	\$ 200.00	?

TOTAL SPARE PARTS CHARGES

: \$ 3,758.00

TOTAL LABOUR CHARGES

: \$ 2,502.00

GRAND TOTAL

: \$ 6,260.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling*
Surveyed Date : *09/03/2010*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not Authorised, 03 Days.*

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant