

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 30974

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0217/2020/NS
Date : 28-Feb-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLP 9529 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ng Kok Siong
Address : Blk 310 Shunfu Road
#05-221
Telephone : (HP) +65 96798446
Type of Claim : Third Party Claims
Policy No. : 71663037 QMY
Vehicle No : **SJL 1424 Y**
Model Code : Q2 1.0 TFSI S TRONIC
Model / Year : 30/5/2017
Engine No : CHZ 117070
Chassis No : WAUZZZGAXHA022803
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Feb-20
Place of Accident : 7 Bedok South Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJL 1424 Y

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assv.	S/N \$ 360.00	/
2	To dismantle and renew front bumper and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,600.00	500
3	To respray front bumper.	\$ 1,200.00	550
4	To reapply paint coating(by owner)	\$ 250.00	X refer to LOD
5	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: \$ 3,602.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 1424 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>/ Re.</i>	\$ 1,763.00	1299.2
2	FRONT BUMPER FIXING PARTS X NN	\$ 326.00	X
3	FRONT BUMPER GRILLE - CENTRE <i>/ CPA.</i>	\$ 186.00	148.4
4	FRONT BUMPER AIR GUIDE GRILLE - RH <i>/ SOL.</i>	\$ 159.00	127.2
5	FRONT BUMPER END CAP - RH <i>/ ABC.</i>	\$ 32.00	25.44
6	FRONT BUMPER SPOILER <i>/ Re.</i>	\$ 282.00	225.2
7	FRONT BU MPER CLOSING ELEMENT <i>/ ORA.</i>	\$ 147.00	117.2
8	WHEEL SPOILER - RH X NN	\$ 32.00	X
9	FRONT BUMPER ADAPTER - RH X NN	\$ 40.00	X
10	RADIATOR GRILLE <i>/ Lost.</i>	\$ 1,328.00	1062.4
11	RADIATOR GRILLE STRIKER PLATE X NN	\$ 117.00	X
12	FRONT BUMPER CARRIER X NN	\$ 646.00	X
13	FRONT BUMPER FOAM FILLER PIECE X NN	\$ 73.00	X
14	FRONT BUMPER DISTANCE PIECE X NN	\$ 13.00	X
15	FRONT BUMPER COVER ☒ BR	\$ 95.00	75.36
16	FRONT BUMPER GUIDE SECTION - RH X NN	\$ 34.00	X
17	SIGNAL HORN - RH HIGH TONE X <i>/ SNN</i>	\$ 178.00	X
18	SPRING SHACKLE - RH LOW TONE X	\$ 30.00	X
19	HEADLIGHT MOUNTING X NN	\$ 112.00	X
20	LED HEADLIGHT - RH X NN	\$ 4,627.00	X
SUB TOTAL SPARE PARTS		: <u>\$ 10,220.00</u>	3080.4

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 1424 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	LIFT CYLINDER - RH X NN	\$ 134.00	X
22	RADIATOR AIR GUIDE - RH X NN	\$ 29.00	X
23	FRONT WHEEL COVER - LH / RH / <i>Ac</i> 2	\$ 606.00	484
24	CAUTION SIGN STICKER X NN	NEC \$ 13.00	X
25	AIRCON STICKER X NN	NEC \$ 7.00	X
26	FRONT NO PLATE / <i>Ac</i>	S/N \$ 40.00	✓
27	SUNDRIES ✓ NEC	\$ 300.00	31.76
TOTAL SPARE PARTS		: \$ 11,349.00	
TOTAL LABOUR CHARGES		: \$ 3,602.00	
GRAND TOTAL		: \$ 14,951.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

3 Days -

Guo Qiang - 8288 0282

03/3/2020

before paint photos.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant