

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0202/2020/RT
Date : 30-Jan-20

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle no : GBG 6104 J

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Hi Rasul,

4 days ok - 16/09/2020 Carrine

Attn: Motor Claims Dept

Tel: 6221 6111 - Fax: 6221 2101

Owner's Name : Mr. Tan Song Guan
Address : Blk 225 Pending Road
#09-173
Singapore 670225
Telephone : (HP)+65 96216078
Type of Claim : Third Party Claims
Policy No. : SD20V01461/VPE/R00
Vehicle No : **SFZ 2796 R**
Model Code : BMW 316I 1.6 AT D/AB 4DR ABS HID
Model / Year : Aug-14
Engine No : A009J734N13B16A
Chassis No : WBA3A16080NS37603
Mileage : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Feb-20
Place of Accident : Bangkit Rd Blk 257 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFZ 2796 R

S/N	Nature of Jobs		Estimated Charges	Surveyor's eaccomendations
1	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	280.00	\$ 280.00
2	To dismantle lhs rear door and lhs sill panel trim. To renew lhs rear door. Re-organise rear crash management components. Reinstall all parts removed.	\$	2,100.00	\$ 500.00
3	To respray lhs rear door, lhs front door, door handles and lhs sill panel trim.	\$	3,000.00	\$ 1,500.00
4	Supplementary	\$	680.00	\$ 680.00
5	To carry out diagnostic check.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,252.00	\$ 3,152.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFZ 2796 R

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/Nett	Remarks
1	REAR DOOR LH	1 \$ 2,125.00	\$ 2,125.00
2	REAR DOOR WIRING SET LH	1 \$ 275.00	
3	REAR DOOR INNER TRIM LH	1 \$ 3,000.00	
4	REAR DOOR STRIP OUTER LH	1 \$ 350.00	\$ 350.00
5	REAR DOOR OUTER SEAL LH	1 \$ 150.00	
6	SUPPLEMENTARY	\$ 375.00	\$ 375.00
TOTAL SPARE PARTS		: \$ 6,275.00	\$ 2,850.00
TOTAL LABOUR CHARGES		: \$ 5,572.00	\$ 3,152.00
GRAND TOTAL		: \$ 11,847.00	\$ 6,002.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

BL-24/08/20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

China Taiping Insurance (SG) Pte Ltd 105 Cecil Street #19-00 The Octagon Singapore 069534 Attn: Motor Claims Dept Tel: 6221 6111 - Fax: 6221 2101		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0202/2020/TF 25-Mar-20 Raymond Ting 1 of 1 SFZ 2796 R BMW 316I 1.6AT D/AB 4DR ABS HID
Quantity	Description	Unit Price	Amount
<u>PARTS</u>			
1	Rear door quarter glass LH (nec)	\$ 275.00	\$ 275.00
2	Glass sealant (nec) S/N	\$ 100.00	\$ 100.00
			\$ 375.00
<u>LABOUR</u>			
1	To remove and reinstall quarter glass LH S/N	\$ 280.00	\$ 280.00
2	To install quarter glass solar film S/N	\$ 400.00	\$ 400.00
			\$ 680.00
	TOTAL	\$ 1,055.00	\$ 1,055.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant