

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : **b1 54500**  
Date Estimated : **17/02/2020**  
Prepared By : **Shukhaizi Bin Misbah**

### - ESTIMATE REPAIR FOR -

**Ponnusamy Soosai**  
**28 Scott Road**  
**#17-01**  
**Singapore**  
**Singapore 228223**

### - ACCOUNT - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLZ5235C</b>	<b>WBAJB32090G460050</b>	<b>08/05/2018</b>	<b>540iA</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments including remove attachments to facilitate repair.	850.00		850.00
To respray front bumper and front right fender.	1,730.00		1,730.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
To replace right LED AHL headlight.	531.00		531.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH BUMPER GUIDE	16.95	1.00		16.95
RH FINISHER	76.25	1.00		76.25
FRT BUMPER PANEL PRIMED (M)	1,653.55	1.00		1,653.55
RH HEADLIGHT LED AHL HIGH (ICON LIG	4,879.55	1.00		4,879.55

### # SUPPLEMENTARY ITEMS

Total Labour :	3,341.00
Total Parts :	6,626.30
Total Labour & Parts :	9,967.30
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,967.30
GST @7%:	697.71
Grand Total :	10,665.01

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Supplementary

Estimate No. : **b1 54500**  
Date Estimated : **17/02/2020**  
Prepared By : **Shukhaizi Bin Misbah**

### - ESTIMATE REPAIR FOR -

**Ponnusamy Soosai**  
**28 Scott Road**  
**#17-01**  
**Singapore**  
**Singapore 228223**

### - ACCOUNT - 121

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLZ5235C</b>	<b>WBAJB32090G460050</b>	<b>08/05/2018</b>	<b>540iA</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# RH BUMPER GUIDE	BR /	16.95	1.00	16.95
-------------------	------	-------	------	-------

### # SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	16.95
Total Labour & Parts :	16.95