

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



*S & R 24-03-2020*

**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

27 FEB 2020

Estimate No. : **b1 54500**  
Date Estimated : **17/02/2020**  
Prepared By : **Shukhaizi Bin Misbah**

Page No. : **1 of 5**

**- ESTIMATE REPAIR FOR -**

**Ponnusamy Soosai**  
**28 Scott Road**  
**#17-01**  
**Singapore**  
**Singapore 228223**

**- ACCOUNT - 121**

**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLZ5235C	WBAJB32090G460050	08/05/2018	540iA	0

DESCRIPTION	VALUE
Replace front bumper including attachment, front right fender and deformation.	<i>850</i> 3,825.00
Painting front bumper and front right fender.	<i>1730</i> 1,923.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	<i>150</i> 177.00
To replace right headlight.	531.00
To carry out body cavity preservation. (Per panel).	118.00
sundries	<i>?</i> 150.00

Total Labour 1: **6,724.00**

DESCRIPTION	QTY	PRIC	VALUE
FRT RH SIDE PANEL ALUMINIUM <i>x R</i>	1	933.30	933.30
VERTICAL CONNECTION RH <i>?</i>	1	19.90	19.90
FRT BUMPER CARRIER <i>?</i>	1	726.70	726.70
FRT BUMPER BOTTOM CARRIER <i>?</i>	1	399.70	399.70
DAMPER KERB DESCENT <i>?</i>	1	5.45	5.45
FRT BUMPER TOP IMPACT ABSORBER (M) <i>?</i>	1	63.00	63.00
RH GRILLE AIR INLET OPEN <i>x</i>	1	83.15	83.15
RH FOG LAMP SUPPORT (M) <i>?</i>	1	65.00	65.00
RH FINISHER <i>cut</i>	1	76.25	76.25
FRT BUMPER BOTTOM IMPACT ABSORBER (M) <i>?</i>	1	63.00	63.00
FRT BUMPER PANEL PRIMED (M) <i>OR</i>	1	1,653.55	1,653.55
SET MOUNTING PDC/PMA SENSOR FRT <i>?</i>	1	69.35	69.35
TRIM GRILLE FRT (I CAM) <i>x</i>	1	29.20	29.20
COVERING CROSS MEMBER (ECE) <i>?</i>	1	33.65	33.65
RH HEADLIGHT LED AHL HIGH (ICON LIG) <i>OR</i>	1	4,879.55	4,879.55
RH FOG LIGHT LED <i>?</i>	1	471.40	471.40
ULTRASONIC SENSOR BLUESTONE WC2Y <i>?</i>	1	381.90	381.90
DECOUPLING RING PDC TORQUE CONVERTER <i>MC</i>	1	5.10	5.10

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : **b1 54500**  
Date Estimated : **17/02/2020**  
Prepared By : **Shukhaizi Bin Misbah**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLZ5235C</b>	<b>WBAJB32090G460050</b>	<b>08/05/2018</b>	<b>540iA</b>	<b>0</b>

Total Parts : **9,959.15**

*24/3/20, 10.45am*  
*Steve (LKK) with P/L*  
*4 days*  
*P/P*  
*By P/L SLJ*

**LKK Auto Consultants hence notify**  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	<b>6,724.00</b>
Parts	:	<b>9,959.15</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>1,167.82</b>
<b>Grand Total</b>	:	<b>17,850.97</b>

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\***

**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***