

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : GUO JINSHUN
BLK 268A PUNGGOL FIELD #08-133
SINGAPORE 821268

Claim No: MC1901076
No: MF1901001
Date: 09 Apr 2020
Policy No: GA405473
Veh Reg No: SJC5581Y
Make/Model: TOYOTA COROLLA
ALTIS 1.5
Chassis No: MR053REH604571756
TP Ins Co: CHINA

ATTN:

Your Ref No: SNM20D201009/
Claim Type: Third Party
Accident Date: 23/02/2020
TP Veh Reg No: SJB3729H

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJC5581Y

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 HEADLAMP RH / CRA	1 PC	1,014.10 /	
2 FRONT BUMPER / CR4	1 PC	576.40 /	
3 FRONT BUMPER SIDE RETAINER RH / MIS	1 PC	67.20 /	
4 FRONT BUMPER CLIPS / NEC	12 PC	46.68 30	
5 FRONT BUMPER GRILLE COVER RH / SCH	1 PC	133.87 /	
6 FRONT BUMPER SPONGE / CR4	1 PC	139.70 /	
7 FRONT FENDER RH / DD	1 PC	809.70 656	
8 FRONT FENDER COWLING RH / CR4	1 PC	175.22 /	
9 FRONT FENDER COWLING CLIPS / NEC	8 PC	25.68 /	
10 FRONT FENDER LOGO RH / NEC	1 PC	49.27 /	
11 WIPER WASHER TANK / CR4	1 PC	176.40 /	
		3,214.22 3,037.84	
	Less 25%	803.56	2,410.67
		-25%	2278.38
LABOUR			
12 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 /	
13 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, TO KNOCK & REPAIR FRONT FENDER LH, BONNET, FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	400.00 /	
14 TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	1 PC	400.00 /	
		840.00 /	840.00

P = 2,278.38
L = 840
3,118.38

P/P \$ 3,118.38
4 days

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : GUO JINSHUN
BLK 268A PUNGGOL FIELD #08-133

SINGAPORE 821268

ATTN:

Your Ref No: SNM20D201009/
Claim Type: Third Party
Accident Date: 23/02/2020
TP Veh Reg No: SJB3729H

Claim No: MC1901076
No: MF1901001
Date: 09 Apr 2020
Policy No: GA405473
Veh Reg No: SJC5581Y
Make/Model: TOYOTA COROLLA
ALTIS 1.5
Chassis No: MR053REH604571756
TP Ins Co: CHINA

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJC5581Y

Description	Quantity	List Price	Amount
		S\$	S\$
	Total		S\$ 3,250.67
	Add GST @ 7%		227.55
	Total Amount Payable		S\$ 3,478.22

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED SEVENTY EIGHT AND CENTS TWENTY TWO ONLY

The above vehicle was surveyed by SUN PIN - LKK on 05/03/2020

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

M/S : GUO JINSHUN
 BLK 268A PUNGGOL FIELD #08-133

SINGAPORE 821268

ATTN:

Your Ref No: SJC5581Y
 Claim Type: Third Party
 Accident Date: 23/02/2020
 TP Veh Reg No: SJB3729H

Estimate No: MC1901076
 Date: 26 Feb 2020
 Policy No: GA405473
 Veh Reg No: SJC5581Y
 Make/Model: TOYOTA COROLLA
 AXIO-1.5 ALTZS ECO
 AUTO

Estimate Repair Cost to Vehicle No :SJC5581Y

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 HEADLAMP RH / CRA	1 PC	1,014.10	
2 HEADLAMP SUPPORT PANEL RH X	1 PC	147.80	
3 HEADLAMP CHROME MOULDING RH X	1 PC	155.74	
4 FRONT BUMPER / CRU	1 PC	576.40	
5 FRONT BUMPER SIDE RETAINER RH / MY	1 PC	67.20	
6 FRONT BUMPER CLIPS / Net	12 PC	46.68	
7 FRONT BUMPER GRILLE CENTRE X	1 PC	158.64	
8 FRONT BUMPER GRILLE COVER RH X	1 PC	133.87 - Photo	
9 FRONT BUMPER UNDER COVER FRONT X	1 PC	179.70	
10 FRONT BUMPER UNDER COVER RH X	1 PC	150.40	
11 FRONT BUMPER SPONGE ? / CRU	1 PC	139.70	
12 FRONT BUMPER REINFORCEMENT RH ? X	1 PC	396.60	
13 FRONT FENDER RH X / CRU	1 PC	809.70	
14 FRONT FENDER COWLING RH / CRU	1 PC	175.22	
15 FRONT FENDER COWLING CLIPS / Net	8 PC	25.68	
16 FRONT FENDER LOGO RH / Net	1 PC	49.27	
17 RADIATOR SUPPORT PANEL X	1 PC	1,074.70	
		5,301.40	
	Less 25%	1,325.35	3,976.05
Special Nett			
18 SPORT RIM FRONT RH CHK PRICE	1 PC	0.0000 X	
19 TYRE FRONT RH CHK PRICE	1 PC	0.0000 X	
20 NUMBER PLATE	1 PC	35.00 X	
21 RADIATOR COOLANT	1 PC	30.00 X	
		65.00	65.00
LABOUR			
22 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00 /	
23 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	1 PC	100.00 X	
24 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00 X	
25 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL, TO KNOCK & REPAIR FRONT FENDER LH, BONNET, FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00 400	

05-03-2020

Siang.

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : GUO JINSHUN
BLK 268A PUNGGOL FIELD #08-133
SINGAPORE 821268

ATTN:

Your Ref No: SJC5581Y
Claim Type: Third Party
Accident Date: 23/02/2020
TP Veh Reg No: SJB3729H

Estimate No: MC1901076
Date: 26 Feb 2020
Policy No: GA405473
Veh Reg No: SJC5581Y
Make/Model: TOYOTA COROLLA
AXIO 1.5

Estimate Repair Cost to Vehicle No :SJC5581Y

Description	Quantity	List Price	Amount
26 TO SPRAY BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL	1 PC	800.00 1,620.00	400 1,620.00
Total			S\$ 5,661.05
Add GST @ 7%			396.27
Total Amount Payable			<u>S\$ 6,057.32</u>

TOTAL: SINGAPORE DOLLAR SIX THOUSAND FIFTY SEVEN AND CENTS THIRTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

Repair day - 4 days

P/P

before paint photo

Sen Pm CLK

05/03/2020

TP without prejudice

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
10 Ang Mo Kio Industrial Park 2A
AMK Autopoint Singapore 568047
TEL: 6483 1244 FAX: 6483 6170
AUTHORISED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC1901076
Date: 05 Mar 2020
Policy No: GA405473
Veh Reg No: SJC5581Y 2017
Make/Model: TOYOTA COROLLA
ALTIS 1.5

Your Ref No: SNM20D201009/
Claim Type: Third Party
Accident Date: 23/02/2020

Estimate Repair Cost to Vehicle No :SJC5581Y

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
SPARE PARTS			
1 WIPER WASHER TANK /CR4	1 PC	176.40 /	
		176.40	
	Less 25%	44.10	132.30
Total			S\$ 132.30
GST Amount			S\$ 9.26
Total Amount Payable			S\$ 141.56

For AH LIM MOTOR COMPANY

AH LIM MOTOR CO.
BLK 10, ANG MO KIO INDUSTRIAL PARK 2A
#01-09, AMK AUTOPPOINT
SINGAPORE 568047
AUTHORISED SIGNATURE