

ASS. REC. BY:

REF: CS/U0120063318/Kyfs

Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Josephine Wong of UOI Date/Time: 28.2.2020 11:06 a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 384B Insured: GP 2667x

at Workshop m/s Trans-196 Tel: 6287 6666

of NO 2 AMK ST 63

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 27.2.2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.2.2020 11:59 a.m Person Contacted: zhe wei Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 384B - CS31 ASM 13015192/KW9352 b.04-12/03/2018
	GP 2667x - x

ASS. REC. BY:

REF: 0021

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S140 384 B Yr Regn: 06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Renault Latitude c.c. 1995Colour: White A/C: Insured / Std / NI / NASp. Reading: 61 P. 439 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VFIAB215AUC 282674Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NIL / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Pailun

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 27/2/20D.O.I. 28/2/2020

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11 Pm @ 7150h (Recd \$24938-23, 77%)

RECEIVED 10 MAR 2020

Claim = M11D09742003  
No

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

18/3/20 TypistDays Of Repair: 7Resurvey No. of Trlp: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

22x25 = 550

250 + 550

60

20

880

Report Format:

Lump Sum / I.B.I. (\$

\$7150/-

TOTAL

18/3/20

## Nivitha (LKK Auto)

---

**From:** WONG JOSEPHINE <josephinewong@uoi.com.sg>  
**Sent:** Friday, 28 February 2020 11:06 AM  
**To:** 'assignments'; SUR  
**Cc:** zhewei.kek@transcab.com.sg; LEE KATIE  
**Subject:** FW: ARRANGE FOR SURVEY SHD384B

Without Prejudice

Dear LKK

Kindly assist to survey third party's vehicle .

Details of survey as email below. Thanks

Josephine Wong  
Executive  
Claims  
United Overseas Insurance Limited  
3 Anson Road, #28-01 Springleaf Tower, Singapore 079909 Main . (65) 6222 7733 | DID . (65) 6490 9329 | Fax . (65) 6327 3869 | Email . josephinewong@uoi.com.sg

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

### -----Original Message-----

**From:** Zhe Wei <zhewei.kek@transcab.com.sg>  
**Sent:** Friday, February 28, 2020 11:03 AM  
**To:** WONG JOSEPHINE <josephinewong@uoi.com.sg>  
**Cc:** candy.kong@transcab.com.sg; LEE KATIE <katielee@uoi.com.sg>  
**Subject:** RE: ARRANGE FOR SURVEY SHD384B

Dear Josephine,

Kindly arrange for LKK Auto Consultant to survey please.

Thank you.

Best Regards,  
Kek Zhewei  
Claims Officer

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

-----Original Message-----

From: Zhe Wei <zhewei.kek@transcab.com.sg>

Sent: Friday, February 28, 2020 10:09 AM

To: WONG JOSEPHINE <josephinewong@uoi.com.sg>

Cc: Candy Kong <candy.kong@transcab.com.sg> <candy.kong@transcab.com.sg>

Subject: RE: ARRANGE FOR SURVEY SHD384B

Hi Josephine

Please arrange for survey as below :

GP2667X - 27.02.2020 AT 0315Hrs - SHD384B

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Best Regards,  
Kek Zhewei  
Claims Officer

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

---

This email has been checked for viruses by AVG.  
<https://www.avg.com>

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD384B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Feb 2020
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002993
Chassis No.:	VF1ABL15AUC282677
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	10 Jun 2016
First Registration Date:	10 Jun 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jun 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$37,164.00
COE Rebate Amount:	\$19,909.00
<b>Total Rebate Amount:</b>	<b>\$34,907.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Feb 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/02/2020 08:55
Date Of Accident	27/02/2020 03:15
Exact Location Of Accident	BALESTIER ROAD TOWARDS MOULMEIN ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD384B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	2XXXXX878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

### Driver

Name of Driver	WONG FOOK WOH
NRIC No	SXXXX355C
Date Of Birth	04/04/1961
Occupation	OUTDOOR
Date Of Driving Pass	12/04/1994
Driving Experience	25 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96386926
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 675C YISHUN AVENUE 4 #04-802
Postcode	763675
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20200227/2017

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH TRAFFIC POLICE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GP2667X
Vehicle Make/Model/Colour	VAN
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name WONG FOOK WOH

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHD384B

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode



**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


Refer to Police Report T/20200227/12017.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20200227/2017

1 of 3

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

Report No. T/20200227/2017

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 27/02/2020 06:23	Vide Report No.: E/20200227/0047	Station Diary No.: 40
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: WONG FOOK WOH			Address: APT BLK 675C YISHUN AVENUE 4 #04-802 SINGAPORE 763675		
ID Type / ID No.: NRIC NO / S1474355C			Contact No.: Home/Office: Mobile: 96386926		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 58	Date of Birth: 04/04/1961	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Drink & Drive	Drink Drive: Yes	Date/Time of Accident: 27/02/2020 03:15	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 BALESTIER ROAD MOULMEIN ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GP2667X	Van	TOYOTA		Silver	Slightly Damaged	1
SHD384B	Car	RENAULT		Red	Totally Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20200227/2017

2 of 3

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

Report No. T/20200227/2017

**CONTINUATION OF REPORT**

Driver			
Name	WONG FOOK WOH	ID No.	S1474355C
Related Vehicle	SHD384B (Car)	Contact No.	96386926
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

**Brief Details.**

On the 27.02.2020 at about 0315hrs, I was travelling along the center lane out of the 3 lanes of Balestier Road and heading towards Moulmein Rd after picking up a Male Chinese passenger from Balestier point in my Taxi bearing registration number SHD384B, Red Transcab Taxi.

As I was driving on the said road, I noticed an accident ahead on the center lane. Hence, I made checks to ensure there were no oncoming vehicle on the 1st lane (Extreme right lane) before changing lane to the said right most lane. After I had successfully changed lane, I continued to drive straight and was approaching the junction of Balestier Road and Kim Keat Road when there was a sudden bump from the rear of my vehicle.

I then immediately stopped my vehicle and came down to make checks. I then saw that a Van had hit onto the rear of my vehicle. The said Van then drove forward and stopped in front of my Taxi, The driver of the Van then came down and informed me that he wished to settle the matter privately. My passenger had left shortly after as he was in a rush.

Shortly after this, Police arrived at the location and engaged both me and the Van driver. They conducted checks on the Van driver and later arrested him for drink driving and advised me to lodge a accident report. Traffic police had seized my in vehicle camera's memory card for investigations. I feel pain on the rear of my neck due to the accident and have yet to see a doctor.



**SINGAPORE  
POLICE FORCE**



T/20200227/2017

3 of 3

Report No. T/20200227/2017

Police Station Of Origin:  
Yishun North N.P.C  
31 Yishun Central SINGAPORE 768827  
Tel No: 1800-8529999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
L /  
Sgt 3 SARVANN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / DDGVT /  
Sr Staff Sgt YUS MASTARI I KHAZALI  
Contact No.: 65476214

SN 085

Authentication Stamp  
NP168



Signature:

Singapore Police Force

Signature Of Informant:

Date/Time:  
27/02/2020 06:23

Classification Of Case:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 384B**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

28 FEB 2020

**PART**

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BRACKET CTR REAR
- 1 BUMPER BRACKET SIDE RH REAR
- 1 BUMPER RETAINER RH REAR
- 1 BUMPER REFLECTOR RH
- 1 BUMPER BRACKET SIDE LH REAR
- 1 BUMPER RETAINER LH REAR
- 1 BUMPER REFLECTOR LH
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 OUTER PANEL REAR (End Panel)
- 1 OUTER PANEL REAR (End Panel) TRIM
- 1 TAILLAMP RH
- 1 TAILLAMP PANEL RH
- 1 TAILLAMP LH
- 1 TAILLAMP PANEL LH
- 1 BOOT REAR
- 1 BOOT FINISHER
- 1 BOOT WHEATERSTRIP
- 1 BOOT REFLECTOR LAMP LH
- 1 BOOT REFLECTOR LAMP RH
- 1 BOOT BADGE 'RENAULT'
- 1 BOOT BADGE
- 1 BOOT INNER TRIM BOARD

**AAD2002-184***Not Authored**1/10/2018 8 7150hr***SHD 384B**

VF1ABL15AUC282677

RENAULT

LATITUDE

27.2.2020

**UOI**

10/06/2016

**LIST**

\$	<i>Bul/ent</i>	561.70	✓
\$	<i>re</i>	411.90	✓
\$	<i>Sn</i>	98.10	X
\$	<i>Sn</i>	82.10	X
\$	<i>R</i>	59.80	X
\$	<i>cm</i>	16.60	✓
\$	<i>Sn</i>	80.80	X
\$	<i>Sn</i>	54.20	X
\$	<i>Sn</i>	16.60	X
\$	<i>R</i>	547.80	✓
\$	<i>R</i>	114.50	X
\$	<i>R</i>	100.90	X
\$	<i>R</i>	745.80	✓
\$	<i>re</i>	404.56	✓
\$	<i>my cm</i>	313.10	✓
\$	<i>R</i>	401.40	X
\$	<i>Sn</i>	401.40	X
\$	<i>R</i>	401.40	X
\$	<i>R</i>	1,677.20	✓
\$	<i>Sn</i>	344.70	X
\$	<i>Sn</i>	178.20	X
\$	<i>Sn</i>	277.70	X
\$	<i>Sn</i>	277.70	X
\$	<i>re</i>	82.40	✓
\$	<i>re</i>	95.80	✓
\$	<i>Sn</i>	611.00	X

**Trans-cab Auto Services Pte Ltd**

AAD2002-184

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 384B**

1 BOOT LOCK	\$	246.60	
1 BOOT HINGE LH	\$	254.20	
1 BOOT HINGE RH	\$	253.80	
1 BOOT STRUT LH	\$	145.10	
1 BOOT STRUT RH	\$	145.10	
2 BOOT RUBBER PLUG	\$	139.30	
1 BOOT LOCK LINKAGE HOLDER	\$	99.50	
1 SPARE WHEEL PANEL TRIM	\$	612.21	
1 SPARE TYRE BOARD	\$	680.90	
1 EXHAUST CAP REAR	\$	125.40	
1 FENDER PANEL INNER TRIM REAR RH	\$	671.45	
1 FENDER PANEL REAR RH	\$	1,933.20	
1 WHEELARCH REAR RH	\$	275.40	X
1 AIR VENT	\$	59.40	X
<b>TOTAL</b>	<b>\$</b>	<b>13,998.92</b>	
<b>10%</b>	<b>\$</b>	<b>1,399.89</b>	
	<b>\$</b>	<b>12,599.03</b>	

**Special Nett**

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	66.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	33.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR RIVET	\$	22.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 BOOT STICKER "Trans-cab"	\$	30.00	✓
1 BOOT STICKER "6555-3333"	\$	30.00	✓
1 BOOT INNER TRIM CLIP	\$	45.00	X
1SET BOOT FINISHER CLIP	\$	24.20	X
1 TAILLAMP CLIP LH	\$	5.00	X
1 TAILLAMP CLIP RH	\$	5.00	✓



**Trans-cab Auto Services Pte Ltd****AAD2002-184**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 384B**

1	Rear Bumper Protector	\$	nn	100.00	30sn
1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	100.00	40sn
1	WINDSCREEN MOULDING	\$	nn	150.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
<b>TOTAL</b>		<b>\$</b>		<b>1,599.20</b>	

**TOTAL PARTS \$ 14,198.23****LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 601

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 601

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ 380.00 X

To transfer of rear bumper fittings, attachment and perform water seepage test.

\$ 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 7,500.00 601 12001

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00 X

To transfer of Rear fender fittings, attachment and perform water seepage test.

\$ 380.00 X



**Trans-cab Auto Services Pte Ltd****AAD2002-184**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 384B**

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To Rust-Proofing Of The Affected Areas.	\$	170.00	901
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	7,500.00	889
To Check Electrical Lighting Concerned.	\$	170.00	201
To repair rear exhaust cap and realign rear exhaust pipe.	\$	nn 170.00	X
<b>TOTAL</b>	<b>\$</b>	<b>17,890.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>32,088.23</b>	

**LUMP SUM ( REPAIR DAY)****25 DAYS****7 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI20003318/Kyf3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 20-03-2020	
			Code : UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GP 2667X	Veh. Inspected	SHD 384B	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D09742003	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	28/02/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282677	Colour	WHITE	
Odometer	619439	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	8 mm	
L/H Front Tyre	215/60 R16	SAILUN	8 mm	
R/H Rear Tyre	215/60 R16	SAILUN	8 mm	
L/H Rear Tyre	215/60 R16	SAILUN	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/02/2020	Inspection Date	28/02/2020	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 384B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BUMPER COVER REAR	BUCKLED / CRACKED	561.70	561.70
1	BUMPER LOWER REAR	DENTED	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	CRACKED	16.60	16.60
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	SERVICEABLE	16.60	-
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	BENT	745.80	745.80
1	OUTER PANEL REAR (END PANEL) TRIM	DENTED	404.56	404.56
1	TAILLAMP RH	MTG CRACKED	313.10	313.10
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	BENT	1,677.20	1,677.20
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE "RENAULT"	NECESSARY	82.40	82.40
1	BOOT BADGE	NECESSARY	95.80	95.80
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-

Report Ref No. CS/UOI20003318/Kyf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT LH	SERVICEABLE	145.10	-
1	BOOT STRUT RH	SERVICEABLE	145.10	-
2	BOOT RUBBER PLUG	SERVICEABLE	139.30	-
1	BOOT LOCK LINKAGE HOLDER	SERVICEABLE	99.50	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	SPARE TYRE BOARD	SERVICEABLE	680.90	-
1	EXHAUST CAP REAR	SERVICEABLE	125.40	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	BUCKLED	1,933.20	1,933.20
1	WHEELARCH REAR RH	SERVICEABLE	275.40	-
1	AIR VENT	SERVICEABLE	59.40	-
	LESS 10% DISCOUNT		-1,399.89	-679.01
			12,599.03	6,111.05
	<b>SPECIAL NETT ITEMS</b>			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	100.00	30.00
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	40.00
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	150.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
			1,599.20	330.00
	<b>LABOUR</b>			
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT LOCK, BOOT HINGE LH AND BOOT HINGE RH.		7,500.00	1,200.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		7,500.00	880.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO REPAIR REAR EXHAUST CAP AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
			17,890.00	2,490.00
<b>GRAND TOTAL</b>			<b>32,088.23</b>	<b>8,931.05</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,150.00
---	--	--	----------

Report Ref No. CS/UOI20003318/Kyf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.