

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003325/KGS3Q2

Date: 29/09/2020

REFERENCE

| | | |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No: | MCOM0015 |
| Claimant | | |
| Vehicle No : SKK3149Y | Insured Vehicle No : | SHA7022R |
| Date of Loss: 23/02/2020 | Nature of Claim: TP | Claim No: MCT20020486 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SKK3149Y | | |
| Make & Model: | NISSAN SYLPHY, 1.5 4AT ABS D/AB 2WD 4DR (A) | Engine No: | HR15334380 |
| Reg. Date: | 01/06/2006 (Man. Year: 2006) | Chassis No: | JN1BAAG11Z0100267 |
| Colour: | Metallic Pearl White | Odometer: | 202771 km |
| Engine Capacity: | 1498 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | Dunlop 8 mm | Rear Left Side: | Dunlop 8 mm |
| Front Right Side: | Dunlop 8 mm | Rear Right Side: | Dunlop 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 4,302.10 | 2,640.01 | 1,662.09 | 38.63 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,300.00 | 880.00 | 420.00 | 32.31 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,602.10 | 3,520.01 | 2,082.09 | 37.17 |
| Approved Total (Overridden) (S\$) | | 2,500.00 | | |
| (S\$) | 5,602.10 | 2,500.00 | 3,102.10 | 55.37 |
| + GST 7.00/7.00% (S\$) | 392.15 | 175.00 | 217.15 | 55.37 |
| Nett Amount (S\$) | 5,994.25 | 2,675.00 | 3,319.25 | 55.37 |
| + Car Rental (4.0 x S\$100.00/day) (S\$) | | 400.00 | | |
| + Doc/Search Fee (S\$) | | 7.45 | | |
| + Other Costs (S\$) | | 45.00 | | |
| Nett Liability (S\$) | | 3,127.45 | | |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 27/02/2020 | |
| Date Inspected: | 27/02/2020 | Inspected At: Allswell Motor Traders (HQ) 25 Defu Lane 9 Singapore 539266 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 01 Sep 2020) |
| Parts: | 143 | NISSAN SYLPHY 1.5 4AT ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKK3149Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------|-------------|--|-----------------|
| 1 | 1 | | *FRONT BUMPER | Bent | 1,510.00 F | *636.20 FL |
| 2 | 1 | | *LH HEADLAMP | Mtg Cracked | 910.00 F | *638.00 FL |
| 3 | 2 | | *LH RETAINER /RH RETAINER | Cracked | 102.00 F | *102.00 FL |
| 4 | 1 | | *FRT FENDER | Bent | 720.10 F | *672.70 FL |
| 5 | 1 | | *LOWER ARM | Distorted | 400.00 F | *400.00 FL |
| 6 | 1 | | *LINKAGE | Serviceable | 180.00 F | *- FL |
| 7 | 1 | | *LH WHEEL KNUCKLE | Bent | 395.00 F | *395.00 FL |
| 8 | 1 | | *LH HEADLAMP LOWER BKT | Distorted | 45.00 F | *45.00 FL |
| 9 | 1 | | *CLIPS /RETAINER STUDS | Necessary | 40.00 FS | *40.00 FS |
| | | | | | Sub Total (S\$) | 4,302.10 |
| | | | | | - List Item Discount on L Items 0.00/10.00% (S\$) | 0.00 |
| | | | | | Total Parts (S\$) | 4,302.10 |
| | | | | | | 2,928.90 |
| | | | | | | 288.89 |
| | | | | | | 2,640.01 |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|---------------|
| <u>Labour Items</u> | | | | |
| 1 | DISMANTLE /ASSEMBLY OF ALL AFFECTED PARTS | New | 600.00 | 480.00 |
| 2 | PANEL KNOCKING OF SUPPORT PANEL | New | 300.00 | 0.00 |
| 3 | SPRAY PAINTING OF ALL AFFECTED PARTS | New | 400.00 | 400.00 |
| Gross Labour Cost (S\$) | | | 1,300.00 | 880.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >