

Date: 29.01.2020
 Vehicle No: SLP2681U
 Model: TOYOTA AQUA
 Chassis: NHP106595204-2017
 Reg.Year: 2017

Third Party Insurer: NTUC
 Third Party Veh No: SFE8991P
 Date of Accident: 25.01.2020

*Not Notified
 11pm @ 1200h
 Running After Rain*

2 days

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	<i>Bul/dri</i>	\$1,136.70
2	FRONT BUMPER CLIPS	10	\$5.80	<i>An</i> \$58.00
3	FRONT BUMPER SIDE BRACKET	1		<i>In</i> \$78.30
4	FRONT BUMPER FOG LAMP COVER RH	1	<i>nd/ly</i>	\$60.90
5	FRONT BUMPER LAMP RH	1		<i>cm</i> \$245.10
SUB TOTAL				\$1,579.00
LESS 25%				-\$394.75
PARTS TOTAL				\$1,184.25

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR & READJUST FRONT BUMPER & ETC. \$350.00 *200h*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER & ETC. \$220.00 *200h*

LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM. \$50.00 *20h*

LABOUR TOTAL \$620.00

ONG TOTAL \$1,804.25

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

