

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 30678

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0206/2020/NS
Date : 26-Feb-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Michelle Saw Mei Sian
Address : 35 Jalan Bangsawan
Singapore 457812
Telephone : (HP) 90906668
Type of Claim : Own Damage Claims
Policy No. : 1900130787
Vehicle No : **SMN 2956 B**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 31/7/2019
Engine No : CVK 085761
Chassis No : WAUZZZF5XKA065436
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 25-Feb-20
Place of Accident : Siglap Road Turning Into Burnfoot Terrace

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 2956 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00 ✓	
2	To renew 1/4 glass to facilitate fender renewal.	S/N	\$ 300.00 ✓	
3	To install 1/4 glass solar film.	S/N	\$ 200.00 ✓	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00 ✓	
5	To remove and reinstall rear seat, back rest, hat tray abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag.	S/N	\$ 1,400.00 ✓	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 3,660.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMN 2956 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dismantle rear bumper, rear lid, and rhs sill panel trim. cut out and weld rhs rear fender and rhs wheel outer wheel housing. To renew rear bumper and rhs sill panel trim. Re-organise crash management components. Reinstall all parts removed	\$ 8,800.00	3000
7	to respray rear bumper, rhs rear fender, rhs outer wheel housing, rhs sill panel trim, rhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 7,100.00	550 x 6 = 3300
8	To renew rhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
9	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 20,032.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 2956 B

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER <i>Repair</i>	\$	2,385.00	+
2	REAR BUMPER FIXING PARTS	\$	156.00	+
3	REAR BUMPER SECURING STRIP	\$	210.00	+
4	TRIM MOLDING	\$	958.00	+
5	REAR LIGHT REFLECTOR - RH	\$	39.00	+
6	LED TAIL LIGHT - RH <i>lit</i>	\$	1,076.00	✓
7	TAIL LIGHT TRIM - RH <i>new</i>	\$	28.00	+
8	REAR PARKING AID SEAL RING <i>new</i>	4 \$	14.00	+
9	SIDE PANEL - RH <i>Distorted</i>	\$	2,354.00	✓
10	SIDE WINDOW - RH <i>new</i>	\$	676.00	✓
11	OUTER WHEEL HOUSING - RH <i>Repair</i>	\$	595.00	+
12	WHEEL HOUSING LINER - RH <i>Completed</i>	\$	259.00	✓
13	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$	86.00	?
14	SIDE MEMBER TRIM - RH <i>delid</i>	\$	778.00	✓
15	ATTACHMENT PARTS ?	\$	123.00	?
16	ADHESIVE TAPES SET <i>new</i>	\$	200.00	✓
17	REAR ALUMINIUM RIM - RH <i>cut</i>	\$	964.00	✓
18	ALUMINIUM RIM RUBBER VALVE <i>new</i>	4 \$	13.00	+
19	ACRYLIC SEALANT	S/N \$	180.00	✓
20	CAVITY WAX	S/N \$	140.00	✓
21	STONE CHIP	\$	180.00	✓
22	METAL FILLER POWDER	\$	280.00	✓
23	1/4 GLASS SEALANT	S/N \$	100.00	✓
24	SUNDRIES ?	\$	300.00	?
TOTAL SPARE PARTS CHARGES		\$	12,094.00	
TOTAL LABOUR CHARGES		\$	20,032.00	
GRAND TOTAL		\$	32,126.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 28/02/20.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant