

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 56Z**AAD2002-182***Not Authised
C/Snp @ 4300/-*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

27 FEB 2020

SHD 56Z

VF1ABL15AUC281583

RENAULT

LATITUDE

26.2.2020

AIG

23/03/2015

PART

- 1 BUMPER COVER FRT
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER RETAINER FRT RH
- 1 BUMPER SUPPORT FRT
- 1 BUMPER UNDERTRAY FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 BUMPER BEAM FRT
- 1 TOW COVER FRT
- 1 FRONT BRACE PANEL
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE BADGE 'RENAULT'
- 1 RADIATOR GRILLE FRAME
- 1 FRAME FULL SUPPORT PANEL
- 1 FRAME FULL SUPPORT BRACKET
- 1 HEADLAMP LH
- 1 HEADLAMP RH
- 1 HEADLAMP PANEL FRT LH
- 1 HEADLAMP PANEL FRT RH
- 1 BONNET
- 1 BONNET INSULATOR
- 1 BONNET STRUT LH

LIST

\$	<i>Re</i>	747.20	—
\$	<i>Re</i>	344.70	} X
\$	<i>Re</i>	394.68	
\$	<i>Re</i>	101.40	
\$	<i>Re</i>	101.40	
\$	<i>Re</i>	10.70	
\$	<i>Re</i>	292.50	
\$	<i>Re</i>	147.00	
\$	<i>Re</i>	207.21	
\$	<i>Re</i>	207.21	
\$	<i>R</i>	663.70	
\$	<i>Re</i>	60.90	} X
\$	<i>R</i>	177.22	
\$	<i>CM</i>	969.90	—
\$	<i>re</i>	225.36	—
\$	<i>CM</i>	686.00	—
\$	<i>Re</i>	592.70	X
\$	<i>R</i>	41.60	X
\$	<i>re</i>	743.60	—
\$	<i>Re</i>	743.60	X
\$	<i>R</i>	127.70	X
\$	<i>R</i>	128.30	X
\$	<i>Re</i>	1,312.70	—
\$	<i>Re</i>	294.30	X
\$	<i>Re</i>	53.30	X

Trans-cab Auto Services Pte Ltd**AAD2002-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 56Z

1 BONNET STRUT RH	\$	53.30	}	X
1 BONNET HINGE LH	\$	236.50		
1 BONNET HINGE RH	\$	237.40		
1 BONNET LOCK	\$	152.80		
1 BONNET CABLE	\$	55.20		
1 FENDER PANEL FRT LH	\$	414.40		
1 WHEELARCH FRT LH	\$	112.30		
1 FENDER BRACKET LOWER LH	\$	11.80		
1 FENDER INSULATOR LH	\$	65.50		
1 FENDER PANEL FRT RH	\$	437.10		
1 WHEELARCH FRT RH	\$	191.40		
1 FENDER BRACKET LOWER RH	\$	11.80		
1 FENDER INSULATOR RH	\$	66.30		
1 WIPER RESERVOIR	\$	179.60		
1 WIPER RESERVOIR NECK	\$	29.30		
1 WIPER RESERVOIR MOTOR	\$	82.60		
1 AIR CLEANER BOX	\$	464.20		
1 AIR CLEANER HOSE	\$	175.85		
1 AIR CLEANER LOWER	\$	271.26		
TOTAL	\$	12,623.49		
10%	\$	1,262.35		
	\$	11,361.14		

Special Nett

Special Net			
1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00 ✓
1SET BUMPER CLIP FRT	\$	na	66.00 ✓
1SET BUMPER BRACKET CLIP FRT LH	\$	na	12.00
1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50
1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00
1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50
1 RADIATOR GRILLE SCREW	\$	na	16.00
1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00
1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00

Trans-cab Auto Services Pte Ltd**AAD2002-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 56Z

1SET FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	X
2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	X
1 FRONT RENAULT TYRE 215/60/16	\$	Sn	300.00	X
1 FRONT RENAULT TYRE RIM	\$	Sn	380.00	X
1 Front licence plate with holder	\$	nd	80.00	45Sn
1SET WHEELARCH CLIP FRT LH	\$	na	30.50	X
1SET WHEELARCH CLIP FRT RH	\$	na	30.50	X

TOTAL	\$	1,189.00
--------------	-----------	-----------------

TOTAL PARTS	\$	12,550.14
--------------------	-----------	------------------

Labour

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To check steering geometry and computer wheel alignment	\$	Sn	220.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		6,000.00	5000
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	Sn	380.00	X
To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	Sn	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	Sn	170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	Sn	170.00	X

Trans-cab Auto Services Pte Ltd**AAD2002-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 56Z

To rust-proofing of the affected areas.	\$	170.00	30%
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20%
Putty and spray painting of the affected portion.	\$	6,000.00	440%
TOTAL	\$	14,000.00	
Over All Total	\$	26,550.14	

(LUMP SUM) Repair Days~~20 DAYS~~

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: