

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SME9660E

Type of Claim : TPVehicle No. : SME9660EMake & Model : BLUECARYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003363CHINA TAIPING
INSURANCE (SINGAPORE)Ins Company : PTE LTDEngine No. : -922403A18W132417107Excess : \$0.00Policy No. : 0Date of Accident : 30/1/2020Time of Accident : 09:40:00Suggested Days of Repair : 14Case Owner : BLUECAR EAST ASIA PTE LTD**Repair Estimates**Parts (a) Cost Price Items \$ 2,873.00Plus/Less 20.0% \$ 574.60Total of Cost / List \$ 3,447.60(b) Nett Price Items \$ -Less 0% \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 185.00**Total Parts Cost (Appendix A)** \$ 3,632.60**Labour (Appendix B)** \$ 2,400.00**Total Repair Cost** \$ 6,032.60*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

ESTIMATED REPAIR COST DETAILS

1

Vehicle No	: SME9660E	Case Owner	: <u>BLUECAR EAST ASIA PTE LTD</u>
Make & Model	: <u>BLUECAR</u>	Year Manufacture	: <u>2018</u>
Chassis No	: <u>VL4BCEB4RJT003363</u>	Engine No	: <u>-922403A18W132417107</u>
Date & Time	: _____ -	Supplier	: <u>0</u>
Order By	: <u>0</u>	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY	Unit Price	Cost Price	Nett Price	S/N
1	BOOT LID GLASS	1	\$ 938.00	\$ 938.00	\$ -	\$ -
2	HATCH PININFARINA LOGO	1	\$ 30.00	\$ 30.00	\$ -	\$ -
3	HATCH PININFARINA EMBLEM	1	\$ 59.00	\$ 59.00	\$ -	\$ -
4	BOOT LID GLASS SCREW COVER	4	\$ 5.00	\$ 20.00	\$ -	\$ -
5	BOOT LID GLASS SCREW	4	\$ 2.00	\$ 8.00	\$ -	\$ -
6	BOOT LID GLASS HINGE ASSY	1	\$ 150.00	\$ 150.00	\$ -	\$ -
7	BOOT LID GLASS DAMPER RH	1	\$ 35.00	\$ 35.00	\$ -	\$ -
8	BOOT LID GLASS DAMPER LH	1	\$ 35.00	\$ 35.00	\$ -	\$ -
9	BOOT LID GLASS LOCK	1	\$ 132.00	\$ 132.00	\$ -	\$ -
10	BOOT LID GLASS LOCK CATCH	1	\$ 55.00	\$ 55.00	\$ -	\$ -
11	BOOT LID GLASS CATCH COVER	1	\$ 35.00	\$ 35.00	\$ -	\$ -
12	STICKER (BLUESG)	1	\$ -	\$ -	\$ -	\$ 50.00
13	ROOF PANEL (EXTERIOR)	1	\$ 541.00	\$ 541.00	\$ -	\$ -
14	ROOF PANEL GARNISH	1	\$ 103.00	\$ 103.00	\$ -	\$ -
15	ROOF PANEL GARNISH SCREW	10	\$ 2.00	\$ 20.00	\$ -	\$ -
16	ROOF LINING (INTERIOR)	1	\$ 120.00	\$ 120.00	\$ -	\$ -
17	THIRD BRAKE LAMP	1	\$ 124.00	\$ 124.00	\$ -	\$ -
18	REAR WEATHER STRIP	1	\$ 32.00	\$ 32.00	\$ -	\$ -
19	REAR BODY FRAME (INNER & OUTER)	1	\$ -	\$ -	\$ -	\$ -
20	REAR BODY FRAME GARNISH	1	\$ -	\$ -	\$ -	\$ -
21	ROOF PANEL & REAR BODY FRAME RIVET (SMALL)	120	\$ 1.00	\$ 120.00	\$ -	\$ -
22	ROOF PANEL & REAR BODY FRAME RIVET (BIG)	70	\$ 1.00	\$ 70.00	\$ -	\$ -
23	FRONT WINDSCREEN GLASS SEALANT (BLACK)	2	\$ -	\$ -	\$ -	\$ 40.00
24	ROOF MOULDING SEALANT (BLACK)	2	\$ -	\$ -	\$ -	\$ 40.00
25	REAR BODY FRAME SEALANT (WHITE)	2	\$ -	\$ -	\$ -	\$ 40.00
26	FRONT WINDSCREEN MOULDING	1	\$ 84.00	\$ 84.00	\$ -	\$ -
27	IU BRACKET	1	\$ -	\$ -	\$ -	\$ 15.00
28	SEAL MOULDING HARD TOP CENT RIGHT ✓ DE	1	\$ 81.00	\$ 81.00	\$ ✓ -	\$ -
29	SEAL MOULDING HARD TOP CENT LEFT ✓ DE	1	\$ 81.00	\$ 81.00	\$ ✓ -	\$ -
30	0	0	\$ -	\$ -	\$ -	\$ -

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$2,646.00 \$ 2,873.00 \$ - \$ 185.00



No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Labour

**BLUECAR
EAST ASIA PTE
LTD**
2018

Vehicle No. : **SME9660E**
Make & Model : **BLUECAR**

Case Owner : LTD
Year of Manufacture : 2018

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quoted accordingly as a supplementary.