

**ACCIDENT REPAIR ESTIMATES**

Our Ref: TP / SME9660E

Type of Claim : TPVehicle No. : SME9660EMake & Model : BLUECARYear of Manufacture : 2018Chassis No. : VL4BCEB4RJT003363**CHINA TAIPING  
INSURANCE (SINGAPORE)**Ins Company : PTE LTDExcess : 0Date of Accident : 30/01/2020Engine No. : -922403A18W132417107Policy No. : Time of Accident : 09:40:00Suggested Days of Repair : 14Case Owner : BLUECAR EAST ASIA PTE**Repair Estimates**TP Vehicle No. : YK8519PParts (a) Cost / List Price Items \$ 1,757.00 (prices for parts with \* not included yet)Plus/Less ~~20.0%~~ 15% \$ 351.40Total of Cost / List \$ 2,108.40 (prices for parts with \* not included yet)(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 185.00Total Parts Cost (Appendix A) \$ 2,293.40 (prices for parts with \* not included yet)Labour (Appendix B) \$ 2,400.00Total Repair Cost \$ 4,693.40 (prices for parts with \* not included yet)

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qian - 8288 0282Company : LKKSurvey conducted on : 28/2/2020 at Remarks By Surveyor : after repair photos.

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 10 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ 

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

## ESTIMATED REPAIR COST DETAILS

BLUECAR EAST ASIA PTE

Vehicle No : SME9660E Case Owner : LTD

Make & Model : BLUECAR Year Manufacture : 2018

Chassis No : VL4BCEB4RJT003363 Engine No : -922403A18W132417107

Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	BOOT LID GLASS / <i>SM</i>	1	\$ 938.00	\$ 938.00	✓		
2	HATCH PINAINFARINA LOGO / <i>SM</i>	1	\$ 30.00	\$ 30.00	✓		
3	HATCH PINAINFARINA EMBLEM / <i>SM</i>	1	\$ 59.00	\$ 59.00	✓		
4	BOOT LID GLASS SCREW COVER / <i>SM</i>	4	\$ 5.00	\$ 20.00	✓		
5	BOOT LID GLASS SCREW / <i>SM</i>	4	\$ 2.00	\$ 8.00	✓		
6	BOOT LID GLASS HINGE ASSY / <i>BT</i>	1	\$ 150.00	\$ 150.00	✓		
7	BOOT LID GLASS DAMPER RH <i>X NN</i>	1	\$ 35.00	\$ 35.00	X		
8	BOOT LID GLASS DAMPER LH <i>X NN</i>	1	\$ 35.00	\$ 35.00	X		
9	BOOT LID GLASS LOCK <i>X NN</i>	1	\$ 132.00	\$ 132.00	X		
10	BOOT LID GLASS LOCK CATCH <i>X NN</i>	1	\$ 55.00	\$ 55.00	X		
11	BOOT LID GLASS CATCH COVER <i>X NN</i>	1	\$ 35.00	\$ 35.00	X		
12	STICKER (BLUESG) / <i>MC</i>	1	\$ -	\$ -			\$ 50.00 ✓
13	ROOF PANEL (EXTERIOR)* / <i>DIS</i>	1	\$ -	\$ 541 -	✓	waiting for overseas part price	
14	ROOF PANEL GARNISH* / <i>DIS</i>	1	\$ -	\$ 103 -	✓	waiting for overseas part price	
15	ROOF PANEL GARNISH SCREW / <i>MC</i>	10	\$ 2.00	\$ 20.00	✓		
16	ROOF LINING (INTERIOR)* / <i>DIS</i>	1	\$ -	\$ 120 -	✓	waiting for overseas part price	
17	THIRD BRAKE LAMP / <i>CRA</i>	1	\$ 124.00	\$ 124.00	✓		
18	REAR WEATHER STRIP / <i>TIV</i>	1	\$ 32.00	\$ 32.00	✓		
19	REAR BODY FRAME (INNER & OUTER)* <i>X NN</i>	1	\$ Repair	\$ -		waiting for overseas part price	
20	REAR BODY FRAME GARNISH* <i>X NN</i>	1	\$ -	\$ -		waiting for overseas part price	
21	ROOF PANEL & REAR BODY FRAME RIVET (SMALL)* / <i>MC</i>	120	\$ -	\$ 120 -	✓	waiting for overseas part price	
22	ROOF PANEL & REAR BODY FRAME RIVET (BIG)* / <i>MC</i>	70	\$ -	\$ 70 -	✓	waiting for overseas part price	
23	FRONT WINDSCREEN SEALANT (BLACK) / <i>MC</i>	2	\$ -	\$ -			\$ 40.00 ✓
24	ROOF MOULDING SEALANT (BLACK) / <i>MC</i>	2	\$ -	\$ -			\$ 40.00 ✓
25	REAR BODY FRAME SEALANT (WHITE) / <i>MC</i>	2	\$ -	\$ -			\$ 40.00 ✓
26	FRONT WINDSCREEN MOULDING / <i>MC</i>	1	\$ 84.00	\$ 84.00	✓		
27	IU BRACKET / <i>MC</i>	1	\$ -				\$ 15.00 ✓
28	0	0					
29	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL** \$ 1,718.00 \$ 1,757.00 \$ - \$ - \$ 185.00 ✓



1

**VEHICLES & EQUIPMENT DIVISION**

Tel: (65) 382 2736 FAX: (65) 6382 2817

15

BLUECAR  
EAST ASIA  
: PTE LTD  
2018

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*