



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA20003345/Gyd3e2

(SINGAPORE BRANCH)  
60 ANSON ROAD #08-01 (8th FLOOR)  
MAPLETREE ANSON  
SINGAPORE 079914

Date : 14-07-2020



Code : AWA

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	PUBLIC LIABILITY	<b>Veh. Inspected</b>	SLV 3168Y
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C038951/003-010	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZEL CHUA	<b>Assign Date</b>	28/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 6	<b>c.c</b>	2488
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	JM6GL103100131782	<b>Colour</b>	RED
<b>Odometer</b>	53756	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/45 R19	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	225/45 R19	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	225/45 R19	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	225/45 R19	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	03/02/2020	<b>Inspection Date</b>	01/04/2020
<b>Survey held at</b>	23 LENG KEE ROAD		
<b>Repairer</b>	TRANS EUROKARS PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------