



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info	
Lee Chong Heng Blk 201 Bukit Batok Street 21 #16-168 Singapore 650201 Contact No Mobile: 94555341	Cust No/Name	KCV13714/Lee Chong Heng
	Reg No/Reg Date	SKQ9443B / 07/01/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WFZ000982
	Engine No	4B12NQ9485
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	14/02/2020/ 13:04	QUE	261 / Edwin Caina	51045
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER & TAILGATE REPAIR RR END PNL & RHR FENDER <i>SSO</i>					<i>1100</i> / 2750.00
E PNT98000 RESPRAY RR BUMPER, TAILGATE, RR END PNL & RHR FENDER <i>470</i>					<i>1760</i> / 840 1680.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT					275.00 ✓
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR					<i>2</i> 275.00 ✓
A 54900099 CHECK WIRING ELECTRICAL SYSTEM					50.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					200.00 ✓
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS					60 X 120.00
E PNT88000 REMOVE & REFIT R WINDSCREEN GLASS					240.00 ✓
M SUNDRY SUPPLY WINDSCREEN SEALANT					80.00 ✓
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING					X 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR					<i>80</i> 100.00 ✓
M SUNDRY SUPPLY REVERSE SENSOR					X ? 220.00
M SUNDRY SUPPLY C&C BADGE					40.00 ✓
M SUNDRY Sundries					<i>30</i> 50.00
M	FACE, RR BUMPER	1.00	1063.00	00.00	1063.00
M	BRKT, R/BMPR FACE SIDE, LH	1.00	12.00	00.00	12.00
M	BRKT, R/BMPR FACE SIDE, RH	1.00	12.00	00.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Lee Chong Heng	Cust No/Name KCV13714/Lee Chong Heng
Blk 201 Bukit Batok Street 21	Reg No/Reg Date SKQ9443B / 07/01/201
#16-168	Date In/Mileage / 0
Singapore 650201	Chassis No JMYXTGF3WFZ000982
Contact No Mobile: 94555341	Engine No 4B12NQ9485
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	14/02/2020/ 13:04	QUE	261 / Edwin Caina	51045			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REINFORCEMENT,RR BUMPER,LH	X	MM		1.00	79.00	00.00	79.00
M	REINFORCEMENT,RR BUMPER,RH	X	MM		1.00	79.00	00.00	79.00
M	CLIP,ENG ROOM COVER	MC			8.00	2.00	00.00	16.00
M	GARNISH,RR BUMPER SIDE,LH	X	MM		1.00	61.00	00.00	61.00
M	GARNISH,RR BUMPER SIDE,RH	X	MM		1.00	64.00	00.00	64.00
M	EXTENSION,RR BUMPER	CH			1.00	516.00	00.00	516.00
M	REFLECTOR,TAIL LAMP,LH	X	MM		1.00	171.00	00.00	171.00
M	REFLECTOR,TAIL LAMP,RH	BR			1.00	171.00	00.00	171.00
M	PANEL ASSY,TAILGATE	00			1.00	1130.00	00.00	1130.00
M	W/STRIP,TAILGATE OPENING	X	MM		1.00	213.00	00.00	213.00
M	GARNISH,TAILGATE	X	MM		1.00	744.00	00.00	744.00
M	LATCH,TAILGATE	X	MM		1.00	475.00	00.00	475.00
M	STRIKER,TAILGATE LATCH	X	MM		1.00	19.00	00.00	19.00
M	DAM,TAILGATE,UPR	MC			1.00	13.00	00.00	13.00
M	FASTENER,WINDSHIELD	MC			4.00	6.00	00.00	24.00
M	DAM,TAILGATE SIDE	MC			2.00	27.00	00.00	54.00
M	STOPPER,WINDSHIELD GLASS	MC			2.00	3.00	00.00	6.00
M	DAM,TAILGATE,LWR	MC			1.00	41.00	00.00	41.00
M	MARK,OUTLANDER	MC			1.00	95.00	00.00	95.00
M	DECAL,MIVEC	MC			1.00	36.00	00.00	36.00

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: _____

DATE: 5/3/20, 2.00pmREMARKS: P/P, Ry Bel 5/16 days

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Third party survey is on a "without prejudice" basis

7% GST on **Nett** 11254.00 **11,254.00**

Total Payable 12,041.78

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date: _____

Surveyor : THADDAEUS
 Claim : AIG OD
 DOA : 13.02.2020
 Emailed : 24.03.2020, 6.20pm
 Date survey : 05.03.2020

VEHICLE NO : SKQ 9443 B
 MODEL : MIT OUTLANDER 2.4
 WIP : 51045

Material	:	\$	3,189.00
Labour	:	\$	3,630.00
Sub-Total	:	\$	6,819.00
	:		-
Less Excess	:	\$	-
Total	:	\$	6,819.00
GST 7%	:	\$	477.33
Grand Total	:	\$	7,296.33
Finalise By/Date	:		LOI / 24/03/2020

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 6 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 8


☒ TP claim SHA 3700 T

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G


THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lee Chong Heng	Cust No/Name	KCV13714/Lee Chong Heng
Blk 201 Bukit Batok Street 21	Reg No/Reg Date	SKQ9443B / 07/01/2015
#16-168	Date In/Mileage	05/03/2020/ 82609
Singapore 650201	Chassis/Package	JMYXTGF3WFZ000982 /DC17RA3T3
Contact No Mobile: 94555341	Engine No	4B12NQ9485
05/03/2020	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CTP00040	Cash	24/03/2020/ 18:07	TLE	260 / AiTing	51045				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E	PNT88000	REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, TAILGATE, REPAIR REAR END PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME					✓		1100.00
E	PNT98000	RESPRAY ON REAR BUMPER, TAILGATE, REAR END PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME (8840 + 0420)					✓		1260.00
E	PNT88000	REMOVE & REINSTALL TAILGATE COMPONENTS TO FACILITATE REPAIR					✓		275.00
E	PNT88000	REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS & CARPET TO FACILITATE REPAIR					✓		275.00
A	54900099	CHECK WIRING & ELECTRICAL SYSTEM					✓		50.00
A	10028901	CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE					✓		200.00
E	PNT88000	REMOVE & REINSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR					✓		240.00
M	SUNDRY	SUPPLY REAR WINDSCREEN GLASS SEALANT					✓		80.00
E	PNT88000	REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR					✓		80.00
M	SUNDRY	SUPPLY C&C BADGE					✓		40.00
M	SUNDRY	SUNDRIES					✓		30.00
X	FACE,RR BUMPER	1.00	✓	1063.00	00.00			1063.00	
X	BRKT,R/BMPR FACE SIDE,LH	1.00	✓	12.00	00.00			12.00	
X	BRKT,R/BMPR FACE SIDE,RH	1.00	✓	12.00	00.00			12.00	
X	CLIP,ENG ROOM COVER	8.00	✓	2.00	00.00			16.00	
X	EXTENSION,RR BUMPER	1.00	✓	516.00	00.00			516.00	
X	REFLECTOR,TAIL LAMP,RH	1.00	✓	171.00	00.00			171.00	
X	PANEL ASSY,TAILGATE	1.00	✓	1130.00	00.00			1130.00	

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Lee Chong Heng	Cust No/Name KCV13714/Lee Chong Heng
Blk 201 Bukit Batok Street 21	Reg No/Reg Date SKQ9443B / 07/01/2015
#16-168	Date In/Mileage 05/03/2020/ 82609
Singapore 650201	Chassis/Package JMYXTGF3WFZ000982 /DC17RA3T3
Contact No Mobile: 94555341	Engine No 4B12NQ9485
05/03/2020	Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	24/03/2020/ 18:07	TLE	260 / AiTing	51045
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
X DAM, TAILGATE, UPR		1.00	✓ 13.00	00.00	13.00
X FASTENER, WINDSHIELD		4.00	✓ 6.00	00.00	24.00
X DAM, TAILGATE SIDE		2.00	✓ 27.00	00.00	54.00
X STOPPER, WINDSHIELD GLASS		2.00	✓ 3.00	00.00	6.00
X DAM, TAILGATE, LWR		1.00	✓ 41.00	00.00	41.00
X MARK, OUTLANDER		1.00	✓ 95.00	00.00	95.00
X DECAL, MIVEC		1.00	✓ 36.00	00.00	36.00
Z TEXT					
TP CLAIM INDIA SHA3700T					
DOA : 13.02.20					
SURVEYOR STEVE LKK 05.03.20					
REPAIR 06 DAYS					

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,189.00		
Labour	3,480.00		
Standard Menu	0.00	7% GST on	6819.00
Specialist Job	0.00		
Diagnostics Job	0.00		
Sundry/Others	150.00		
Total(w/o GST)	6,819.00		
		Nett	6,819.00
		Total Payable	7,296.33

This is not an official tax invoice.
 This is a computer generated document, no signature is required.