

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lee Chong Heng Blk 201 Bukit Batok Street 21 #16-168 Singapore 650201 Contact No Mobile: 94555341	Cust No/Name	KCV13714/Lee Chong Heng
	Reg No/Reg Date	SKQ9443B / 07/01/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WFZ000982
	Engine No	4B12NQ9485
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim	P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	14/02/2020/ 13:04	QUE	261 / Edwin Caina	51045		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER & TAILGATE REPAIR RR END PNL & RHR FENDER SS9							1100 2750.00
E PNT98000 RESPRAY RR BUMPER , TAILGATE , RR END PNL & RHR FENDER 470							840 1680.00
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT							275.00
E PNT88000 REMOVE & REFIT RR FLR BOARD,TRIM & CARPET TO FACILITATE REPAIR							275.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM							50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS							60 120.00
E PNT88000 REMOVE & REFIT R WINDSCREEN GLASS							240.00
M SUNDRY SUPPLY WINDSCREEN SEALANT							80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING							X 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR							80 100.00
M SUNDRY SUPPLY REVERSE SENSOR							220.00
M SUNDRY SUPPLY C&C BADGE							40.00
M SUNDRY Sundries							30 50.00
M FACE,RR BUMPER / DO				1.00	1063.00	00.00	1063.00
M BRKT,R/BMPR FACE SIDE,LH / NC				1.00	12.00	00.00	12.00
M BRKT,R/BMPR FACE SIDE,RH / NC				1.00	12.00	00.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Lee Chong Heng	Cust No/Name KCV13714/Lee Chong Heng
Blk 201 Bukit Batok Street 21	Reg No/Reg Date SKQ9443B / 07/01/201
#16-168	Date In/Mileage / 0
Singapore 650201	Chassis No JMYXTGF3WZF000982
Contact No Mobile: 94555341	Engine No 4B12NQ9485
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27)
	Colour/Trim P02 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	14/02/2020/ 13:04	QUE	261 / Edwin Caina	51045
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M REINFORCEMENT,RR BUMPER,LH	X	1.00	79.00	00.00	79.00
M REINFORCEMENT,RR BUMPER,RH	X	1.00	79.00	00.00	79.00
M CLIP,ENG ROOM COVER	MC	8.00	2.00	00.00	16.00
M GARNISH,RR BUMPER SIDE,LH	X	1.00	61.00	00.00	61.00
M GARNISH,RR BUMPER SIDE,RH	X	1.00	64.00	00.00	64.00
M EXTENSION,RR BUMPER	CH	1.00	516.00	00.00	516.00
M REFLECTOR,TAIL LAMP,LH	X	1.00	171.00	00.00	171.00
M REFLECTOR,TAIL LAMP,RH	BR	1.00	171.00	00.00	171.00
M PANEL ASSY,TAILGATE	OD	1.00	1130.00	00.00	1130.00
M W/STRIP,TAILGATE OPENING	X	1.00	213.00	00.00	213.00
M GARNISH,TAILGATE	X	1.00	744.00	00.00	744.00
M LATCH,TAILGATE	X	1.00	475.00	00.00	475.00
M STRIKER,TAILGATE LATCH	X	1.00	19.00	00.00	19.00
M DAM,TAILGATE,UPR	MC	1.00	13.00	00.00	13.00
M FASTENER,WINDSHIELD	MC	4.00	6.00	00.00	24.00
M DAM,TAILGATE SIDE	MC	2.00	27.00	00.00	54.00
M STOPPER,WINDSHIELD GLASS	MC	2.00	3.00	00.00	6.00
M DAM,TAILGATE,LWR	MC	1.00	41.00	00.00	41.00
M MARK,OUTLANDER	MC	1.00	95.00	00.00	95.00
M DECAL,MIVEC	MC	1.00	36.00	00.00	36.00

Estimate

SURVEYOR NAME: Steve (LKK)SURVEYOR SIGNATURE: [Signature]DATE: 5/3/20, 2.00pmREMARKS: P/P, Ry Bel sp6 days

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Authorized signatory and company stamp

Third party survey is on a "Without Prejudice" basis

Nett 11,254.00
7% GST on 11254.00 787.78
Total Payable 12,041.78

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Separate costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date: