

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SCK5599M

TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES2090192/YISHUN

Date: 02 Mar 2020

Policy No: 5083995229-03 DC

Veh Reg No: SCK5599M

Make/Model: TOYOTA COROLLA
 AXIO 1.5G CVT ABS
 D/AIRBAG 2WD

WS Ref: TP/FC

Claim Type: Third Party

Accident Date: 26/02/2020

TP Veh Reg No: SHD8626B

Chassis No: NRE1610020244

Engine No: 2NR8654616

Reg. Date: 15/09/2016

Not Withheld
Money After Party
U/Ling &
5 days

Estimate Repair Cost to Vehicle No :SCK5599M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	530.50	1 PC	<i>Am</i> 530.50	✓
2 REAR BUMPER RH SIDE RETAINER	92.30	1 PC	<i>Am</i> 92.30	✓
3 REAR BUMPER CLIPS	3.50	6 PCS	<i>Am</i> 21.00	✓
4 REAR BOOT	684.80	1 PC	<i>Am</i> 684.80	✓
5 REAR BOOT LOGO	50.20	1 PC	<i>Am</i> 50.20	✓
6 REAR BOOT EMBLEM 'AXIO'	36.40	1 PC	<i>Am</i> 36.40	✓
7 REAR BOOT EMBLEM 'G'	44.60	1 PC	<i>Am</i> 44.60	✓
8 REAR BOOT EMBLEM 'COROLLA'	39.20	1 PC	<i>Am</i> 39.20	✓
9 REAR BOOT INNER RUBBER	185.80	1 PC	<i>Am</i> 185.80	✓
10 REAR BOOT INNER LOCK	382.20	1 PC	<i>Am</i> 382.20	✓
11 RH TAILLAMP	555.00	1 PC	<i>cut</i> 555.00	✓
12 RH TAILLAMP CLIP	5.00	1 PC	<i>src</i> 5.00	✗
13 RH TAILLAMP LOWER RETAINER	82.80	1 PC	<i>src</i> 82.80	✗
14 REAR END PANEL	602.00	1 PC	<i>Am</i> 602.00	✓
15 REAR END PANEL INNER TOP GARNISH	218.20	1 PC	<i>Am</i> 218.20	✓
16 REAR END PANEL BUZZER SENSOR	144.70	1 PC	<i>Painted</i> 144.70	✓
17 REAR SPARE TYRE TOP BOARD	390.80	1 PC	<i>src</i> 390.80	✗
			4,065.50	
	Less 25%		1,016.38	3,049.13
Special Net				
18 REVERSE SENSOR	200.00	1 SET	<i>shocked</i> 200.00	✓
19 REAR END PANEL SEALANT	40.00	1 PC	<i>Am</i> 40.00	30.00
			240.00	240.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Estimate No: ES2090192/YISHUN

Date: 02 Mar 2020

Policy No: 5083995229-03 DC

Veh Reg No: SCK5599M

Make/Model: TOYOTA COROLLA
AXIO 1.5G CVT ABS
D/AIRBAG 2WD

Chassis No: NRE1610020244

Engine No: 2NR8654616

Reg. Date: 15/09/2016

WS Ref: TP/FC

Claim Type: Third Party


Accident Date: 26/02/2020

TP Veh Reg No: SHD8626B

Estimate Repair Cost to Vehicle No :SCK5599M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
20 REMOVE & REFIX REAR BUMPER & ATTACHMENTS,REAR BOOT & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL;KNOCKING & REPAIR REAR SPARE TYRE PANEL,REAR RH FENDER & REALIGN THE SAME	800.00	1 LA	800.00	600
21 PUTTY & RESPRAY REAR BUMPER,PARKING SENSORS,REAR BOOT,REAR END PANEL,REAR SPARE TYRE PANEL,FENDERS & ALL AFFECTED AREAS	800.00	1 LA	800.00	700
22 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	50.00	1 PC	50.00	✓
23 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,710.00	1,710.00
			Total	S\$ 4,999.13
			Add GST @ 7%	349.94
			Total Amount Payable	S\$ 5,349.07

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE