


SIE: _____ Vehicle Nos: **PC 8095 T**
 Date of Survey: _____ Model: Toyota Hiace
 Date of ReSurvey: _____ After-Paint: _____ Year: _____
 Contacts: _____ Chassis No: _____

*** AGREED Cost Of Repair and Repair Day/s with SIE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 2,195.00	\$ 2,195.00	DDV ✓
2	Tailgate logo	1	\$ 61.10	\$ 61.10	NEC ✓
3	Tailgate emblem 'TOYOTA'	1	\$ 69.20	\$ 69.20	NEC ✓
4	Tailgate emblem 'HIACE'	1	\$ 72.30	\$ 35.50	-72.30
5	Tailgate outer garnish	1	\$ 281.75	\$ 281.75	NDX ✓
6	Tailgate inner lock	1	\$ 289.90	\$ 289.90	NDX ✓
7	Tailgate lock actuator	1	\$ 381.45	\$ 381.45	NDX ✓
8	Tailgate lock striker	1	\$ 68.10	\$ 68.10	NDX ✓
9	Tailgate weatherstrip	1	\$ 282.90	\$ 282.90	NDX ✓
10	Tailgate windscreen moulding	1	\$ 182.25	\$ 182.25	NDX ✓
11	Rear bumper	1	\$ 496.54	\$ 429.80	-96.54
12	Rear bumper side retainer	2	\$ 60.70	\$ 121.40	-244.20
13	Rear bumper lower bracket	2	\$ 34.00	\$ 68.00	-337.00
14	Rear bumper step panel	1	\$ 374.45	\$ 374.45	NSX ✓
15	Rear end panel centre	1	\$ 581.45	\$ 581.45	DDV ✓
16	Rear end panel side	1	\$ 287.72	\$ 287.72	NDX ✓
17	Rear end panel top garnish	1	\$ 262.80	\$ 262.80	NDX ✓
18	Exhaust pipe	1	\$ 974.45	\$ 974.45	NDX ✓
19	Exhaust pipe mounting	1	\$ 65.30	\$ 65.30	NDX ✓
Parts Sub Total:				\$ 3555.45	7,507.86
Discount 25%:				\$ 888.86	1,876.97
PARTS TOTAL:				\$ 2666.59	5,630.90

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX ✓
2	Sticker '60 km/h'	1	\$ 35.00	\$ 15.00	-35.00
3	Sticker	1	\$ 180.00	\$ 60.00	-180.00
4	Tailgate windscreen inner seal	1	\$ 120.00	\$ 120.00	NSX ✓
5	Tailgate windscreen sealant	1	\$ 80.00	\$ 40.00	-80.00
6	Tailgate windscreen primer and cleaner	1	\$ 60.00	\$ 60.00	NNX ✓
7	Rear bumper clips	1	\$ 50.00	\$ 30.00	-50.00
8	Rear end panel sealant	1	\$ 100.00	\$ 100.00	NNX ✓
9	Rear end panel side sealant	1	\$ 60.00	\$ 60.00	NNX ✓
10	Reverse sensor	4	\$ 200.00	\$ 200.00	SCV ✓
11	Tailgate outer garnish clips	1	\$ 50.00	\$ 50.00	NNX ✓
SPECIAL NETT TOTAL:				\$ 345.00	1,615.00



Nos.	LABOUR	S\$	
1	R&R tailgate component	\$ 30.00	150.00
2	R&R reverse sensor	\$ 60.00	100.00
3	R&R rear windscreen	\$ 120.00	250.00
4	R&R Exhaust pipe	\$	150.00
5	Check wiring	\$ 50.00	150.00
6	Panel beat	\$ 800.00	1,400.00
7	Spray painting	\$ 600.00	1,400.00
8	Rust proofing	\$ 60.00	200.00
LABOUR TOTAL:		\$ 1770.00	3,800.00

PARTS TOTAL: \$ 2666.59 5,630.90
SPECIAL NETT TOTAL: \$ 345.00 1,615.00
LABOUR TOTAL: \$ 1770.00 3,800.00
GRAND TOTAL: \$ 4781.59 11,045.90

Survey 5/3/2020

Re-survey 24/3/2020

TG Lim
Min
1530.00

TG Lim
1530 hrs
Lum sum Repair
Repair days 5

4781.59
@ 20% 956.32
3825.27

L/S 3800/2

TG Lim
Min
28/4/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

