

Vehicle Estimate

Supplier:

Attention to: LKK

Page: 1/1

Vehicle No.:

SKV 2390P

DETAIL LAB
Person-in-charge:
Chassis No.:
Year:

Make & Model:

MB CLA180

Parts/Description	Qty	Unit Price (\$)
1 R/H LA Quarterpanel X (CR)	1 PC	1850.00
2 Rear Bump X (CR)	1 PC	1350.00
3 LA R Door ✓ BT	1 PC	1250.00 ✓
4 LA R Door X (CR)	1 PC	1250.00
5 LA R Door seal ✓ nec	1 PC	185.00 ✓
6 LA R Door seal ✓ nec	1 PC	185.00 ✓
7 LA Side Skirt R/H ✓ SCR	1 PC	455.00 ✓
8 LA Wheel Hub } Any ✓ CRU	1 PC	368.00 ✓
9 LA Wheel Bearing }	1 PC	- ✓
10		
11 parts less	-	100%
12		
13 S/Nett		700 ✓
14 19" R/H ✓ SCR	1 PC	1600.00 ✓
15 R/H PDC sensor R/H ✓ short	1 PC	325.00 ✓
16 19" tyre X (svc)	1 PC	335.00
17		
18		
19		
20		
21 Labor		
22 wheel alignment ✓		180.00 60 ✓
23 wing check ✓		120.00 30 ✓
24 Removal / Replace undercarriage → (R+R/H only) ✓		180.00 100 ✓
25 door mechanism → R+R/H only ✓		180.00 70 ✓
26 spray painting ✓		1600.00 900 ✓
27 panel beating ✓		1300.00 750 ✓
28 Remove / Replace R/H 19" X (refer to labor)		60.00
29 Remove / Replace PDC sensor ✓		80.00 20 ✓
30		
31 L/S repair	parts	2443
32 without prep work	parts less	100%
33 manager of car part (4:30pm)		2198.70
34 5 day (27/2/20)	spl nett	960
35 Hoch ANN (11th)	labor	1880
36 Hoch ANN @ ilkk auto.com		5038.70
85312883 / 6741874	4/5 less	200%
		4030.96
	total	4000.00