

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 90930037

TP 1st Cap.
 Vic

ESTIMATE

Repair Code : CLM16096

Date in : 26/02/2020

Vehicle Num. : SLW4061J

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng# : RU31222459/LEB5922466

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Replaced</i>	1	810.70	✓ 810.70
FRONT BUMPER SIDE RETAINER L/R <i>Rt side</i>	2	20.60	<i>20.60</i> 41.20
FRONT RH DOOR <i>Replaced</i>	1	1080.50	✓ 1,080.50
FRONT RH DOOR FRAME BLACK STICKER <i>new</i>	1	33.00	— 33.00
FRONT RH DOOR INNER PLASTIC SEAL COVER <i>new</i>	1	35.30	+ 35.30
FRONT RH DOOR MECHANISM LOCK <i>Damaged</i>	1	196.30	— 196.30
FRONT RH FENDER 'HYBRID' EMBLEM <i>new</i>	1	95.00	✓ 95.00
FRONT RH FENDER ARCH GARNISH <i>cut</i>	1	220.00	— 220.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	+ 46.00
REAR RH BUMPER SIDE <i>Replaced</i>	1	195.00	+ 195.00
REAR RH DOOR <i>Dented</i>	1	930.60	✓ 930.60
REAR RH DOOR CENTER RUBBER SEAL <i>cut</i>	1	35.00	✓ 35.00
REAR RH DOOR CLEAR STICKER <i>new</i>	1	21.70	✓ 21.70
REAR RH DOOR FRAME BLACK STICKER <i>new</i>	1	28.50	✓ 28.50
REAR RH DOOR HINGES (TOP & LOWER) <i>Best</i>	2	38.50	✓ 77.00
REAR RH DOOR INNER PLASTIC SEAL COVER <i>new</i>	1	35.30	+ 35.30
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	196.30	+ 196.30
REAR RH FENDER ARCH GARNISH <i>cut</i>	1	195.00	✓ 195.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

Kaki Bukit Ave 2

#01-11 / #01-13 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 90930037

ESTIMATE

Repair Code : CLM16096

Date in : 26/02/2020

Vehicle Num. : SLW4061J

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng# : RU31222459/LEB5922466

REAR RH WHEEL CAP <i>NEW</i>	3743.90	1	198.00	<i>+</i> 198.00
	2995.12			
		Subtotal before discount		4,470.40
Percentage discount 20%				894.08
		Sub-total 1		3,576.32
FRONT BUMPER CLIPS - SET <i>NEW</i>		1	50.00	<i>30</i> 50.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>NEW</i>		1	50.00	<i>+</i> 50.00
FRONT RH FENDER ARCH GARNISH CLIPS - SET <i>NEW</i>		1	30.00	<i>90</i> 30.00
REAR BUMPER CLIPS - SET <i>NEW</i>		1	50.00	<i>+</i> 50.00
REAR RH DOOR INNER TRIM BOARD CLIPS - SET <i>NEW</i>		1	50.00	<i>+</i> 50.00
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>NEW</i>		1	30.00	<i>30.00</i> 30.00
		Subtotal before discount		260.00
Percentage discount 0%				0.00
		Sub-total 2		260.00
		Parts-total		3,836.32

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

30 ~~50.00~~

+ 100.00

160 ~~200.00~~

1100 ~~1,300.00~~

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Lokit AutoHub
181 Lokit Ave 2
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 90930037

ESTIMATE

Repair Code : CLM16096
Date in : 26/02/2020
Vehicle Num. : SLW4061J
Model : HONDA VEZEL HYBRID 1.5 AUTO
Chassis/Eng# : RU31222459/LEB5922466

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

1940	600	800.00
	50	100.00
Labour Total		2,550.00
Parts & Labour Total		6,386.32

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lij
H/S 28/02/20
oblays.

total: 5025.12

H/S: HK. ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: