



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
REPAIR PERFORMA INVOICE

AIG Singapore
 78 Shenton Way
 Singapore 079120

Vehicle number	SJR5212J
Make / Model	MERCEDES/CLC180K
Chassis number	WDB2037462E066187
Accident date	20 February 2020
Reference	2002-47

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

- | | | |
|---|------------------------------|-------|
| 1 | REAR BUMPER | |
| 2 | REAR BUMPER BRACKET | 71.30 |
| 1 | REAR BUMPE RINFORCEMENT | |
| 1 | REAR BUMPER CENTRE MOULDING | |
| 1 | REAR BUMPER SIDE MOULDING RH | |
| 1 | REAR RH FENDER | 3501 |
| 1 | FUEL LID COVER | 275 |
| 1 | RIM | |
| 1 | REAR RH WHEEL CARRIER | 1611 |
| 1 | REAR RH WHEEL BEARING | |
| 1 | REAR RH SHOCK ABSORBER | |
| 1 | REAR RH CHAMBER ARM | |
| 1 | REAR RH RADIS ROD | |
| 1 | REAR RH TIE ROD | |

ole ✓ 1491.55 ?
 LH-X 142.60 RH-Bt ✓
 nn 1093.65 x 1n
 930.35 x nn
 167.90
 4908.20 bt ✓
 575.00 dd ✓
 1200.00 int ✓
 2173.50 ? bt ✓
 435.85 ? bt ✓
 661.25 x
 218.50 x }
 108.10 x }
 193.20 x }

8753.60
 7878.24
 Less 10 %
 Subtotal

14299.65
 1429.96
 12869.69

Balance C/F

12869.69

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- | | | |
|-------|--------------------|--|
| 1 SET | REAR BUMPER CLIP | |
| 1 BOT | BRAKE FULD | |
| 1 | JOINT SEALANT | |
| 1 | WINDSCREEN SEALANT | |

30.00 ne ✓
 60.00 x nn ✓
 120.00 40 ne ✓
 120.00 60 ne ✓

Subtotal

330.00 120

Balance C/F

13199.69

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	13199.69
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30
2	REMOVE, REFIT LINING, TRIM AND GARNISH	200.00 60
3	COMPUTERISE AND CHECK REAR WHEEL ALIGNMENT	150.00 80
4	REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓
5	REMOVE AND RENEW REAR WHEEL UNDERCARRIAGE	✓ 200.00 100? parts
6	REMOVE AND REFIT FUEL TANK	150.00 60? parts
8	PANEL BEATING ON AFFECTED AREAS	1400.00 700
9	SPRAY PAINTING ON AFFECTED AREAS	1200.00 600
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
Subtotal		1780
		3630.00
Grand total		16829.69

7878.24

130

1780

613.62

20

80

10,501.86

4/5 \$ 8400 #
07 days

Taughin 97495747
'WP'

4/3/20 @ 1050

Cumprison

Resurvey after repair

500
Taughin @ 11 hours
6-7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

SUPPLEMENTARY

Vehicle number SJR5212J
Make / Model MERCEDES/CLC180K
Chassis number WDB2037462E066187
Accident date 20 February 2020
Reference 2002-47

AIK Singapore
78 Shenton Way
Singapore 079120

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	QUARTER GLASS MOULDING RH	net 240.00 165
1	REAR RH FENDER GARNISH	net 444.00 210
1	REAR RH FENDER CHROME	net 80.00
1	REAR RH FENDER INNER SHIELD	net 226.80
	681.80	990.80
	613.62 Less 10 %	99.08
	Subtotal	891.72
	Balance C/F	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	REAR RH FENDER GARNISH CLIP	net 80.00
	Subtotal	80.00
	Balance C/F	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	
1	REMOVE AND REFIT REAR QUARTER GLASS	80 net 200.00
	Subtotal	200.00
	Grand total	937.38

5/2