

Date: 09.03.2020
Vehicle No: SCY123L
Model: FERRARI 458 SPECIALE
Chassis: ZFF75VHC000205521-2014
Reg.Year: 2014

Third Party Insurer: AIG
Third Party Veh No: SKZ7066Y
Date of Accident: 22.02.2020

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS SET	1		<i>nn</i> \$80.00
2	FRONT BUMPER RIVET SET	1		SVC \$60.00
3	FRONT BUMPER GROMMET SET	1		SVC \$118.00
4	FRONT BUMPER PPF PROTECTION FILM STICKER	1	<i>nn</i> (B/I)	\$800.00
S/N TOTAL				\$1,058.00

ESTIMATE

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE & REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$400.00 *2301*

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT FRONT BUMPER & ETC.

\$600.00 *400*

TO DIAGNOSE FAULTY CODE & RESET MEMORY.

nn \$150.00 *X*

LABOUR TOTAL \$1,150.00

ONG TOTAL \$2,208.00

Not with order

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Cheng Road Singapore 159143
Tel: (+65) 6472 1313 / Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 / Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 / Fax: (+65) 6452 9223

