

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD Ref: CS/AWA20003385/Kyf3e2

(SINGAPORE BRANCH)

60 ANSON ROAD #08-01 (8th FLOOR)

ESTIMATED NORMAL PERIOD FOR REPAIR:

MAPLETREE ANSON

Date: 18-05-2020



SINC	GAPORE 079914					
			Code: AWA			
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBN 1744H	Veh. Inspected	SKU 1404X		
	Policy No.	AVFMSB0000651901	Coverage (\$)	0.00		
	Claim No.	NSV2000091/KW	Excess (\$)	0.00		
	Assign From	WONG KIN	Assign Date	28/02/2020		
2.		Vehicle Particulars & Condition				
	Make & Model	NISSAN TEANA (A)	c.c	2488		
	Engine No.	HIDDEN	Year of Reg.	2015		
	Chassis No.	MNTBCAL33Z0003043	Colour	METALLIC DARK GREY		
	Odometer	50538	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
3.		Condit	ions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	215/55 R17	FALKEN	8 mm		
	L/H Front Tyre	215/55 R17	FALKEN	8 mm		
	R/H Rear Tyre	215/55 R17	FALKEN	8 mm		
	L/H Rear Tyre	215/55 R17	FALKEN	8 mm		
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	24/02/2020	Inspection Date	02/03/2020		
	Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD				
		BLK 8 SIN MING IND EST				
		#01-64/66 SINGAPORE 575643				
5a.		Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

6 Working Days