Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003421/GPA3Q2

Date: 23/04/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant

SHC7228D Insured Vehicle No: SHD3642L Vehicle No:

Date of Loss: Nature of Claim: TP 28/02/2020 Claim No: MCT20020608

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SHC7228D** Reg No:

HYUNDAI 140, 1.7 D CRDI F/L ABS AIRBAG 4DR Make & Model: Engine No: D4FDGU662603 (A)

KMHLB41UMGU092623 Reg. Date: 11/08/2016 (Man. Year: 2016) Chassis No:

Colour: Yellow Odometer: 382789 km

1685 cc **Engine Capacity:** Market Value/New Car N/A

Price: Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: Triangle 5 mm Rear Left Side: Triangle 5 mm Front Right Side: Rear Right Side: Triangle 5 mm Triangle 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,926.50	155.00	3,771.50	96.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	860.00	690.00	44.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,476.50	1,015.00	4,461.50	81.47
+ GST 7.00/7.00% (S\$)	383.36	71.05	312.31	81.47
Nett Amount (S\$)	5,859.86	1,086.05	4,773.81	81.47
+ Loss of Use (4.0	x S\$40.00/day) (S\$)	160.00		
+ Car Rental (4.0 x	( S\$105.30/day) (S\$)	421.20		
+ [	Doc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	1,674.70		
Global S	Sum Settlement (S\$)	1,670.00		

**INSPECTION** 

Date of Assignment: 02/03/2020

Date Inspected: Ding Automotive Pte Ltd 02/03/2020 Inspected At: 31 CORPORATION ROAD

SINGAPORE 649825

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference			
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)	
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	de: (Unsubmitted, no print-code for SHC7228D)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

# **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RHS DOOR	Repair	2,256.83 FL	*- FL
2	1		*REAR RHS DOOR	Repair	2,201.30 FL	*-FL
3	1		*REAR RHS DOOR STICKER -COMFORTDELGRO ,BOOK NOW ,GOOGLE PLAY ,APPSTORE	Necessary	150.00 FS	*80.00 FS
4	1		*FRONT RHS DOOR STICKER -COMFORTDELGRO	Necessary	150.00 FS	*75.00 FS
5	1		*FRONT AND REAR RHS DOOR CLIPS	Not Necessary	60.00 FS	*-FS
F=Fra	nchise	part. S=	SpcNett. L=ListItemDisc.			
Sub Total (S\$)				4,818.13	155.00	
- List Item Discount on L Items 20.00/20.00% (S\$)				891.63	0.00	
			To	otal Parts (S\$)	3,926.50	155.00
			Report was unsubmitted during this print-o	ut.		

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	New	800.00	400.00
2	RESPRAY FRONT RHS DOOR	New	250.00	200.00
3	RESPRAY REAR RHS DOOR	New	250.00	200.00
4	R&R FRONT AND REAR DOOR COMPONENTS	New	150.00	60.00
5	RUST PROOFING	New	100.00	0.00
	Gross Labor	ur Cost (S\$)	1,550.00	860.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.