

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113

HP: 8386 8989

Co. Reg. No. : 53368526E

Date of Estimate: 21.04.2020

Vehicle No: PC3355B

Owner: Goh Transport Services Co Pte Ltd

Date of Accident: 17.02.2020

Make & Model: YUTONG ZK6107H

Chassis No : LZYTBD68B1033756

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE FOR ACCIDENT VEHICLE NO PC3355b

PARTS

1	1	Rear side panel(repair)	XR	\$0.00
2	1	Rear side engine compartment(repair)	XX	\$0.00
SUB TOTAL				\$0.00
LESS 5 %				\$0.00
DISCOUNTED SUB TOTAL				\$0.00

LABOUR

1	Panel beating for replace and repair affected parts	\$500.00	400
2	Spray painting on affected area X 4 colours	\$800.00	650
3	Apply putty and anti-corrosion to affected parts	\$100.00	50
SUB TOTAL (LABOUR)		\$1,400.00	1,100

SUB TOTAL (PARTS) \$0.00

SUB TOTAL (LABOUR) \$1,400.00

ESTIMATED GRAND TOTAL \$1,400.00

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP

Repair day - 2 days

P/P

After paint photo.

Sun Pin (Lhl)

23/04/2020

TP without prejudice

P/P
\$1,100
2 days