

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elizabeth Chew

Date: 04 Jun 2020

Preliminary Advice

Insured Vehicle No : YN7099A

TP Vehicle No : PC3355B

Make : YUTONG ZK6107H

Date of Inspection : 23/04/2020

Inspection At : A T Auto Consultant (HQ)
B/113 Teck Whye Lane, #05-650
Singapore 680113

Accident Date : 17/02/2020

Assignment Date : 04/06/2020

Est. Duration of Repair : 2 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s & n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,400.00
Revised Amount	:S\$	1,100.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,100.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP