

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Feb-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6367 S

1 pc	Boot lid xun xun	\$	1,119.00
1 pc	Boot lid lock xun	\$	99.00
1 pc	Bootlid striker xun	\$	21.00
1 pc	Bootlid emblem nec	\$	27.00
1 pc	Bootlid CRDi nec	\$	29.00
1 pc	Boot lid rubber weatherstrip xun	\$	96.00
1 pc	Boot lid lower garnish x(R)	\$	290.00
1 pc	Rear bumper CR	\$	696.00
1 pc	Rear bumper lower cover DEF	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 xun	\$	58.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper reinforcement ?	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 xun	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ?	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ?	\$	36.00
		\$	3,542.00
		Less 10%	\$ 415.50
		\$	3,126.50

S/NETT

1 set	Rear bumper clips nec	\$	48.00
1 set	End panel inner garnish clips xun	\$	30.00
1 set	Bootlid lower garnish clips nec	\$	60.00
1 set	Bootlid stickers nec	\$	100.00
1 set	Reverse sensor ?	\$	280.00

27-Feb-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6367 S

Sundry	\$ 50.00	\$30
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00	\$60
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	\$90
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$ 800.00	\$360
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel	\$ 800.00	\$360
To apply rustproofing on the repaired and replaced panels.	\$ 120.00	\$30
	<u>\$ 5,714.50</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5775.80
Ran (LKR)
2/3/2020 1715hrs
PareSuem@lkkauto.co
88622778
(LIS) after repair photo
Dismantle Required
3 repair days