

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR. AHMAD SYUHADAK BIN SAHED
BLK 812A CHOA CHU KANG AVE 7 #06-677
SINGAPORE 681812

Contact : 97734291

ESTIMATE

Repair Code : CLM14889

Date in : 02/03/2020

Vehicle Num. : SLG1043R

Model : HONDA VEZEL 1.5X A

Chassis/Eng# : RU11112973/L15B4032977

TP 1st Cap.
Ashes

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>2hd</i>	1	487.10	487.10 ✓
REAR BUMPER RH REFLECTOR <i>ren</i>	1	141.10	141.10 +
REAR BUMPER SIDE COVER RH <i>2hd</i>	1	195.00	195.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>ren</i>	2	23.00	46.00 ✓
REAR RH FENDER ARCH GARNISH <i>free</i>	1	195.00	195.00 +
REAR RH FENDER INNER AIR VENT	1	30.30	30.30 +
Subtotal before discount			1,094.50
Percentage discount 20%			218.90
Sub-total 1			875.60
REAR BUMPER CLIPS - SET <i>ren</i>	1	80.00	80.00 30
REAR BUMPER TOP PANEL <i>xben</i>	1	350.00	350.00 +
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>xben</i>	1	30.00	30.00 +
Subtotal before discount			460.00
Percentage discount 0%			0.00
Sub-total 2			460.00
Parts-total			1,335.60

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

100.00 70
140.00 +

*** This is a computer-generated document which requires no signature.***

winCar AUTOMOTIVE PTE LTD

Bukit AutoHub
Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MR. AHMAD SYUHADAK BIN SAHED
BLK 812A CHO A CHU KANG AVE 7 #06-677
SINGAPORE 681812

Contact : 97734291

ESTIMATE

Repair Code : CLM14889

Date in : 02/03/2020

Vehicle Num. : SLG1043R

Model : HONDA VEZEL 1.5X A

Chassis/Eng# : RU11112973/L15B4032977

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,340.00
Parts & Labour Total	2,675.60

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Y
h/s 02/03/20
02 Days

total: 1182.48

h/s: 900 ✓