

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 1612E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	DEEP CUT	766.80	766.80
1	FRONT BUMPER FOG LAMP COVER-RH (CONSISTENT)	NOT NECESSARY	21.60	-
1	FRONT BUMPER SIDE RETAINER RH (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT FENDER RH (CONSISTENT)	TO REPAIR SEE LABOUR	412.80	-
1	FRONT HEADLAMP -RH (CONSISTENT)	CRACKED	972.00	972.00
1	FRONT SHOCK ABSORBER -RH (CONSISTENT)	NOT NECESSARY	336.00	-
1	FRONT SHOCK ABSORBER TOP MOUNT (CONSISTENT)	NOT NECESSARY	102.00	-
1	FRONT LOWER ARM AND BALL JOINT (CONSISTENT)	NOT NECESSARY	405.60	-
1	FRONT KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	420.00	-
1	FRONT WHEEL HUB (CONSISTENT)	NOT NECESSARY	174.00	-
1	FRONT WHEEL BEARING (CONSISTENT)	NOT NECESSARY	157.20	-
1	FRONT ANTI ROLL BAR (CONSISTENT)	NOT NECESSARY	304.80	-
1	FRONT ANTI ROLL BAR LINK (CONSISTENT)	NOT NECESSARY	86.40	-
	LESS 10% DISCOUNT		-	-176.88
			4,189.20	1,591.92
	SPECIAL NETT ITEMS			
1	FRONT SPORT WHEEL O/S (50%) (SN) (CONSISTENT)	CUT	320.00	160.00
1	FRONT TYRE O/S (SN) (CONSISTENT)	NOT NECESSARY	180.00	-
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	45.00	45.00
			545.00	205.00
	LABOUR			
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE ,REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	_
	TO CHECK WHEEL ALIGNMENT.		120.00	60.00
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	60.00	-
	TO RESPRAY PAINTING AND ETC.		800.00	300.00
	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH .		800.00	400.00
			2,180.00	780.00

Report Ref No. CC4/ASM20003430/Uga3q2



Page No.:2 of 2

GRAND TOTAL	6,914.20	2,576.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		2,050.00

Report Ref No. CC4/ASM20003430/Uga3q2

CHUA KANG SENG
Licensed Appraiser