

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 02/03/2020

Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLES087Z

CHASSIS NO: NSP1707016100

MAKE / MODEL: Toyota Sienta 1.5GX CVT

DATE OF ACCIDENT: 09/01/2020

YOUR INSURED VEHICLE NUMBER: SL24316J

MILEAGE: 226062km

PARTS DESCRIPTION

	QTY	UNIT PRICE	LIST PRICE
1 Rear tailgate	1PC	\$ 1,879.00	\$ 1,879.00 <i>bt / 1086</i>
2 Rear tailgate windscreen moulding	1PC	\$ 54.00	\$ 54.00 <i>net</i>
3 Rear tailgate Toyota emblem	1PC	\$ 53.00	\$ 53.00 <i>net</i>
4 Rear bumper center pad	1PC	\$ 90.00	\$ 90.00 <i>net</i>
5 Rear bumper	1PC	\$ 1,257.83	\$ 1,257.83 <i>net / 045</i>
LIST TOTAL S\$			\$ 3,333.83 <i>1928</i>
25.00% DISCOUNT S\$			\$ 833.46 <i>1446</i>
			\$ 2,500.37

S/Nett

Reverse sensor

Sealant

\$ 240.00 *200mm*
\$ 60.00 *40mm* *240*

Total \$ 300.00

LABOUR CHARGES

- 1 To labour charge for removing rear tailgate and rear bumper out to facilitate replacement of damaged part \$600.00 *400*
- 2 To respray rear bumper and rear tailgate \$600.00 *400*
- 3 Transfer taigate mechanism \$150.00 *60*
- 4 Remove and install rear tailgate windscreen glass \$150.00 *130 980*

LABOUR TOTAL S\$	\$1,200.00
TOTAL S\$	\$4,900.37
7% GST	\$343.03
GRAND TOTAL S\$	\$5,243.40

LKK Auto Consultants hereby notify the Reparer of the following:

- To repair and/or replace damaged parts
- To repair and/or replace damaged parts
- To repair and/or replace damaged parts
- To repair and/or replace damaged parts
- To repair and/or replace damaged parts
- To repair and/or replace damaged parts
- To repair and/or replace damaged parts
- To repair and/or replace damaged parts

Acknowledged by Reparer

1446
240
980
2666
1/5/2100

Tanfer 97495747
WP
2/3/20 0520pm
Lump sum
Rising after repair
4 days
Tanfer e lthart.com