

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 02/03/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLE5087Z

CHASSIS NO : NSP1707016100

MAKE / MODEL : Toyota Sienta 1.5GX CVT

DATE OF ACCIDENT : 09/01/2020

YOUR INSURED VEHICLE NUMBER : SLZ4316J

MILEAGE : 226062km

PARTS DESCRIPTION

	QTY	UNIT PRICE	LIST PRICE	
1 Rear tailgate	1PC	\$ 1,879.00	\$ 1,879.00	bt ✓
2 Rear tailgate windscreen moulding	1PC	\$ 54.00	\$ 54.00	ue ✓
3 Rear tailgateToyota emblem	1PC	\$ 53.00	\$ 53.00	ue ✓
4 Rear bumper center pad	1PC	\$ 90.00	\$ 90.00	ant ✓
5 Rear bumper	1PC	\$ 1,257.83	\$ 1,257.83	de ✓
LIST TOTAL S\$:			\$ 3,333.83	
25.00% DISCOUNT S\$:			\$ 833.46	
			\$ 2,500.37	

S/Nett

Reverse sensor

Sealant

Total

\$ 240.00 200mm ✓
 \$ 60.00 40mm ✓
 \$ 300.00

LABOUR CHARGES

- | | | | |
|---|---|----------|------|
| 1 | To labour charge for removing rearm tailgate and rear bumper out to facilitate rplacement of damaged part | \$600.00 | 400. |
| 2 | To respray rear bumper and rear tailgate | \$600.00 | 400 |
| 3 | Transfer taigate mechanism | \$150.00 | 60. |
| 4 | Remove and install rear tailgate widscreen glass | \$150.00 | 120. |

LABOUR TOTAL S\$: \$1,200.00
 TOTAL S\$: \$4,900.37
 7% GST \$343.03
 GRAND TOTAL S\$: \$5,243.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfah 97495749
 'WP'
 2/3/20 2520pm
 Lumpur
 Resurvey after repair
 4 days
 Tanfah e lkkauto.com