



## Case Details

Case Reference Number : TAX/02/20/2092  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHB5112Y

Company Type : SMRT Taxis Pte Ltd  
Estimation ID : EST-10682-ID  
Assigned By : Taxi Claims Manager Team

Insurance Company Name : India International Insurance Pte Ltd  
Accident Date and Time : 26/02/2020 09:15 PM  
Vehicle Age(In Months) : 27

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| SMRT Recommendation   |              |         |                 |                           |     |                         |                |        |                 |                  | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------|-----|-------------------------|----------------|--------|-----------------|------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                 | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace  | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | DOOR FRT/RH               | 1   | 894.40                  | 894.40         | 25.00  | 670.80          | Replace          | 0                 | 0                        | Not Given      | X       |
| One Time Key In       | Main         |         |                 | STICKER DECAL SMRT (DOOR) | 1   | 60.00                   | 60.00          | 0.00   | 60.00           | Replace          | 0                 | 0                        | Not Given      | X       |
| One Time Key In       | Main         |         |                 | MIRROR ASSY,RH            | 1   | 1,307.10                | 1,307.10       | 10.00  | 1,176.39        | Replace          | 1                 | 1,176.39                 | Replace        | am      |
| One Time Key In       | Main         |         |                 | MIRROR LAMP RH            | 1   | 65.30                   | 65.30          | 10.00  | 58.77           | Replace          | 0                 | 0                        | Check          | ?       |
| One Time Key In       | Main         |         |                 | COVER, OUTER MIRROR, RH   | 1   | 107.40                  | 107.40         | 25.00  | 80.55           | Replace          | 1                 | 80.55                    | Replace        | miz     |
| Total Spare Part Cost |              |         |                 |                           |     |                         |                |        | 2,046.51        | Surveyor Total   |                   | 1,256.94                 |                |         |
| Lump Sum Discount (%) |              |         |                 |                           |     |                         |                |        | 0.00            | Lump Sum Dis (%) |                   | 0                        |                |         |
| Final Spare Part Cost |              |         |                 |                           |     |                         |                |        | 2,046.51        | Final Sur Total  |                   | 1,256.94                 |                |         |

### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope                  | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|----------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR FRONT RH PORTION | 338.00                  | 100                     |         |
| Total: |              |                            | 338.00                  | 100.00                  |         |

### Spray Cost Detail

| S.No.  | Costing Type | Job Scope                | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|--------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY FRONT DOOR RH | 378.00                  | 0                       |         |
| 2      | Main         | RESPRAY MIRROR COVER RH  | 180.00                  | 100                     |         |
| Total: |              |                          | 558.00                  | 100.00                  |         |

# Other Cost Detail

| S.No.  | Costing Type | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks              |
|--------|--------------|-------------------------------------|-------------------------|-------------------------|----------------------|
| 1      | Main         | TO REMOVE AND REFIX WING MIRROR     | 120.00                  | 120.00                  |                      |
| 2      | Main         | TO REPLACE SUNDRY PARTS             | 100.00                  | 0                       |                      |
| 3      | Main         | TO CHECK WIRING AND SYSTEM FUNCTION | 80.00                   | 30                      |                      |
| 4      | Main         | TO WASH AND VACUUM                  | 60.00                   | 0                       |                      |
| 5      | Main         | TOWING CHARGE                       | 84.00                   | 0                       | Check towing receipt |
| Total: |              |                                     | 444.00                  | 150.00                  |                      |

## Summary

|                          | Estimator Assesment(\$)                                                             | Surveyor Assesment(\$)                                                                |
|--------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|
| Total Spare Part Detail  | 2,046.51                                                                            | 1,256.94                                                                              |
| Total Labour Cost        | 0.00                                                                                | 100.00                                                                                |
| Total Spray Painting     | 0.00                                                                                | 100.00                                                                                |
| Other                    | 0.00                                                                                | 150.00                                                                                |
| Overall Total            | 2,046.51                                                                            | 1,606.94                                                                              |
| Lump Sum Repair Option   |                                                                                     |                                                                                       |
| Lump Sum Total           | 2,050.00                                                                            | 1,600.00                                                                              |
| Surveyor Approved Amount |                                                                                     | 1,600.00                                                                              |
| No of Repair Days*       | 4                                                                                   | 1                                                                                     |
| Remarks                  |                                                                                     | Resurvey after repair                                                                 |
| Surveyor Name            |                                                                                     | Taufikh                                                                               |
| Signature                |  |  |

Survey Date

02/03/2020

Taufikh 97495749  
WP  
2/3/20  
01 day  
Resurvey after repair  
Taufikh & Whiston

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: