



Section A - Accident Details

Registration Number	SHB5112Y
Case Reference Number	TAX/02/20/2092
Registration Date	3/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TEO CHENG GUAN
Type of Accident	Side Swipe
Accident Date and Time	27/2/2020 5:15 AM
Accident Reported Date and Time	28/2/2020 4:10 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	27/2/2020 8:25 PM
Replacement Vehicle issued?	No
Job Card Number	24105951
Special Instruction to ARC, if any	TOWED \$60
Prepared Date and Time	29/2/2020 8:36 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$100.00
Total Spray Cost	\$558.00	\$100.00
Total Spare Part Cost	\$2,046.51	\$1,256.94
Total Other Cost	\$444.00	\$210.00
TOTAL COST	\$3,386.51	\$1,666.94 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	1.0
Prepared / Adjusted By	Ang Bang Kien	Taufikh (LKK) / III
ARC / Surveyor Sign Off Date	29/02/2020 8:43 AM	02/03/2020 3:51 PM
Signature		
Remarks	Resurvey after repair	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2003-0142	Invoice Number	
Quotation Date	09.03.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$338.00	\$100.00
Total Labour	\$338.00	\$100.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00
RESPRAY MIRROR COVER RH	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$558.00	\$100.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$120.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$84.00	\$60.00
Total Other Costs	\$444.00	\$210.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		67001-47070	DOOR FRT/RH	0.00	\$894.40	0.00	\$0.00	Replace	Not Given
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given
		87910-47330	MIRROR ASSY,RH	1.00	\$1,307.10	10.00	\$1,176.39	Replace	Replace
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Check
		879157-4010	COVER, OUTER MIRROR, RH	1.00	\$107.40	25.00	\$80.55	Replace	Replace
Total					\$2,434.20		\$1,256.94		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1256.94
+ 100.00
+ 310.00
1666.94

Email Poh Suan
\$1666.94, 1 day.