

FBD6952T.
Yamaha X-12.
453010160

TPMS16. Xiao Chen.

Front Wheel Fender	cut	70	✓
Front Tyre	2 NP	180(SN)	X
Front Wheel Rim.	1 new	250(SN)	X
Front Fork Assy.	Best	590	✓
Front Fork Oil Seal	new	50(SN)	✓
Front Fork Bracket	Best	145	✓
Steering Cone and Bearing	new	75	✓
Headlamp	cracked	265	✓
Headlamp Cowling	cut	160	✓
Headlamp Top Garnish (Black)	new	95	X
Front Side Garnish (White) x 02	cut	105 x 2 = 210	✓
Front Side Garnish Signal Lamp x 02	LH cut	45 x 2 = 90	45
Handle Grip x 02	LH cut	20 x 2 = 40	20
Front Wing Mirror x 02	LH cut, RH Missing	65 x 2 = 130	✓
Brake Lever	new	60(SN)	X
Clutch Lever	cut	60(SN)	✓
Handle Bar	new	180	X
Radiator	new	450	X
Front Basket	distorted	70(SN)	✓
Speedometer	new	380	X
Front Footrest Rubber x 02	cut	28 x 2 = 56	✓
Front Footrest Bracket	Best	75	✓
Foot Clutch Lever	Best	40	✓
Rear Footrest x 02	LH cut	35 x 2 = 70	35
Rear Seat Cushion	torn	165	✓
Rear Seat Side Garnish (White) x 02	LH cut	95 x 2 = 190	95
Rear Exhaust Pipe	Repair	320	X
Rear Exhaust Pipe Heat Shield	Dented	55	✓

FBD6952T.

Taillamp	New	75	X
Brake Master Pump	Damaged	160(SN)	✓
Brake Master Pump Bracket	Bent	35(SN)	✓
Handle Bar Bracket (Blue)	Bent	30(SN)	✓
Brake Oil	New	20(SN)	✓

2231

S.N 425

200790

Panel Bending	350 250	
Spray Painting	350 250	
Wiring.	50 30	570.
To straighten body chassis	250	X
Towing Fees.	40	✓

total: 3002.90

R/S: 2-4K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: